









1779



**RM03**  
  
DISK DRIVE

PROCESSOR TYPE 10, 11, VAX

**RM03-00001 CODE D DD A**  
OCT 77 CORRECTION 1 Change model numbers and change sheet metal finish on drawing B DD RM03 0  
IN-PLANT EFFECTIVITY Documentation change only

**RM03-00002 CODE D**  
OCT 77 - CORRECTION 1 Add new shipping bracket and make changes to model numbers on drawing D UA-RM03-0-0  
IN PLANT EFFECTIVITY Documentation change only

**RM03-00003 CODE D**  
NOV 77 PROBLEM 1 No deck support in drive  
CORRECTION 1 Incorporate self contained deck support on all manufacturing drives Retain and install UL label  
IN PLANT EFFECTIVITY This ECO must be installed by December 15, 1977

**RM03-00004 CODE: D DD B**  
DEC 77 CORRECTION 1 Add supports to drive and cabinet to meet drop test requirements  
CORRECTION 2 Update drawing B-DD-RM03-0-0 to include new 100 volt/50 Hz and Business Systems models  
IN-PLANT EFFECTIVITY Marlboro Colorado Springs, Westminster and Salem NH Retrofit immediately

**RM03-00005 CODE: D**  
DEC 77 PROBLEM 1 Lid may be opened while spindle is spinning when no pack is mounted  
CORRECTION 1 replace 6SGV' logic card with new ASGV card  
IN PLANT EFFECTIVITY Presently being incorporated in Colorado Springs and in Westminster FA and T areas

**RM03-00006 CODE D**  
JAN 78 PROBLEM 1 Front door does not meet 1978 CSA standards  
CORRECTION 1 Replace door stop with new bracket which allows door to be closed by a mechanical fastener  
IN PLANT EFFECTIVITY Phase in by February 21 1978 ECO H969 00003 must be implemented in conjunction with this ECO

**RM03-00007 CODE D**  
MAR 78 PROBLEM 1 Canadian safety standards require labels indicating device electrical requirements to be located on external surface of cabinet  
CORRECTION 1 Add ID label with appropriate information and CSA label to rear cover  
IN PLANT EFFECTIVITY External labels are required on all units shipped into Canada after June 30, 1978



**RM03-00008 CODE: D**  
MAR 78 - PROBLEM 1 Deck support bracket is secure when used in upright position  
CORRECTION 1 Add thumb screw to provide more stability  
IN PLANT EFFECTIVITY Implemented by CDC prior to shipment

**RM03-00009 CODE: D**  
MAR 78 - CORRECTION 1 Invert clock data to improve READ CLOCK margin  
IN PLANT EFFECTIVITY Implemented by CDC prior to shipment

**RM03-00010 CODE D DD C**  
JUN 78 CORRECTION 1 Update documentation to agree with Colorado manufacturing  
CORRECTION 2 Add a label to distinguish RM02 from RM03  
IN PLANT EFFECTIVITY Colorado Springs Phase-in to assembly by June 26 1978

**RM03-00011 CODE D**  
JUN 78 PROBLEM 1 Units may draw in excess of 6 amps  
CORRECTION 1 Change 6 amps fuses to 8 amp type  
Change 5V Regulator board from ASHV to BSHV in A1 3 location  
IN PLANT EFFECTIVITY Documentation change only

**RM03-00012 CODE D**  
JUN 78 PROBLEM 1 Deck support bracket requires warning labels  
CORRECTION 1 Add warning labels to deck support bracket  
IN PLANT EFFECTIVITY Implemented by CDC



PROCESSOR TYPE: PDP-11, DEC 10/20, VAX

RM03-S0013 CODE: F
NOV 78 - PROBLEM 1 HFSV head alignment card with AZPV card which will accept 2,400 RPM and 3,600 RPM drives
IN-PLANT EFFECTIVITY (June 1978)
COMPATIBILITY: AZPV (2,400/3,600 RPM) head alignment board may be used on RM02 and RM03.
FIELD EFFECTIVITY: Exchange JFSV (2,400 RPM) and HFSV (3,600 RPM) head alignment boards with AZPV (2,400/3,600 RPM) universal head alignment board.
QUICK CHECK. Presence of AZPV board in FTU.

The DEC on-site labor charge will be the time required to install and test the FCO at the then-current hourly rate.

FCO KIT ORDERING:
EQ-00900-00. FCO, PARTS
FA-04064-00: FCO only

RM03-00014 CODE: D
JUL 78 - PROBLEM. Specifications missing from drawing directory
CORRECTION: Add specifications to drawing directory.
IN-PLANT EFFECTIVITY Documentation change only.
FIELD EFFECTIVITY None
QUICK CHECK None

RM03-00015 CODE: D
JUL 78 - PROBLEM Interference between fit of Chassis Slides and Vertical Supports of Frame Assembly
CORRECTION Change mounting of Chassis Slides from inside Vertical Supports to outside
IN-PLANT EFFECTIVITY. Immediately
FIELD EFFECTIVITY: None
QUICK CHECK. None

RM03-00016 CODE: D
SEP 78 - PROBLEM. Dust accumulation in shroud area.
CORRECTION: Add foam tape to front bezel
IN-PLANT EFFECTIVITY Phase-In to Galway by 22 August 1978 Immediately in Colorado
FIELD EFFECTIVITY. None.
QUICK CHECK. None.

RM03-00017 CODE: D
SEP 78 - PROBLEM 1: Flow and timing diagrams do not reflect latest revisions made to M7684 module.
CORRECTION 1 Update drawings and add to drawing directory
PROBLEM 2: Wrong variation of Bottom Pan called out on parts list
CORRECTION 2: Call out correct Bottom Pan variation
IN-PLANT EFFECTIVITY: Documentation change only
FIELD EFFECTIVITY: None.
QUICK CHECK None

RM03-00018 CODE: D
DEC 78 - PROBLEM 1. Serial number information not called out
CORRECTION 1 Add note to unit assembly drawing referencing method of serialization
PROBLEM 2 Tie wraps must be cut to remove flat cable in service loop
CORRECTION 2 Revise method of dressing flat cable
PROBLEM 3 Cable clamp not large enough to contain power cord and ground strap
CORRECTION 3 Change to large cable clamp.
IN-PLANT EFFECTIVITY Phase-In to Colorado by 1 June 1979
FIELD EFFECTIVITY None.
QUICK CHECK None

RM03-00019 CODE: D
JUN 79 - PROBLEM Incorrect part number for Terminator Assembly listed on drawing directory
CORRECTION Change part number on drawing directory
IN PLANT EFFECTIVITY Documentation change only
FIELD EFFECTIVITY None
QUICK CHECK None

RM03-00020 CODE: D
JUN 79 - PROBLEM Serial number labels must be hand typed.
CORRECTION Use pin feed decals for automated printing
IN-PLANT EFFECTIVITY Phase-In to Colorado by 1 June 1979
FIELD EFFECTIVITY None
QUICK CHECK: None.

DIGITAL EQUIPMENT CORPORATION

Engineering Change  
Order Log

RM03

PROCESSOR TYPE: PDP-11, DEC 10/20, VAX

Disk Drive

**RM03-00021 CODE: D**

AUG 79 - PROBLEM 1 Side panel assembly re design needs to be documented  
CORRECTION 1 Update Unit Assembly drawing  
PROBLEM 2: Document additions and corrections needed.  
CORRECTION 2: Update and add drawings  
IN-PLANT EFFECTIVITY Phase-In to Colorado by 1 May 1979.  
FIELD EFFECTIVITY: None.  
QUICK CHECK None.

**RM03-00022 CODE: D**

FEB 80 - PROBLEM 1 Present dual port switch not accessible from outside disk drive cabinet  
CORRECTION 1: Add dual port switches near front door of drive.  
PROBLEM 2 Various part numbers called out incorrectly on parts list  
CORRECTION 2 Update drawings to reflect correct parts.  
IN-PLANT EFFECTIVITY Phase-In to Colorado by 1 October 1980 Immediately in Galway  
FIELD EFFECTIVITY: None  
QUICK CHECK None.

**RM03-S0023 CODE: F**

SEP 81 - PROBLEM SYMPTOM. Intermittent data checks (DCK)  
PROBLEM Ungrounded brake assembly is source of intermittent read errors.  
CORRECTION Add grounding to brake assembly.  
IN-PLANT EFFECTIVITY (February, 1981) Immediately into drives with serial number 45,300 or above.  
FIELD EFFECTIVITY Retrofit all RM03 drives, series 29 and 36, when problem symptom is evident.  
QUICK CHECK. Presence of ground jumper wire from brake assembly to drive motor mounting plate

The DEC on-site labor charge will be the time required to install and test the FCO at the then-current hourly rate.

**FCO KIT ORDERING**

EQ-01097-00 FCO, PRINTS, PARTS  
FA-04323-00 FCO only

**RM03-00024 CODE: D**

MAY 81 - PROBLEM ECC algorithm occasionally gives false correction to data  
CORRECTION. Modify recommended recovery procedure.  
IN-PLANT EFFECTIVITY: Documentation change only.

**RM03-00025 CODE: D**

DEC 81 - PROBLEM: Spindle Stop Time exceeds specification.  
CORRECTION: Replace or rework ASGV Modules.  
IN-PLANT EFFECTIVITY: Immediately by Vendor.

**RM03-00026 CODE: D**

DEC 81 - PROBLEM: Excessive Data Checks.  
CORRECTION: Replace Cap on Voice Coil Assembly.  
IN-PLANT EFFECTIVITY: Immediately by Vendor.

**RM03-00027 CODE: D**

JAN 82 - PROBLEM: Part number 7419781-00 is obsolete.  
CORRECTION: Correct parts list drawing K-PL-RM03-0-DBP to reflect current part number 7419781-15.  
IN-PLANT EFFECTIVITY: Documentation change only

**RM03-S0028 CODE: F**

JAN 83 - PROBLEM SYMPTOM: Excessive data check or header CRC errors.  
PROBLEM: Arcing contacts on A1K2 emergency retract relay  
CORRECTION. Rework Power Supply Board 5VQN per vendor ECO, CDC NEC J296.  
IN-PLANT EFFECTIVITY: (April, 1982) Immediately  
FIELD EFFECTIVITY. Retrofit all RM03 drives series code 43 and below when problem symptoms are evident..  
QUICK CHECK. Presence of 5.0 MFD capacitor mounted on underside of Mother Board. (Use flashlight and inspection mirror to determine presence of capacitor.)

The DEC on-site labor charge will be the time required to install and test the FCO at the then-current hourly rate.

LIBRARY TYPE**PDP8, PDP11, DEC 10/20, VAX**

**FCO KIT ORDERING:**  
EQ-01170-00: FCO, PARTS  
FA-04414-00: FCO only

**RM03-00029 CODE: D**  
JUN 82 - PROBLEM: Update the specification to include MBA MTBF page 4, sec 4 0 and correct the soft error rate page 6, sec., 6 0  
CORRECTION. Add the new MBA MTBF and soft error correction per this ECO.  
IN-PLANT EFFECTIVITY. Documentation change only.

**RM03-S0030 CODE: F**  
MAY 84 - PROBLEM Possible start relay failure due to the peak inverse voltages in the excess of the device rating.  
CORRECTION. Replace the 600 volt start relay (A3K5) with the 800 volt start relay per CDC NEC #J255  
IN-PLANT EFFECTIVITY: Aug 82  
FIELD EFFECTIVITY: Retrofit all RM03 drives, series 42 and below when the Problem/Symptom is evident.  
QUICK CHECK. CDC P/N 94378603 is stamped on the relay at location A3K5 in the RM03 drive.

The DEC on-site labor charge will be the time required to install and test the FCO at the then current hourly rate.

**FCO KIT ORDERING.**

EQ-01253-01: FCO, PARTS  
FA-04425-01. FCO only

**RM03-00031 CODE: D**  
SEP 85 - PROBLEM BC06S rework (74-19781-15) is being replaced.  
CORRECTION: Replace with cable, MASS BUS (BC06S-15)  
IN-PLANT EFFECTIVITY: Documentation change only.

**RM03-00032 CODE: D**  
NOV 82 - PROBLEM: 1. Jumpers have been used in the RM03 Drive, but have not been properly documented.  
CORRECTION: 1. Document jumpers in the RM03 assy and parts list.  
PROBLEM: 2. Documentation updates are required.  
CORRECTION: 2. Make a documentation change on UA-PL.  
IN-PLANT EFFECTIVITY: Documentation change only.

**RM03-00033 CODE: D**  
JUL 83 - PROBLEM: Transformer A1T1 can potentially short to deck plate due to insufficient adjustment travel in the mounting strap on the 50hz units.  
CORRECTION: Incorporate Transformer with a new mounting strap on the failed units (50 hz only) per CDC NEC #J388  
IN-PLANT EFFECTIVITY: JUL 83

**RM03-M0034 CODE: F**  
AUG 85 - IN-PLANT EFFECTIVITY MAY 85  
PROBLEM: Transformer (A1T1) may come in contact with the upper deck plate assembly (when raised or lowered); resulting in damage to the transformer winding insulation and/or shorting of the transformer windings to the chassis.  
FIELD EFFECTIVITY: Inspect and retrofit (if necessary) all RM03 50 Hertz Drives. All 29-22908 50 Hertz Replacement Transformers require incorporation of this FCO when they are installed.  
QUICK CHECK. Drive Revision is "T" or standoffs or Power Amplifier Assembly.

The DEC on-site labor charge will be the time required to install and test the FCO at the then current hourly rate.

**FCO KIT ORDERING.**

EQ-01334-01: FCO, PARTS  
FA-04615-01: FCO only



5-Nov-1986  
RM03-INDEX.A  
REV A

MICROMEDIA PUBLISHING

Field Change Order Index  
-----

FCO Number -----	FA REV ---	Rel. Date -----	SB# ---	Problem -----
-RM03---S013	A	2-Nov-78		Present HFSV head alignment card can only be used on 3600 RPM drive
-RM03---S023	A	23-Sep-81	199	Data checks (DCK)-ungrounded brake assembly is source of read errors
-RM03---S028	A	28-Jan-83	266	Data check/header CRC error-arcng contacts on AlK2 emerg retr relay
-RM03---S030	A	11-May-84	330	Start failure due to peak inverse voltages in excess of device ratin
-RM03---M034	A	15-Aug-85	396	Transformer (AlT1) may come in contact w/ upper deck plate assemb

Rm03 - FCO /

**digital**

# FIELD CHANGE ORDER

FCO RM03

S

0013

PAGE 1 of 1

Level of Urgency (LOU)

STATUS LOU	FCO EXPENSE RESPONSIBILITY			ESTIMATED TIME TO INSTALL and TEST (on-site) (Travel time not included)
	WARRANTY	CONTRACT	PER CALL	
Mandatory				0.3 DECIMAL HOURS
Required		DIGITA	CUST	
Specification			CUST	
Improvement			CUST	RM02 RJM02 RWM02
Hardware Option	PURCHASABLE OPTION			
Cosmetic	CUST	CUST	CUST	

On site FCO installation, by DEC will be in accordance with both APPLICABILITY and the above FCO EXPENSE RESPONSIBILITY matrix

QUICK CHECK (To determine if FCO has been installed)

PRESENCE OF AZPV BOARD IN FTU.

LAST PREVIOUS FCO: NONE

RELATED OR PREREQUISITE FCOs / MCOs

NONE

FCO KIT CHARGES (United States and Canada only)

KIT ITEM	DOCUMENTATION	PARTS	OTHER
<input checked="" type="checkbox"/> FCO	<input type="checkbox"/> PRINTS \$5.00	::	

Parts charges are as of FCO release date and are subject to change

PARTS AVAILABILITY DATE DECEMBER 1978

LOGISTICS CODING (174) (174) (200)

LOGISTICS REVIEW *John J. Moore / Nov 78*

QTY	PART NUMBER	DESCRIPTION
1	29-23202	CDC FCO KIT, 89053483

ORDER BY THIS NUMBER	KIT INCLUDES		
	FCO	PRINTS	PARTS
EQ-0900-00	X		X
FA-04064-00	X		

:: PARTS PRICE UNDETERMINED AT DATE OF FCO RELEASE

### APPLICABILITY

EXCHANGE JFSV (2,400 RPM) AND HFSV (3,600 RPM) HEAD ALIGNMENT BOARDS WITH AZPV (2,400/3,600) UNIVERSAL HEAD ALIGNMENT BOARD.

RETURN HFSV AND/OR JFSV TO S/R 126 BY 28 FEBRUARY 1979 USE PART NUMBER EQ-00900-00.

TO RECEIVE CREDIT: USE RAC # 8037.

### SPECIAL TEST EQUIPMENT, TOOLS, or SUPPLIES

(Not included in the Field Retrofit Kit)

### FIELD INSTALLATION and TEST PROCEDURE

PROBLEM FROM ECO RM03-00013:  
PRESENT HFSV HEAD ALIGNMENT CARD CAN ONLY BE USED ON 3600 RPM DRIVE.

NOTES: COMPATIBILITY NOTE: AZPV (2,400/3,600 RPM) HEAD ALIGNMENT BOARD MAY BE USED ON RM02 AND RM03.

AFFECTED PM PROCEDURE: RM03 HEAD ALIGNMENT PROCEDURE AND RM02 HEAD ALIGNMENT PROCEDURE

APPROVED - Field Service Product Support

GREG EKHOLM

DISTRIBUTION CODING

LIST 11,10

LHQ 200

FCO RELEASE DATE

NOVEMBER 2, 1978



# FIELD CHANGE ORDER

FCO

RM03

S

0023

PAGE 1 of 4

Level of Urgency (LOU)

STATUS LOU	FCO EXPENSE RESPONSIBILITY			ESTIMATED TIME TO INSTALL and TEST (on-site) (Travel time not included)	
	WARRANTY	R	PER CALL		
Mandatory	DIGITAL			1.0 DECIMAL HOURS	
Required					CUST
Specification					CUST
Improvement					
Hardware Option	PURCHASEABLE OPTION				
Cosmetic	CUST	CUST	CUST		

On-site FCO installation, by DEC, will be in accordance with both APPLICABILITY and the above FCO EXPENSE RESPONSIBILITY means.

QUICK CHECK (To determine if FCO has been installed)

PRESENCE OF GROUND JUMPER WIRE FROM BRAKE ASSEMBLY TO DRIVE MOTOR MOUNTING PLATE.

LAST PREVIOUS FCO: RM03-S0013

RELATED OR PREREQUISITE FCO # / MCO #

NONE

FCO KIT CHARGES (United States and Canada only)

KIT ITEM	DOCUMENTATION	PARTS	OTHER
<input checked="" type="checkbox"/> FCO	<input type="checkbox"/> NONE	10.00	::
	<input type="checkbox"/> PRINTS		

Parts charges are as of FCO release date and are subject to change.

PARTS AVAILABILITY DATE: SEPTEMBER, 1981

LOGISTICS CODING: 5K 500 1K

LOGISTICS REVIEW: *ETM Duffen* 7/16/81

QTY	PART NUMBER	DESCRIPTION
1	29-11997	CDC FCO KIT PE 60378

ORDER BY THIS NUMBER	KIT CONTAINS FCO PRINTS	PARTS
EO-01097-00	X	X
FA-04323-00	X	

::PARTS PRICE UNDETERMINED AT DATE OF FCO RELEASE.

### APPLICABILITY

RETROFIT ALL RM03 DRIVES, SERIES 29 AND 36, WHEN PROBLEM SYMPTOM IS EVIDENT.

### SPECIAL TEST EQUIPMENT, TOOLS, or SUPPLIES (Not included in the Field Retrofit Kit)

NONE

### FIELD INSTALLATION and TEST PROCEDURE

SEE PAGES 2 THROUGH 4 OF THIS FCO.

PROBLEM SYMPTOM: INTERMITTENT DATA CHECKS (DCK)

APPROVED Field Service Product Support

*Greg Ekholm*

GREG EKHOLM

LIBRARIES: ALL

RM03-FCO-2

*DM-*

FCO RELEASE DATE

23 SEPTEMBER 1981



REWORK PROCEDURE  
FOR  
RM03-S0023

- 1- POWER DOWN DRIVE.
- 2- REMOVE DISC PACK AND STORE IN PROPER AREA.
- 3- TURN OFF CIRCUIT BREAKERS AT REAR OF DRIVE.
- 4- REMOVE REAR COVER.
- 5- INSTALL REAR HOLD DOWN BRACKET.
- 6- REMOVE TWO (2) SCREWS IN PACK WELL AND RAISE TOP DECK TO MAINTENANCE POSITION.
- 7- LOCK MAINTENANCE BRACKET IN PLACE WITH THUMB SCREW .
- 8- INSTALL ONE END OF GROUND JUMPER (CDC 77579946) ON DRIVE MOTOR MOUNTING PLATE USING EXISTING SCREW AND WASHER INT. #8 (CDC 10126104). (FIGURE 1)
- 9- INSTALL OTHER END OF GROUND JUMPER ASSEMBLY ON BRAKE ASSEMBLY STANDOFF USING WASHER INT. #10 (CDC 10126105), STANDOFF (CDC 73078800), AND SCREW PAN HD. (CDC 10127361). (FIGURE 1)
- 10- UNLOCK THE MAINTENANCE BRACKET AND LOWER TOP DECK TO NORMAL POSITION.
- 11- RE-INSTALL TWO SCREWS IN WELL AREA AND CLOSE ACCESS COVER.
- 12- REMOVE REAR HOLD DOWN BRACKET AND RETURN TO STORAGE POSITION.
- 13- UPDATE FCO LOG TABLE ON SIDE OF LOGIC CARD CAGE TO NEC J115 CDC FCO PE60378.
- 14- INSTALL REAR COVER.
- 15- POWER UP DRIVE BY TURNING ON CIRCUIT BREAKERS.
- 16- PURGE DRIVE WITHOUT A PACK AND ALL CIRCUIT BREAKERS ON FOR TEN (10) TO FIFTEEN (15) MINUTES.

- 17- UPDATE SITE MANAGEMENT GUIDE TO REFLECT THIS FCO.
- 18- INSTALL A SCRATCH DISK PACK.
- 19- RUN APPROPRIATE DIAGNOSTIC FOR A MINIMUM OF TEN (10) MINUTES TO ENSURE PROPER OPERATION:
  - PDP11: CZRMUA0 OR LATER, RM02, 03, 05 PERFORMANCE EXERCISER
  - VAX: ESRAA 7.0 OR LATER, RPOX/RKOX/RMOX RELIABILITY TEST.
  - 20'S: MD-10-DDRPI-A OR LATER RELIABILITY TEST.
- 20- RETURN DISK DRIVE TO PROPER CUSTOMER CONFIGURATION.




FIGURE 1

# digital

## FIELD CHANGE ORDER

FA-04414-00

FCO

RM03

S

0028

PAGE

1 of 4

Level of Urgency (LOU)

STATUS  
LOU

## FCO EXPENSE RESPONSIBILITY

	WARRANTY	K	PER CALL
Mandatory			
Required			CUST
Specification			CUST
Improvement			CUST
Hardware Option	PURCHASEABLE OPTION		
Cosmetic	CUST	CUST	CUST

ESTIMATED TIME TO INSTALL and TEST (on-site)  
(Travel time not included)1.0  
DECIMAL HOURS

## APPLICABILITY

RETROFIT ALL RM03 DRIVES SERIES CODE 43 AND BELOW WHEN PROBLEM SYMPTOMS ARE EVIDENT.

On-site FCO installation, by DEC, will be in accordance with both APPLICABILITY and the above FCO EXPENSE RESPONSIBILITY matrix.

QUICK CHECK (To determine if FCO has been installed)

PRESENCE OF 5.0 MFD CAPACITOR MOUNTED ON UNDER-SIDE OF MOTHER BOARD. (SEE NOTE)

LAST PREVIOUS FCO: RM03-S0023, S0013

RELATED OR PREREQUISITE FCO s / MCO s

SPECIAL TEST EQUIPMENT, TOOLS, or SUPPLIES  
(Not included in the Field Retrofit Kit)

STANDARD TOOL KIT, 3/16" DRILLBIT, AND DRILL

## FCO KIT CHARGES (United States and Canada only)

KIT ITEM	DOCUMENTATION		PARTS	OTHER
	<input checked="" type="checkbox"/> FCO	<input type="checkbox"/> PRINTS \$10.00		
			::	

Parts charges are as of FCO release date and are subject to change

PARTS AVAILABILITY DATE MARCH, 1983LOGISTICS CODING 6K 1.4K 2KLOGISTICS REVIEW Ruth Fried 1/14/83

QTY PART NUMBER DESCRIPTION

1 29-12318-00 CDC FCO KIT 89053939

ORDER BY  
THIS NUMBEREQ-01170-00  
FA-04414-00KIT CONTAINS  
FCO PRINTS PARTSX X  
X

\*\*PARTS PRICE UNDETERMINED AT DATE OF FCO RELEASE.

PROBLEM SYMPTOM: EXCESSIVE DATA CHECKS OR HEADER CRC ERRORS.

NOTE: USE FLASHLIGHT AND INSPECTION MIRROR TO DETERMINE PRESENCE OF CAPACITOR.

APPROVED Field Service Product Support

*Lloyd G. Buchanan*

LOYD G. BUCHANAN

LIBRARIES: 10  
11  
VAX*DM*

RM03-FCO-6

FCO RELEASE DATE

28 JANUARY 1983



## REWORK PROCEDURE

FOR

FCO RM03-S0028

- 1- POWER DOWN DRIVE.
- 2- DISCONNECT AC POWER CORD AT SOURCE.
- 3- RAISE DECK.

NOTE: ENSURE REAR SHOCK MOUNT HAS SHIPPING BOLT IN PLACE.

- 4- DISCONNECT CONNECTORS PIB, PIA, AND P100 FROM POWER SUPPLY BOARD 5VQN.
- 5- REMOVE THREE POWER SUPPLY CARDS.
- 6- REMOVE AND RETAIN SEVEN 6-32 BY 5/6 PHILLIPS HEAD SCREWS SECURING POWER SUPPLY BOARD 5VQN TO STANDOFFS.
- 7- REMOVE POWER SUPPLY BOARD.
- 8- DRILL A 3/16 (.187)" HOLE IN POWER SUPPLY BOARD. (FIGURE 1)
- 9- INSTALL A 5 MFD CAPACITOR, EITHER A CDC ZD2A505K OR A CDC X663F 5.0-10-200 WITH INSULATION (CDC 92261120) OVER EACH LEAD, BETWEEN NEWLY DRILLED HOLE AND EDGE OF POWER SUPPLY BOARD, AND FLUSH WITH EDGE OF BOARD. (FIGURE 2)
- 10- SOLDER ONE LEAD OF CAPACITOR TO PIN 8 OF RELAY K2.
- 11- SOLDER OTHER LEAD OF CAPACITOR TO PIN 6 OF PLUG J1.
- 12- ENSURE CAPACITOR IS FLUSH WITH EDGE OF POWER SUPPLY BOARD AND USE TIE WRAP (CDC 94277401) TO SECURE CAPACITOR TO BOARD.

CAUTION

WHEN SECURING CAPACITOR TO POWER SUPPLY BOARD, USE MINIMAL FORCE ON TIE WRAP. CAPACITOR MUST BE HELD FIRMLY IN PLACE WITHOUT DEFORMING OR DAMAGING OUTSIDE CASE.

- 13- RE-INSTALL POWER SUPPLY BOARD.
- 14- RE-INSTALL SEVEN 6-32 BY 5/16 PHILLIPS HEAD SCREWS SECURING POWER SUPPLY BOARD TO STANDOFFS.
- 15- RE-INSTALL THREE POWER SUPPLY CARDS
- 16- RE-CONNECT CONNECTORS PIB, PIA, AND P100 TO POWER SUPPLY BOARD.
- 17- CLOSE DECK.
- 18- RE-CONNECT AC POWER CORD TO SOURCE.
- 19- POWER UP DRIVE.
- 20- RUN PERFORMANCE EXERCISOR TO ENSURE CHANGE WAS DONE CORRECTLY.

RM03-FCO-7

ORIGINAL




FIGURE 1  
POWER SUPPLY BOARD 5VQN




FIGURE 2  
POWER SUPPLY BOARD 5VQN

# digital

## FIELD CHANGE ORDER

FA-04425-01

FCO

RM03

S

0030

PAGE  
1 of 5

Level of Urgency (LOU)

Mandatory Required Specification Improvement Hardware Option Cosmetic	FCO EXPENSE RESPONSIBILITY			ESTIMATED TIME TO INSTALL and TEST (on-site) (Travel time not included)  1 hour DECIMAL HOURS
	WARRANTY	R	PER CALL	
	DIGITAL			CUST
				CUST
				CUST
	PURCHASEABLE OPTION			
	CUST	CUST	CUST	

On-site FCO installation, by DEC, will be in accord with both APPLICABILITY and the above FCO EXPENSE RESPONSIBILITY marks.

**QUICK CHECK (To determine if FCO has been installed)**

CDC P/N 94378603 stamped on relay at location A3K5 in RM03 drive.

LAST PREVIOUS FCO: RM03-S0023

RELATED OR PREREQUISITE FCOs / MODs

**APPLICABILITY**

Retrofit all RM03 drives, series 42 and below when Problem/Symptom is evident.

**SPECIAL TEST EQUIPMENT, TOOLS, or SUPPLIES**  
(Not included in the Field Retrofit Kit)

Standard Tool Kit  
Thermal Grease (90-08268)

**FIELD INSTALLATION and TEST PROCEDURE**

See attached. FCO predominantly effects 50 HZ, 220/240 volt units.

\*\*\*\*\*NOTE\*\*\*\*\*

This FCO implements ECO # RM03-CX030

**FCO KIT CHARGES (United States and Canada only)**

KIT ITEM	DOCUMENTATION	PARTS	OTHER
	<input type="checkbox"/> FCO <input type="checkbox"/> PRINTS		

Parts charges are as of FCO release date and are subject to change.

PARTS AVAILABILITY DATE: June 1984

LOGISTICS CODING: 1800 - 200 - 500

**LOGISTICS REVIEW**

QTY PART NUMBER DESCRIPTION  
1 each 80 volt relay CDC P/N 94376503  
(29-22929)

Order by	Kit Contains
This Number	FCO Prints Parts
EQ-01253-01	X X
FA-04425-01	X

Failure/Symptoms: Possible start relay failure due to peak inverse voltages in excess of device rating.

APPROVED-Field Service Product Support

*Mark O. Himes*  
Mark Himes

Libraries: 11  
Mini  
LCG

APPROVED-Field Service Product Safety

*Bob Barnard* 4-19-84  
Bob Barnard

FCO RELEASE DATE

11 May 1984

ANALOG FCO-10

digital

**REWORK PROCEDURE  
FOR  
FCO RM03-S0030**


This FCO replaces the existing 600 vclt A3K5 Start Triac (CDC P/N 94376501) with an 800 vclt Start Triac (CDC P/N 94376503)

1. Raise the pack access cover with power applied to the Drive.
2. Remove the Drive power with the pack access cover in the open position.

**CAUTION**

The RM02 AC Power Cord "plug" must be removed from the AC power source receptacle before proceeding.

3. Loosen the locking screws that hold the Drive top cover in place and slide it backwards off the Drive.
4. Install the heads actuator locking pin into the "shipping lock" hole to prevent the actuator from moving.
5. Install the rear deck hold-down spacer. (See Figure 1)



**Figure 1 Deck Maintenance Position**

1111111111  
|d|1|g|1|t|a|1|  
1111111111

FCO RM03-30030

PAGE 3 OF 5

6. Remove the two (2) deck hold-down screws from inside the pack shroud area.
7. Raise the deck upward until its support bracket locks into place. Secure the support bracket locking the thumb screw and strap it into the lower hole of the support arm assembly.
8. Locate and remove all connectors from the start triac A3K5. (See Figure 2)




Figure 2 Start Triac A3K5

RM03-FCO-12

d	l	g	l	t	a	l
\_	\_	\_	\_	\_	\_	\_

FCO RM03-S0030

PAGE 4 OF 5

- 
9. Remove the two (2) screws that secure the triac in place.
  10. Apply a light coat of dielectric grease to the base of the new triac.
  11. Mount the new triac using the two (2) screws previously removed. Be sure to attach the green grounding wire to one of these screws.
  12. Reconnect all wires to the triac terminals according to Figure 2.
  13. Release the deck support bracket and lower the deck into the operating position.
  14. Re-install the two (2) deck hold-down screws inside the pack shroud area.
  15. Remove the rear hold-down spacer and install it in the keeper hole.
  16. Restore the head actuator holding pin to its "storage" hole.
  17. Replace the top cover onto the Drive.

1111111111  
|d|1|g|1|t|a|l|l|  
1111111111

FCO RM03-50030

PAGE 5 OF 5

---

**VERIFICATION TEST  
FOR  
RM03-50030**

1. Connect the Drive to the MBA and the processor.
2. Apply the power to the Drive.
3. Install a scratch pack and close the pack access cover.
4. Press the START switch on the Drive's operator panel and verify that the Drive goes READY in approximately 30-40 seconds and that no FAULT condition exists.
5. Spin the drive down and repeat step 4.
6. Load and execute any of the available diagnostics on site that perform read/write functions to verify the final Drive operation.
7. Log the installation of this FCO into the Digital Site Management Guide.



# FIELD CHANGE ORDER

FA-04615-01  
FCO                      RMD3 M 0034 PAGE 1 of 21  
Level of Losses (LOL)                     

**APPLICABILITY**  
Inspect and retrofit (if necessary) all RMD3 50 Hertz Drives.  
  
All 29-2290P 50 Hertz Replacement Transformers require incorporation of this FCO when they are installed.

STATUS LOL	FCO EXPENSE RESPONSIBILITY		
	WARRANTY	CONTRACT	PER CALL
Mandatory	DIGITAL		CLST
Required			CLST
Specification			CLST
Improvement			CLST
Hardware Option	PURCHASEABLE OPTION		
Cosmetic	CLST	CLST	CUST

**ESTIMATED TIME TO INSTALL and TEST**  
(on-site)  
(Travel time not included)  
1.0  
DECIMAL HOURS

On site FCO installation by DEC will be in accordance with both APPLICABILITY and the above FCO EXPENSE RESPONSIBILITY means

**CLICK CHECK (To determine if FCO has been installed)**  
  
Drive Revision is "T" or standoffs on Power Amplifier Assembly.

**SPECIAL TEST EQUIPMENT, TOOLS, or SUPPLIES**  
(Not included in the Field Retrofit Kit)  
Offset Phillips Screwdriver, Flashlight  
2mm (.08 inches) Feeler Gauge or small ruler

LAST PREVIOUS FCO: RMD3-S-030  
RELATED OR PREREQUISITE FCO: MCO: RMD2-M0026

**FIELD INSTALLATION and TEST PROCEDURE**  
  
.....  
NOTE  
.....  
This FCO incorporates ECO number RMD3-CXC33 and RMD3-CX034.  
.....

PARTS AVAILABILITY DATE October 1985

LOGISTICS CODING 1000-100-500

LOGISTICS REVIEW *[Signature]*

QTY	PART NUMBER	DESCRIPTION
4	90-00001-32	Standoffs
4	90-08007-01	10-32 X 1/4 Screws
1	29-22908-00	EMR & MTG Strap

Order by	Kit Contains	
This Number	FCO	Prints
EQ-01334-01	X	X
FA-04615-01	X	

**Problem/Symptoms:** Transformer (A171) may come in contact with the upper deck plate assembly (when raised or lowered); resulting in damage to the transformer winding insulation and/or shorting of the transformer windings to the chassis.

APPROVED: *[Signature]*  
Rick Swanson  
  
*[Signature]*  
John Freudenberg

Libraries:  
ICG  
PDP 11  
MINI  
KS10

FCO RELEASE DATE  
15 August 1985

d	i	g	i	t	a	l		

FCO RM03-M0034  
PAGE 2 OF 21

REWORK PROCEDURE  
FOR  
FCO RM03-M0034

SECTION I - INSPECTION PROCESS

1. Remove any existing disk pack from the drive and power-down the Unit.

\*\*\*\*\*  
\* DANGER \*  
\* REMOVE AC POWER FROM THE RM02 DISK DRIVE BY REMOVING THE AC POWER \*  
\* PLUG FROM THE BRANCH RECEPTACLE BEFORE PROCEEDING. \*  
\*\*\*\*\*

2. Remove the drive top cover assembly.
  - A. Loosen the two locking screws on the back of the top cover.
  - B. Slide the drive top cover back and then lift it off the rear of the drive.
3. Loosen the logic chassis clamp screws from the rear of the drive (See FIGURE 1).

1111111111  
1111111111  
1111111111

4. Carefully slide the logic chassis (on its hinges) towards the rear of the drive and then up and to the left (counter clockwise) into the maintenance position (ARROWS 1 & 2 in FIGURE 1).




FIGURE 1

RM02-3 REAR VIEW

5. Locate the main (50HZ) Transformer (A1T1) as shown in FIGURE 2.




FIGURE 2

RMD2-3 Drive Logic chassis in  
the maintenance position

digital

6. The upper deck plate assembly may have to be raised into its maintenance position to view all areas of the transformer, (a closer view of the transformer is shown in FIGURE 3).




FIGURE 3

RM02-3 50 Hz Transformer  
(Close-up View)

d	i	g	i	t	a	l		

FCO RM03-M0034

PAGE 6 OF 21

7. Carefully examine the insulation on both sides of the transformer (transformer windings insulation) for any signs of physical damage (ie: punctures, tears, scratches, indentations, etc.).

\*\*\*\*\*  
\* **WARNING** \*

\* **IF PHYSICAL DAMAGE HAS OCCURRED THIS WILL REQUIRE REPLACEMENT** \*  
\* **OF THE TRANSFORMER. GO TO SECTION 2 FOR TRANSFORMER REPLACEMENT** \*  
\* **PROCEDURES.** \*  
\*\*\*\*\*

8. If there is no physical damage to the AC power transformer winding insulation, check to ensure that the required clearance between the AC power transformer winding insulation and the upper deck plate assembly is 2mm (.08 inches).
9. With the deck in its lowered position, check to be sure that there is a minimum clearance of 2mm (.08 inches), between both the left and right side of the AC power transformer winding insulation and any part of the upper deck plate assembly. The critical areas of clearance are noted by the arrows labeled with no. 5 in FIGURE 3. A flashlight and feeler gauge may be required. The side of the transformer closest to the power supply assembly, see FIGURE 4, can be observed by looking through the hole in the rear of the positioner (ARROW 3, FIGURE 1) and applying sufficient light (with a flashlight) as shown by ARROW 4 in FIGURE 1. Assure that there are no pinched wire harnesses and no chance of damage due to contact between the transformer assembly and the upper deck chassis or other surrounding components.

digital




FIGURE 4

RM02-3 Lower Chassis Assembly

d	i	g	i	t	a	l		

SECTION I - INSPECTION PROCESS (CON'T)

10. If the clearance on the left or the right side of the transformer is not sufficient, go to Section 2 for Transformer Rework Procedures.

SECTION 2 - TRANSFORMER REWORK PROCEDURES

PART 1 - ADJUSTING THE TRANSFORMER  
-----

It may be possible to get the required 2mm (.08 inches) clearance between both the left and right sides of the AC power transformer winding insulation and the upper deck plate assembly by adjusting the transformer from left to right. However, if physical damage has occurred then proceed directly to Section 2, Part 2 - Transformer Replacement Procedure.

1. Remove any existing disk pack from the drive and power-down the Unit.

\*\*\*\*\*  
\* **DANGER** \*  
\* **REMOVE AC POWER FROM THE RM02 DISK DRIVE BY REMOVING THE AC POWER** \*  
\* **PLUG FROM THE BRANCH RECEPTACLE BEFORE PROCEEDING.** \*  
\*\*\*\*\*

2. Remove the drive top cover assembly.
3. Remove the two (2) top deck hold down screws (from inside the pack shroud area) that secure the upper deck chassis to the lower deck chassis.
4. Raise the deck to its maintenance position and lock the maintenance.

\*\*\*\*\*  
\* **WARNING** \*  
\* **ENSURE THAT THE MAINTENANCE BRACKET IS LOCKED WITH THE THUMB SCREW** \*  
\* **BEFORE PROCEEDING.** \*  
\*\*\*\*\*

d	i	g	i	t	a	l				

FCO RM03-M0034  
PAGE 9 OF 21

**SECTION 2, PART 1 - ADJUSTING THE TRANSFORMER (CONT'D)**

5. Slightly loosen the transformer mounting screws #1, #2, #3, and #4 (shown in FIGURE 4).

**NOTE: ACCESS TO TRANSFORMER MOUNTING SCREW #4 MAY BE OBTAINED BY FIRST REMOVING THE POWER AMP ASSEMBLY MODULE LOCATED ON THE SIDE OF THE HEADS ACTUATOR ASSEMBLY, (SEE FIGURE 1).**

- A. Remove the quick connect terminal (yellow leadwire) from Faston on the upper left hand corner of the power amp assembly A3A04 (ITEM 35 on FIGURE 5).
- B. Remove the screw that secures the upper left hand corner of the power amplifier assembly.
- C. Remove connector J200.
- D. Cut the tie wrap from the bottom right hand corner.
- E. Remove the two screws that secure the power amplifier to the deck casting. An offset phillips screwdriver will be needed.
6. Carefully move the transformer to the left or right to obtain the required clearance of 2mm (.08 inches), on both sides of the transformer. This would be in a direction from left-to-right when viewing the transformer from the front of the drive (See ARROW 6 in FIGURE 4).
7. Check clearance as indicated in Section 1 - Inspection, Step 9.
8. If the required clearance cannot be obtained on both sides of the transformer (with the upper deck in its lowered position and both screws in the pack well assembly secured) using this adjustment procedure, then go to part 2 and perform the Transformer Replacement Procedure. Otherwise, continue with step 9.
9. Tighten the four (4) transformer mounting screws.




FIGURE 5

DOCK ASSEMBLY

Initial

FCO RM03-M0034  
PAGE 11 OF 21

10. To replace the servo power amplifier assembly, perform the following:
  - A. Secure the servo power amp in place by installing the two (2) screws that mount the power amp to the baseplate. Do not tighten. Install and secure the screw in the upper left hand corner of the power amp assembly. Tighten the two remaining screws.
  - B. Connect J200 to the power amp assembly. Connect yellow faston connector to the tab in the upper left hand corner.
11. With the upper deck in its lowered position and both screws in the pack well assembly secure, check again for required clearance on the both sides of the transformer, especially if the transformer has been re-adjusted in steps 1 through 8.
12. Carefully return the logic chassis to its normal operating position and tighten the logic chassis clamp screws per FIGURE 1.
13. Install the drive top cover assembly.
14. Power up the drive and verify drive operation using the available diagnostics on site.
15. Change the revision of the drive to revision "T", fill out LARS form as shown on attached example (see pages 19 thru 21) and log the performed FCO activity into the Digital Site Management Guide.

id:lgllt|all

**SECTION 2, PART 2 - REPLACING THE TRANSFORMER**

1. Remove any existing disk pack from the drive and power-down the Unit.

**DANGER**

**REMOVE AC POWER FROM THE RM02 DISK DRIVE BY REMOVING THE AC POWER PLUG FROM THE BRANCH RECEPTACLE BEFORE PROCEEDING.**

2. Remove the drive Top Cover Assembly.
3. Remove the two (2) top deck hold down screws (from inside the pack shroud area) that secure the upper deck chassis to the lower deck assembly.
4. Install the rear hold-down spacer.
5. Raise the deck to its maintenance position and lock the maintenance.

**WARNING**


**ENSURE THAT THE MAINTENANCE BRACKET IS LOCKED WITH THE THUMB SCREW BEFORE PROCEEDING.**

6. Locate the terminal strip TB1 in front of the 50HZ transformer on the lower deck chassis assembly. Refer to item 2 on FIGURE 6.
7. Remove the plastic insulators from Terminals 1 through 6 on TB1.

**NOTE**

**RECORD THE COLORS OF THE TRANSFORMER WIRES ATTACHED TO TERMINALS 1 THROUGH 6 ON TB1, BEFORE PROCEEDING.**

digital



BASE ASSEMBLY

d		g		t		a		l

8. Loosen the terminal screws and remove the transformer wires attached to Terminals 1 through 6 on TB1.
9. Disconnect Transformer connector P100 from the power supply assembly, refer to FIGURE 7.




FIGURE 7

POWER SUPPLY ASSEMBLY

d		g		t	a			

FCO RM03-M0034

PAGE 15 OF 21

**SECTION 2, PART 2 - REPLACING THE TRANSFORMER (CON'T)**

10. Remove the two (2) orange transformer wires connected to the tuning capacitor C8 (Item 38 Figure 6).
11. Remove the three (3) transformer mounting screws #1, #2, and #3 as shown in FIGURE 4.
12. TO remove the power amplifier assembly to gain access to transformer screw #4, perform the following:
  - A. Remove the quick connect terminal (yellow leadwire) from faston on the upper left hand corner of the power amplifier assembly. (Item 35 FIGURE 5).
  - B. Remove the screw that secures the upper left hand corner of the power amplifier assembly.
  - C. Remove connector J200.
  - D. Cut the tie wrap from the bottom right hand corner.
  - E. Remove the two (2) screws that secure the power amp to the deck casting. An offset phillips screwdriver will be needed.
13. Remove transformer screw #4 (FIGURE 4).
14. Remove the transformer (Alt1) and dispose of properly.  
Note: cut the tie wraps if necessary.
15. Install the new FCO replacement transformer (CDC P/N 76846800) with new transformer mounting strap (CDC P/N 95656840) incorporated (supplied in the FCO parts kit using the hardware removed in steps 11 and 12).  
NOTE: The new replacement transformer supplied with EQ-01334-01 has a new transformer elbow mounting bracket with slightly longer mounting holes to allow more tolerance in transformer adjustment. Refer to FIGURE 6.
16. Connect the two (2) transformer orange wires to the tuning capacitor (C8) as previously removed in step 10, polarity is not important. These two orange wires are identified as having spade lugs attached at their ends and both enter the transformer windings at a location different from a 3rd orange wire containing no spade lug.

RM03-FCO-29

\_	\_	\_	\_	\_	\_	\_
d	i	g	i	t	a	l
\_	\_	\_	\_	\_	\_	\_

FCO RM03-M0034

PAGE 16 OF 21

17. Route the wires away from movable parts.
18. Connect the transformer wires to terminal strip TB1 by color code as previously noted in steps 7 and 8.

\*\*\*\*\*  
\* CAUTION \*  
\* \*  
\* TERMINAL CONFIGURATION FOR 220 VOLT, 50HZ OPERATION IS: \*  
\* \*  
\* COLOR TERMINAL NO. COLOR TERMINAL NO. \*  
\* ----- \*  
\* BLACK 1 YELLOW 4 \*  
\* ORANGE 2 GREY 5 \*  
\* BROWN 3 WHITE 6 \*  
\* \*  
\*\*\*\*\*

19. Tighten all terminal strip screws and replace plastic insulators.

\*\*\*\*\*  
\* WARNING \*  
\* \*  
\* ENSURE THAT ALL PLASTIC INSULATORS ARE REPLACED BEFORE PROCEEDING. \*  
\* \*  
\*\*\*\*\*

20. Steps 21 through 33 will move the power amplifier assembly (A3A04) and servo pre-amplifier assembly (A3A05) further away from the Transformer to allow more room for adjustment.  
NOTE: The power amplifier assembly and the servo pre-amplifier assembly are attached to the side of the magnet assembly.
21. Remove the two screws (10-32 x 3/8, Item 7 FIGURE 5) that secure the power amplifier to the deck casting. An offset phillips screwdriver will be needed.
22. Carefully remove the power amplifier assembly out of the Unit.
23. Remove the uppermost left hand screw (Item 11 FIGURE 5) on the preamp housing shield (Item 13) and save it. Carefully slide back the servo preamp shield (Item 13 FIGURE 5) enough to get access to the servo head plug.
24. Unplug the servo head from the preamp board and slide the preamp shield off the servo head plug.

d	i	g	i	t	a	l

FCO RM03-M0034

PAGE 17 OF 21

25. Remove the two most left-hand screws (10-32 x 3/8 Item 7 FIGURE 5) that secure the servo preamp housing to the baseplate and discard them. Carefully lift the servo preamp housing up approximately 2 inches. Disconnect connector J-8 (Item 36 FIGURE 5) from the bottom of the servo preamp housing.
26. Lift servo preamp housing out of the drive.
27. Install the four new standoffs supplied in the FCO kit to the baseplate in mounting holes for the servo preamp housing and the mounting holes for the power amp assembly, as shown in FIGURE 5.
28. Attach the servo preamp housing by first connecting J8 to the bottom of the servo preamp housing. Mount and secure the servo preamp housing to the new standoffs with the new screws (10-32 x 1/4) supplied in the FCO kit.
29. Install the servo preamp shield by sliding the servo head connector through slot in the servo preamp shield. Connect servo head connector to servo preamp. This connector is keyed. Make sure servo head cable is installed in cable clamp mounted on the baseplate.
30. Secure servo preamp shield into place with screw previously removed, see Item 11 Figure 5.
31. Replace tie wraps previously removed when the transformer was replaced.
32. Secure the power amp into place by installing the two new screws (10-32 x 1/4), supplied in the FCO kit, that mount the power amp to the new standoffs, but do not tighten. Install and secure screw in the upper left hand corner of the power amp assembly. Now tighten the two 10-32 x 1/4 inch screws.
33. Perform the transformer adjustment and inspection procedures outlined in sections 2, part 1. If the required clearance is obtained, continue with step 35 to verify proper operation of the drive.
34. Connect J200 to power amp assembly.
35. Connect the yellow faston connector to the tab in the upper left hand corner.
36. Restore the upper deck chassis assembly to its lowered position. Secure the two (2) top deck hold down screws.
37. Raise the logic card cage to its service position by sliding it back and lifting it up and over on its side. Refer to arrows 1 and 2 on FIGURE 1.

digital

FCO RM03-M0034

PAGE 18 OF 21

38. Connect the main AC power cord to the site power source and apply power to the drive.
39. Using a Digital volt-ohmmeter, the following DC voltages can be measured on the bottom of the card cage (FIGURE 8.).
  - A. +/- 5V (+/- 0.05V) on faston connectors.
  - B. +/- 20V (+/- 1.0V) on faston connectors.
  - C. +42V (+/- 2.0V) at Pin 32B on connector BAPA09.
  - D. -42V (+/- 2.0V) at Pin 3B on connector BAPA09.
  - E. +12V (+/- 0.3V) at Pin 8B on connector PA80.
  - F. -12V (+/- 0.3V) at Pin 8A on connector PA80.
40. Command the drive to perform repetitive seeks between cylinders 0 and 32.
41. The +5V output should read +5.0 V (+/- 0.05V). If not, adjust the +5 V potentiometer on card A1A03 (FIGURE 7) until it is within specification.
42. The -5V output should read -5.0V (+/- 0.05V). If not adjust the -5V potentiometer on card A1A03 (FIGURE 7) until it is within specification.
43. If any adjustment was necessary in the preceding two (2) steps, recheck both outputs.
44. Disconnect the Digital volt/ohmmeter from the logic chassis and power down the drive.
45. Remove the main AC power cord from the site power source.
46. Carefully return the logic chassis to its normal operating position and tighten the logic chassis clamp screws per FIGURE 1.
47. Install the drive top cover assembly.
48. Connect the drive main AC power cord to the site power source and apply power to the drive.
49. Power-up the drive and verify drive operation using the available diagnostics on site.
50. Change the revision of the drive to revision "T", fill out Lars Form as shown on attached example (see pages 19 thru 21) and log the performed FCO activity into the Digital Site Management Guide.









7-Nov-1986  
RM03-INDEX.A  
REV A

MICROMEDIA PUBLISHING


Tech Tip Index

Tech Tip Number	REV	Rel. Date	SB#	Title
-RM03--TT-01	0	16-May-78		Diag Failure/RP04/5/6, RM02/3
-RM03--TT-02	B	9-Jun-78		Troubleshooting
-RM03--TT-03	0	11-Jan-79		XXDP Diagnostic Media
-RM03--TT-04	0	1-Feb-79		Maintenance Print Errors
-RM03--TT-05	0	31-Jan-79		Module Pin Marking
-RM03--TT-06	0	31-Jan-79		Heat Problem
-RM03--TT-07	0	31-Jan-79		Alignment Problems
-RM03--TT-08	0	26-Mar-79		RL11/RM03 Configured on 1170
-RM03--TT-09	0	9-Mar-79		Side Panel Fastening
-RM03--TT-10	0	25-Apr-79		Head Alignment Locking Pin
-RM03--TT-11	A	7-May-79		Jumper for LCG 2020 Compatability
-RM03--TT-12	0	6-Jun-79		5.1 Volt Adjustment
-RM03--TT-13	A	10-Dec-79		Power Regulator Board Blows Fuse
-RM03--TT-14	0	12-Jul-79		Offline Tester Head Algnmt Problem
-RM03--TT-15	0	6-Aug-79		Upgrade Restriction
-RM03--TT-16	0	20-Jul-79		HCE's DTE's Errors
-RM03--TT-17	0	20-Oct-79		Premature Bearing Failure
-RM03--TT-18	0	7-Nov-79		Air Circulation Problem
-RM03--TT-19	0	18-Sep-79		Premature Bearing Failure
-RM03--TT-20	0	28-Jan-80		RM02/3 Will Not Run DEC/X11
-RM03--TT-21	0	1-Feb-80		Write Check Error w/o Data Check
-RM03--TT-22	0	20-Feb-80		Seek Incomplete & Misposition Prob
-RM03--TT-23	A	12-Aug-80		Velocity Gain Adjustment
-RM03--TT-24	0	5-Dec-79		Head Alignment Tool Problem
-RM03--TT-25	0	30-Apr-80		Fault Latch Guard
-RM03--TT-26	A	13-May-81		Power Supply-Vib Sensitivity/DCR's
-RM03--TT-27	0	28-Jul-80		RM02/3/5/80 Module Compatibility
-RM03--TT-28	0	28-Jul-80		ASGV vs 6SGV Speed Detect
-RM03--TT-29	0	28-Jul-80		RM02/3/5/80 MBA Backplane
-RM03--TT-30	0	11-Jul-80		Head Crashes
-RM03--TT-31	0	12-Aug-80		Dual Port Logic Test Part 2
-RM03--TT-32	0	1-Dec-80		RM02/3/5/80 Dual Port
-RM03--TT-33	0	9-DEC-80		240 to 220v 50 HZ Power Conversion
-RM03--TT-34	0	16-Jan-81		Head Identification
-RM03--TT-35	0	19-Mar-81		Head Refurbishment Guideline
-RM03--TT-36	0	16-Mar-81		Poor Massbus Cable ZIP Connectors
-RM03--TT-37	0	19-Mar-81		ARL Module Guidelines
-RM03--TT-38	0	2-Apr-81		NRZ to MFM Part No Confusion
-RM03--TT-39	0	9-Jul-81		Noise Suspectibility
-RM03--TT-40	0	14-Jul-81		New Part No for CDC Drive ECO
-RM03--TT-41	0	22-Jul-81		DECX11 Module RMDA0
-RM03--TT-42	0	14-Aug-81		Intermittant Positioning Errors
-RM03--TT-43	0	14-Aug-81		Read-Write Servo Intermittents
-RM03--TT-44	A	9-Feb-82		RH11 Setup for RM02/3 on 11/44
-RM03--TT-45	A	9-Feb-82		Emergency Retract Relay
-RM03--TT-46	A	10-Mar-82		+12V Power Supply Too Low

RM03-TT-1


-RM03--TT-47	A	22-Feb-82		RM02/2/5 Alt Head Alignment Proc
-RM03--TT-48	A	22-Apr-82		Velocity Gain Adjustment w/o FTU
-RM03--TT-49	A	18-Apr-82		Exclusive or Gate Error
-RM03--TT-50	A	18-Apr-82		Testing Carrage Bearings
-RM03--TT-51	A	15-Apr-82		Brake Assy Causing Intermnt Fail
-RM03--TT-52	A	28-Apr-82	231	Disk Pack Cleaning/Inspection
-RM03--TT-53	A	17-May-82	235	Pack Seal Adj/Hold Down Bolts
-RM03--TT-54	A	15-Apr-83	277	Header Compare Error
-RM03--TT-55	A	18-May-83	281	50 HZ Power Transformer Shorting
-RM03--TT-56	A	6-Jun-83	285	New Line Filter/Series 34 and up
-RM03--TT-57	A	26-Oct-83	305	Brake Noise and Grounding PCO's
-RM03--TT-58	A	3-Jan-84	314	Data Errors Due to Runout
-RM03--TT-59	A	3-Jan-84	314	Problem Using Rail Alignment Tool
-RM03--TT-60	A	24-Mar-84	325	EVRDA Rev 4.1 Problem
-RM03--TT-61	A	25-Jun-84	342	RM Massbus Adapter Caution
-RM03--TT-62	A	3-Jan-85	363	RM Adapter Power Supply Caution
-RM03--TT-63	A	6-Mar-85	372	Speed Sensor Problem
-RM03--TT-64	A	7-Oct-85	402	PCO: RM02-S0020 Documentation
-RM03--TT-65	A	2-OCT-85	402	CPX Head Inspection Tool Kit
-RM03--TT-66	A	10-Nov-86	456	Diagnostic CZRMPBO.BIC Failure

AM03-TT-2

	<b>FIELD SERVICE TECHNICAL MANUAL</b>					Option or Designator
	12 Bk <input type="checkbox"/>	16 Bk <input checked="" type="checkbox"/>	18 Bk <input checked="" type="checkbox"/>	32 Bk <input type="checkbox"/>	36 Bk <input checked="" type="checkbox"/>	RM02/3

Title <b>DIAGNOSTIC FAILURES ON RPS4, RPS5/6, RM2/3</b>				Tech Tip Number <b>RM02/3-TT-1</b>	
Author <b>Bill Davis/John Kwolek</b>		F.S. Office <b>Nagog Woods</b>		Date <b>6.5.78</b>	
Processor Applicability		Mtg /Sup. <b>Harry Dugas</b>		Date <b>5/14/78</b>	
All <b>11/40</b>		Approval <i>Harry Dugas</i>		Date	
				Revision <b>0</b>	
				Cross Reference	

1. There is a chance of diagnostic failures on disks capable of formatting in 16 bit and 18 bit modes when connected to an 11/40. Typically, failures will occur in 18 bit mode due to an internal CPU jumper.
2. When testing the 18 bit data field function, the diagnostics use the PA and PB unibus lines.
3. On PDP-11/40's without Parity Memory, jumper W5 on the M7234 CPU timing board is inserted, grounding the PA line, and thus disabling bit 17 of the 18 bit data field.
4. If failures occur in the 18 bit mode, check to see if W5 on the M7234 is in. If so, cut the jumper.
5. On KL10's with the 11/40 as a front end, this jumper should always be removed, regardless of the memory configuration (i.e., parity or non-parity).

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/3

Title <b>RM03/RM02 TROUBLESHOOTING</b>			Tech Tip Number <b>RM02/3-TT-2</b>		
Author <b>D. MCELVANEY/L. BUCHANAN</b>		FS Office <b>MAYNARD</b>		Date <b>6/9/78</b>	
Revision <b>B</b>		Mgr /Sup <b>LARRY GOELZ</b>		Date <b>6/9/78</b>	
Processor Applicability		Approval <i>Larry Goelz</i>		Date <b>6/9/78</b>	
AN		11		Cross Reference	

READ THIS BEFORE YOU START TROUBLESHOOTING

THIS TECH TIP IS TO EMPHASIZE THE IMPORTANCE OF THE  $\pm 5$  VOLT ADJUSTMENT ON RM03/02 DISK DRIVES. THE SPECIFICATIONS FOR THIS ADJUSTMENT ARE  $5.1 \pm .05$  VOLTS POSITIVE AND NEGATIVE. A DVM ACCURATE TO .01 VOLTS MUST BE USED TO MAKE THE ADJUSTMENT, NOT A SCOPE. ALSO, THE VOLTAGE MUST BE MEASURED ON THE LOGIC CHASSIS WHILE PERFORMING REPETITIVE SEEKS FROM CYLINDER 0 TO 32. ANOTHER METHOD THAT HAS BEEN FOUND EFFECTIVE IS TO SET THE VOLTAGE AT 5.12 TO 5.15 VDC WITHOUT PERFORMING THE SEEKS.

THIS ADJUSTMENT MAY DRIFT AND SHOULD BE CHECKED FREQUENTLY, PARTICULARLY IF THE UNIT IS CLOSE TO AN AIR CONDITIONING VENT OR THE SITE TEMPERATURE VARIES APPRECIABLY. ALWAYS CHECK THIS ADJUSTMENT BEFORE AND AFTER ANY C.M. ON THE DRIVE, AS A VERY SMALL ERROR IN THIS ADJUSTMENT CAN APPEAR AS RANDOM ERRORS OF ANY TYPE. PERFORMING THE 5 VOLT ADJUSTMENT AS A REGULAR PART OF PM WILL SIGNIFICANTLY REDUCE INTERMITTENTS ON THIS (OR ANY) C.D.C. DRIVE.

THE PLUS FIVE VOLT REGULATOR FOR THE MBA, RH70, CACHE, AND MEMORY MANAGEMENT SHOULD BE SET FOR 5.05 TO 5.10.

PAGE 1A	PAGE REVISION B	PUBLICATION DATE NOV 1978
---------	-----------------	---------------------------

RM03 TT-4

Title <b>RM02/3 XXDP DIAGNOSTIC MEDIA</b>		Tech Tip Number <b>RM02/3-TT-3</b>	
Author <b>BOB BRASSARD</b> <i>BRB</i>	F S Office <b>MERRIMACK</b>	Date <b>11 JAN 79</b>	Revision <b>0</b>
Processor Applicability <b>All</b>	Mgr /Sup <b>IRV PATON</b> <i>IP</i>	Date <b>11 JAN 79</b>	Cross Reference
Approval		Date	

### RM03 XXDP SUPPORTING PROGRAMS

AS OF JANUARY 79, THE RM02/3 DISK DRIVE SUBSYSTEM WILL HAVE XXDP DIAGNOSTIC STORAGE, LOADING, MEDIA COPYING, AND DEC/X GENERATION CAPABILITIES THROUGH DECO'S (DIAGNOSTIC ENGINEERING CHANGE ORDER) TO THE XXDP SOFTWARE PACKAGE. PREVIOUSLY, THE RM03 HAD NOT BEEN SUPPORTED BY DIAGNOSTIC OR RELEASE ENGINEERING AS AN XXDP DIAGNOSTIC LOAD DEVICE. THE DECO'S WERE ORIGINALLY PUBLISHED TO THE FIELD ON MICROFICHE MINI LIBRARY SPEED BULLETIN #62 (NOVEMBER 27, 1978). THE UPDATED SOFTWARE UTILITIES AND DOCUMENTATION AND THE NEW RM02/3 XXDP BOOT/LOAD MONITOR RRDP WILL BE AVAILABLE IN THE DELAYED JANUARY 1979 SDC XXDP RELEASE, ORIGINALLY SCHEDULED FOR DECEMBER 1978.

STANDARD XXDP MEDIA CREATION PROCEDURES AS FOUND IN THE XXDP USER'S MANUAL (CZQXA??) SHOULD BE FOLLOWED TO CREATE AND TRANSFER DIAGNOSTICS TO THE "RRDP" MEDIA. BELOW IS A LIST OF XXDP SOFTWARE PRODUCTS AND THEIR MINIMUM REVISION LEVELS WHICH SUPPORT THE RM02/3.

<u>MAINDEC #</u>	<u>REV/ECO TALLY</u>	<u>MAINDEC TITLE</u>	<u>DECO DATE</u>
MD-11-CZQUR	L0/05	CZQURLO XXDP UPD3R	15 OCT 78
MD-11-CZQUS	E0/04	CZQUSE0 XXDP HLP FILE (HELP FILE)	15 OCT 78
MD-11-CZQU1	C0/02	CZQU1C0 XXDP UPD3 PROG	15 OCT 78
MD-11-CZQU2	C0/02	CZQ72C0 XXDP COPY 2 PROG	15 OCT 78
MD-11-CZQU6	A0/00 (NEW!!)	CZQU6A0 RRDP XXDP RM02/3 MON	15 OCT 78
MD-11-CZQUX	H0/07	CZQUXH0 DEC/X11 CONF1 LKR	20 SEP 78

### RM03 XXDP DISCLAIMERS

1. ONLY THE "TOP LEVEL" (LARGEST) UTILITIES - UPD3, UPD3R, COPY2, DEC/X CONFIGURATOR LINKER (CZQUX-H0) - HAVE BEEN MODIFIED FOR THE RM02/3 BECAUSE THE RM03 IS GENERALLY NOT FOUND ON SYSTEMS REQUIRING THE SMALLER UTILITIES (WHICH WILL NOT BE UPGRADED FOR THE RM03): UPD1, UPD1A, UPD2, COPY1, DEC/X SMALL SYSTEM CONFIGURATOR LINKER (CZQUY E0).
2. THE "XTECO" XXDP TEXT EDITOR (CZQUG-G0) HAS NOT BEEN MODIFIED FOR USE WITH THE RM02/3.
3. ONLY THE NEW DEC/X CONFIGURATOR LINKER (CZQUX-H0), WHICH IS INCOMPATIBLE WITH THE "OLD" DEC/X "LIBRARIES AND MODULES", WILL SUPPORT THE

DEC

2

DEC CONFIDENTIAL This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only

N 11000 12 R277 (78V)

RM08-TT-5

Title <b>RM02/3 XXDP DIAGNOSTIC MEDIA</b>		Tech Tip Number <b>RM02/3-TT-3</b>	
Author <b>BOB BRASSARD</b>	FS Office <b>MERRIMACK</b>	Date <b>11 JAN 79</b>	Revision <b>0</b>
Processor Applicability All       S		Mgr /Sup. <b>IRV PATON</b>	Date <b>11 JAN 79</b>
		Approval	Date
		Cross Reference	

RM02/3 FOR RUN-TIME-EXERCISER (RTE) GENERATION.

4. DIAGNOSTICS: THE 11/70 INSTRUCTION EXERCISER (EQKC??) AND RM70 CONTROLLER TEST (ERHA??) HAVE NOT BEEN MODIFIED TO WORK WITH THE RM02/3.

RM02/3 XXDP DIAGNOSTIC MEDIA POLICY

THE RM02/3-P DISK PACK WILL NOT BE AVAILABLE FROM SDC-NR, NOR WILL IT BE USED BY F.A.&T. (NI, WM) AS AN XXDP DIAGNOSTIC DISTRIBUTION MEDIA. F.A.&T. WILL CONSIDER EXCEPTIONS TO THIS POLICY ON A CASE-BY-CASE BASIS, JUST AS WITH OTHER LARGE DISK PRODUCTS (RP02-6), FOR SYSTEMS WITH THE RM02/3 AS THE SOLE XXDP LOAD DEVICE IF FIELD SALES REQUESTS AND THE PRODUCT LINE FUNDS F.A.&T. TO TRANSFER THE XXDP DIAGNOSTIC PACKAGE TO AN RM02/3-P.

ORDERING INFORMATION

XXDP DIAGNOSTIC PACKAGES AND THE RM03 SUPPORTING UTILITIES ARE AVAILABLE ON THE FOLLOWING STANDARD MEDIA AND XXDP PACKAGE NAMES:

RX01/RXDP, RX02/RXDP, RL01/RLDP, RK05/RKDP, RK06-7/RMDP, TU60/TADP, TU56/TCDP (PENDING OBSOLESCENCE), TU10-16/TMDP-THDP, TR79/TRDP, AND PAPERTAPE.

NOTE THAT F.S. OFFICES AUTOMATICALLY RECEIVE PAPERTAPES AND DOCUMENTATION FOR UPGRADED AND NEW PDP11 DIAGNOSTIC SOFTWARE THROUGH THE "PDP11 DIAGNOSTIC PAPERTAPE AND DOCUMENT F.S. LIBRARY".

TO ORDER ANY OF THE ABOVE XXDP DISTRIBUTION MEDIA AND/OR DOCUMENTATION, CONSULT THE FOLLOWING FOR THE CORRECT PROCEDURES AND UNC (UNIFIED NUMBERING CODE) COMPONENT PART #'S:


1. ADMIN-TT-3: "F.S. PROCEDURES FOR ORDERING SOFTWARE AND PRINTS".  
MINIFICHE TECH INFO SECTION: "TT-MISC". (MISC. TECH TIPS)
2. PDP11 DIAGNOSTIC SOFTWARE COMPONENTS CATALOGUE: ORDER #:  
AV-8021F-TC (NO CHARGE)
3. PDP11 MAINDEC INDEX CZQAF??: MINIFICHE DIAGNOSTIC SECTION: "11 INDEX",  
DOCUMENT ORDER # AC-9024Q-MC.

Title <b>RM03 MAINTENANCE PRINT ERRORS</b>				Tech Tip Number <b>RM02/3-TT-4</b>	
Author <b>M. J. DONESKI</b>		FS Office		Date <b>1/31/79</b>	Revision <b>0</b>
Processor Applicability		Mgr /Sup.		Date	
All	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		Approval		Date <b>2/1/79</b>	
Cross Reference					

IN THE RM03 DISK DRIVE MAINTENANCE PRINT SET, THERE IS A FLIP/FLOP LABELED "FINE F/F" ON PAGE 1-82, SHEET #2, CROSS REFERENCE #192. THIS F/F IS LABELED INCORRECTLY. THE OUTPUTS OF THIS F/F READS (-COARSE OUTPUT PIN 16B) SET-SIDE, AND (-FINE OUTPUT PIN 16A) CLEAR-SIDE. THEY SHOULD READ (-FINE OUTPUT PIN 16A) SET-SIDE AND (-COARSE OUTPUT PIN 16B) CLEAR-SIDE.

RM03 TT 7

P  
F  
M  
C  
D  
L  
  
PC  
  
R/  
SP  
SP  
  
B  
B  
H  
M  
S  
|


	<b>FIELD SERVICE TECHNICAL MANUAL</b>				<b>Option or Designator</b>
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/3

<b>Title</b> RM03 MODULE PIN MARKING				<b>Tech Tip Number</b> RM02/3-TT-5	
<b>Processor Application</b>		<b>Author</b> DONESKI, M.J.		<b>Rev</b> 0	
<b>All</b>		<b>Approval</b> <i>[Signature]</i>		<b>Cross Reference</b>	
<b>X</b>		<b>Date</b> 1/31/79			

A problem exists on the RM03 modules and extenders. The pins are labeled 1 to 17 (A&B) then 21 to 34 (A&B). Be very careful when shooting the backplane. Pins 18, 19, and 20 were omitted by C.D.C.

<b>PAGE</b> 4A	<b>PAGE REVISION</b> 0	<b>PUBLICATION DATE</b> FEB 1979
----------------	------------------------	----------------------------------

HMU3-TT-8


	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/3

Title <b>RM03 HEAT PROBLEM</b>				Tech Tip Number <b>RM02/3-TT-6</b>	
All Processor Applicability			Author <b>DONESKI, M.J.</b> Rev <b>0</b>		Cross Reference
<b>X</b>			Approval <i>[Signature]</i> Date <b>1/31/79</b>		

In the RM03 disk drive, the card cage is cooled by directed air flow. When the card cage is in the maintenance position, for trouble shooting, it is no longer cooled by a directed air flow, and the modules start heating up fairly fast. Caution should be taken when trouble shooting in this area.

PAGE 48	PAGE REVISION 0	PUBLICATION DATE FEB 1979
---------	-----------------	---------------------------

RM03-TT-9

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				<b>Option or Designator</b>
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/3

<b>Title</b> RM03 ALIGNMENT PROBLEMS				<b>Tech Tip Number</b> RM02/3-TT-7	
<b>App</b> X	<b>Processor Applicability</b>		<b>Author</b> DONESKI, M.J.	<b>Rev</b> 0	<b>Cross Reference</b>
			<b>Approval</b> <i>[Signature]</i>	<b>Date</b> 1/21/79	

The air pressure inside the RM03 shroud area is critical to head alignment, when the drive is up and running. Therefore, any disturbance to the drive cover can and will cause momentary, and prolonged, alignment problems. Nothing (pack, pack covers, coffee cups, elbows, or dead bodies) is to be placed on top of the RM03.

<b>PAGE</b> 4C	<b>PAGE REVISION</b> 0	<b>PUBLICATION DATE</b> FEB 1979
----------------	------------------------	----------------------------------

RM08-TT-10

Title <b>RL11 AND RM03 CONFIGURED ON 11/70</b>		Tech Tip Number <b>RM02/3-TT-8</b>	
Author <b>CLAY HORSE</b>	F.S. Office <b>CZ</b>	Date <b>3.26.79</b>	Revision <b>0</b>
Processor Applicability <b>All</b>	Mgr./Sup. <b>B. NICKERSON</b>	Date	Cross Reference
	Approval	Date	<b>RL11-TT-4</b>

THIS TECH TIP IS FOR CROSS REFERENCE ONLY.

5

**DEC CONFIDENTIAL** This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only.

EN-11000-12-0277-170V1

REV A


**RM08-TT-11**

**APR 1979**

<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/3
12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title <b>RM02/RM03 SIDE PANEL FASTENING</b>			Tech Tip Number <b>RM02/3 - TT-9</b>	
Author <b>GREG EKHOLM</b>	F.S. Office <b>MAYNARD</b>	Date <b>3/9/79</b>	Revision <b>0</b>	
Processor Applicability All	Mgr./Sup. <b>B. NICKERSON</b>	Date	Cross Reference	
	Approval	Date		

A RECENT ECO # TO THE RM02/03 CABINET WILL NOW REQUIRE FASTENING THE DEC SIDE PANELS ON TO THE MODIFIED H9691 CABINET AT THE TOP OF THE H9691 INSTEAD OF THE BOTTOM AS WAS THE PREVIOUS METHOD. THE OLD HOLES WILL NOT BE REMOVED SO THERE SHOULD BE NO PROBLEM WITH DOWNWARDS COMPATABILITY. ON THE NEW STYLE UNITS IN ORDER TO REMOVE THE SIDE PANELS YOU WILL HAVE TO REMOVE THE TWO SCREWS AND WASHERS ON EACH SIDE PANEL FROM THE MBA AREA OF THE DRIVE. THE SCREWS WILL BE TOWARDS THE TOP OF THE CABINET CLOSE TO THE RETAINING LUGS FROM THE SIDE PANEL.



Title RMO3 HEAD ALIGNMENT LOCKING PIN		Tech Tip Number RM02/3-TT-10	
Author Larry McGee	F.S. Office Memphis, Tn.	Date 2-26-79	Revision 0
Processor Applicability		My Sup. _____	Cross References
All		Approved: <i>[Signature]</i>	Date 4-25-79

WHEN REMOVING THE COVER FOR ACCESS TO THE HEAD ASSEMBLY, DRIVE LOGIC, AND POWER SUPPLY, THE "HEAD ALIGNMENT LOCKING PIN" HAS A TENDENCY TO GET PULLED OUT OF ITS STORAGE HOLE AND MAY DROP IN THE DRIVE. THE RING IN THE LOCKING PIN GETS MAGNETIZED FROM THE STRONG MAGNETIC FIELD OF THE EMA ASSEMBLY AND MAGNETICALLY ADHERES TO THE DRIVE COVER. TO PREVENT THIS FROM HAPPENING, USE TAPE TO HOLD THE LOCKING PIN IN PLACE

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/3

Title RM02/03 Jumper for LCG 2020 Compatibility			Tech Tip Number RM02/02-TT-11	
Author J. Gannelli/M. Ronayne	FS Office PROD SUPPORT MNEG. ENG.	Date 4/13/79	Revision A	
Processor Applicability	Mgr /Sup A. O'Donnell	Date 4/19/79	Cross Reference	
All	Approval <i>[Signature]</i>	Date 5/2/79		

FOR LCG 2020 SOFTWARE COMPATIBILITY INSTALL JUMPER FROM E6E1 to E6C2 (GROUND) ON THE DEC MBA CONTROLLER BACKPLANE.

REASON:


REFERENCE (RM02/03) DISK SYBSYSTEM USERS GUIDE  
 0EK-RM023-UG-001 PAGE 4-55 TABLE 4-22. PRINT  
 REFERENCE RM03 FIELD MAINTENANCE PRINT SET, PRINT  
 DS6 - SHEET 6 OF 15 COORDINATES C3 SIGNAL NAME  
 BP144 ENBH.

NOTE:

1. THIS JUMPER INHIBITS BAD SECTOR ERROR FROM COMING UP AS A RESULT OF MF OR UF BITS BEING TRUE IN FIRSTHEADER WORD. LCG 2020 DO NOT USE THESE BITS TO FLAG BAD SECTORS.
2. FOR ONLY 2020 SYSTEMS (NOT 8 & 11 SYSTEMS). IF YOU ARE HAVING TROUBLE WITH A PDP11 SYSTEM GETTING MF OR UF BITS, CHECK TO MAKE SURE THIS JUMPER IS NOT IN.

PAGE 6A	PAGE REVISION A	PUBLICATION DATE MAY 1979
---------	-----------------	---------------------------

KMCC-TT 14

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/3
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title <b>5.1 VOLT ADJUSTMENT</b>			Tech Tip Number <b>RM02/3-TT-12</b>		
Author <b>Larry Wakeman</b>		FS Office <b>San Francisco</b>		Date <b>7-MAY-79</b>	
Revision <b>-0-</b>		Processor Applicability		Cross Reference	
All		Mfg / Sup <i>[Signature]</i>		Date <b>5-7-79</b>	
		Approval <i>[Signature]</i>		Date <b>6-6-79</b>	

When adjusting the 5.1 Volt supply in the RM03, it is best to have the drive performing oscillating seeks between cylinders 0 and 32 ('Normal Load'). The following program will perform the requisite seeks.

```

LOC.    CONT.
1000    12737      MOV     @DRV,@@RMCS2
1002          0           : DRIVE @
1004    176710
1006    12737      MOV     @DRVCLR,@@RMCS1
1010          11
1012    176700
1014    105737     TSTB   @@RMCS1
1016    176700
1020    100375     BPL    .-2
1022    12737      MOV     @PACACK,@@RMCS1
1024          23
1026    176700
1030    105737     TSTB   @@RMCS1
1032    176700
1034    100375     BPL    .-2
1036    13737     LOOP:  MOV     @SWR,@@RMD
1040    177570
1042    176734
1044    12737      MOV     @SEEK,@@RMCS1
1046          5
1050    176700


```

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip see Administration Tech Tip Number 2.

Page <b>7</b>	Page Revision <b>0</b>	Publication Date <b>Jun 1979</b>
---------------	------------------------	----------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/3
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title 5.1 VOLT ADJUSTMENT (cont.)			Tech Tip Number RM02/3-TT-12
Author LARRY WAKEMAN	FS Office SAN FRANCISCO	Date 7 MAY 79	Revision 0
Processor Applicability All	Mgr /Sup	Date	Cross Reference
	Approval G. EKHOLM	Date 6.6.79	

LOC.	CONT.		
1052	105737	TSTB	@#RMCS1
1054	176700		
1056	100375	BPL	.-2
1060	105737	TSTB	@#RMDS
1062	176712		
1064	100375	BPL	.-2
1066	12737	MOV	#0,@#RMDC
1070	0		
1072	176734		
1074	12737	MOV	#SEEK,@#RMCS1
1076	5		
1100	176700		
1102	105737	TSTB	@#RMCS1
1104	176700		
1106	100375	BPL	.-2
1110	105737	TSTB	@#RMDS
1112	176712		
1114	100375	BPL	.-2
1116	747	BR	LOOP

To adjust the 5.1 volt supply, bring drive to ready, Load Address 1000, place 40 in the switch register and Start. Adjust for 5.1 volts at the fastons on the bottom of the logic cage. This adjustment is very important as even a slight variation can cause problems with the drive.

If you wish to use a drive other than 0, just load the drive number in location 1002 and restart.

DEC CONFIDENTIAL

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 8	Page Revision 0	Publication Date JUN 1979
-----------	--------------------	------------------------------

PRINTED IN USA

EN 1189C 12 R277 78V

RMCS-TT-16

<b>FIELD SERVICE TECHNICAL MANUAL</b>					Option or Designator RM02/3
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12 Bk	16 Bk	18 Bk	32 Bk	36 Bk	

Title RM02-03 power regulator board fuse blowing				Tech Tip Number RM02/3-TT-13	
Author Tom Tobiasen		F S Office Colo Springs		Date 10 May 79	
Processor Applicability		Mgr /Sup Rollie Neff		Date 10 may 79	
All 11 10 20 VAX		Approval GREG EKHOLM		Date 10 DEC 79	
				Revision A	
				Cross Reference	

SUBJECT F2 SHV POWER REGULATOR BOARD

ON SOME RM02-03'S THE 6 AMP FUSE (F2) ON THE SHV REGULATOR BOARD, MAY BLOW INTERMITTANTLY ON DRIVE POWER UP. THIS BOARD DEVELOPS PLUS AND MINUS 5 VOLTS . REPLACE THE 6 AMP FUSE WITH AN 8 AMP FUSE PER ECO RM03-00011. THE OLD REGULATOR IS ASHV AND HAS 6 AMP FUSES. THE NEW REGULATOR IS BSHV AND HAS 8 AMP FUSES. OTHER THAN THE FUSE THERE IN NO DIFFERENCE BETWEEN THE TWO BOARDS.


CDC HAS ALSO CHANGED THE PLUS AND MINUS 42 VOLT REGULATOR BOARD. THE OLD ONE IS A 5 SJV AND HAS A 6 AMP FUSE ON IT. THE NEW ONE IS A ASJV AND HAS BOTH 8 AMP AND A BLEEDER RESISTER ON IT. AT THE PRESENT TIME IT IS NOT RECOMMENDED TO CHANGE THESE 6 AMP FUSES ON THE 5 SJV TO 8 AMP FUSES.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 9	Page Revision B	Publication Date DEC 1979
--------	-----------------	---------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				<b>Option or Designator</b>
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/3

<b>Title</b> RM03 OFFLINE TESTER HEAD ALIGNMENT PROBLEM		<b>Tech Tip Number</b> RM02/3-TT-14	
<b>Author</b> JOHN R. STRAUSS		<b>F.S Office</b> COLUMBUS OH. <b>Date</b> 2-JUL-79	
<b>Processor Applicability</b>		<b>Revision</b> 0	
<b>All</b>		<b>Mgr /Sup.</b> JACK DONAHUE <b>Date</b> 2-JUL-79	
		<b>Approval</b> <i>Greg Etkin</i> <b>Date</b> 7/12/79	
		<b>Cross Reference</b>	


WHEN USING THE OFFLINE TESTER FOR HEAD ALIGNMENT, THERE IS A POSSIBILITY OF GETTING A FALSE INDICATION WHILE ALIGNING THE HEADS DUE TO EMI BEING INDUCED IN THE CABLES USED FOR THE TESTERS METER. THESE CABLES RUN FROM THE TEST CARD WHICH PLUGS INTO SLOT A2 ON THE RM03 TO THE TESTER'S METER INPUT.

I FOUND THAT TO GET A CORRECT INDICATION ON THE METER, YOU SHOULD TRY TO KEEP THE METER TEST LEADS SEPARATED. I ALSO FOUND THAT IF THESE LEADS ARE LYING ACROSS THE REGULATORS ON THE BACK OF THE DRIVE THIS CAN ALSO GIVE YOU A FALSE INDICATION.

TO RESOLVE THIS PROBLEM, IT MAY BE A GOOD IDEA TO USE SHIELDED CABLES FOR THESE TEST LEADS.

<b>PAGE</b> 9A	<b>PAGE REVISION</b> B	<b>PUBLICATION DATE</b> DEC 1979
----------------	------------------------	----------------------------------

RM03-TT-18

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/3
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title <b>RM02 TO RM03 UPGRADE RESTRICTION</b>			Tech Tip Number <b>RM02/3 - TT - 15</b>	
Author <b>BOB BRASSARD</b>	F S Office <b>MK1-2/G15</b>	Date <b>6 AUG 79</b>	Revision <b>0</b>	
Processor Applicability <b>All 10'11'5 V   A   X  </b>		Mgr /Sup <b>IRV PATON</b>	Date <b>6 AUG 79</b>	Cross Reference
		Approval <b>GREG EKHOLM</b>	Date	

**PROBLEM**

FIELD UPGRADES OF THE RM02 TO THE RM03 IS NOT RECOMMENDED OR SUPPORTED BY THE PRODUCT MANAGER OR F.S. PRODUCT SUPPORT. ALTHOUGH THE ONLY FUNCTIONAL DIFFERENCE BETWEEN THE TWO PRODUCTS IS PACK SPIN RATE (RM02 = 2400 RPM; RM03 = 3600RPM) AND DATA TRANSFER RATE (16 BIT FORMAT: RM02 = 806 KB/SEC; RM03 = 1212 KB/SEC), THE FOLLOWING PARTS ARE DIFFERENT BETWEEN THEM:

LOGIC MODULES (7):	<u>RM03 DESIG.</u>	<u>RM02 DESIG.</u>	<u>FUNCTION</u>	<u>LOCATION</u>
	HFRV	JFRV	FINE SERVO	A2A03
	HLRV	LLRV	DATA LATCH	A2A05
	CLSV	BLSV	WRITE PLO	A2A01
	ELTV	NLTV	ACC. CONT.	A2B08
	BLZV	CLZV	READ PLO	A2A06
	NZJN	SZJN	HD SEL. AMP	A3A02
	EZKN	DZKN	WR DRIVER	A3A03
POWER SUPPLIES:	ASHV	BSHV	±5 V. - REG.	A1A03
(FUSE CHANGE ONLY)				
R/W HEADS:	ALL 5 R/W HEADS AND 1 SERVO HEAD DIFFERENT.			
SPINDLE ASSY.	3600 R.P.M.	2400 R.P.M.		
SPINDLE MOTOR:	(292 MFD.)	(193 MFD.)	DRIVE MOTOR	A3DM1
			STARTING CAP.	A3C6
			DRIVE BELT	(A3DM1)

ADDITIONALLY, THERE ARE NO WRITTEN "UPGRADE" PROCEDURES, NO DISK ENGINEERING SUPPORT, NO MANUFACTURING TESTS AND NO FIELD EXPERIENCE TO GUARANTEE SUCCESS WITH THE UPGRADE. THIS RESTRICTION HAS NOT BEEN MENTIONED IN ANY OF THE RM02/3 DOCUMENTATION OR MAINTENANCE PLAN.


**SOLUTION/BACKGROUND - (CONTINUED ON NEXT PAGE.)**

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip see Administration Tech Tip Number 2.

Page <b>10</b>	Page Revision <b>0</b>	Publication Date <b>AUG 1979</b>
----------------	------------------------	----------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/3
	12 Bit <input type="checkbox"/>	16 Bit <input type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title RM02 TO RM03 UPGRADE RESTRICTION			Tech Tip Number RM02/3 - TT- 15		
Author BOB BRASSARD <i>MB</i>		F S Office MK1-2/G15	Date 6 AUG 79	Revision 0	
Processor Applicability		Mgr./Sup. IRV PATON	Date 6 AUG 79	Cross Reference	
All	10's	11's	V	A	X
		Approval GREG EKHOLM	Date		

SOLUTION/BACKGROUND

THE NEED TO UPGRADE THE RM02 MAY ARISE WHEN PLANNING A MOVE OR RE-INSTALLING AN RM02 FROM A UNIBUS - BASED SYSTEM (11/34 - 11/60) TO A HIGHER PERFORMANCE CPU (11/70, VAX, 10,20,ETC.). THE FACT IS THAT THE RM02 TRANSFER RATE IS ONLY 33% SLOWER THAN THE RM03 - THIS WAS INTENDED TO PREVENT "SWAMPING" / OVERLOADING OF UNIBUS SYSTEMS - AND IS TOTALLY COMPATIBLE WITH LARGER SYSTEMS AND RM03'S: MASSBUS, DIAGNOSTICS, RM02/3 MIXES. THAT PERFORMANCE DIFFERENCE IS FURTHER REDUCED WHEN CONSIDERING THAT NO DATA IS TRANSFERRED DURING HEAD REPOSITIONING ("SEEKS") WHICH TAKES A SIGNIFICANT AMOUNT OF THE DRIVE'S TIME. (THE SEEK PERFORMANCE BETWEEN THE RM02 AND RM03 IS IDENTICAL, ALTHOUGH AVERAGE ROTATIONAL LATENCY INCREASES FROM 8.3 TO 12.5 MILLISECONDS - THE DIFFERENCE REPRESENTING ONLY 14% OF THE 30MS. AVERAGE SEEK TIME.) UNLESS CONTINUOUS MASSBUS DATA TRANSFERS CAN BE MAINTAINED ON AN RM02/3 SUBSYSTEM THROUGH THE USE OF "OVERLAPPED - SEEK" SOFTWARE DEVICE DRIVERS AND MULTIPLE "SPINDLES," THE NET THROUGHPUT DIFFERENCE BETWEEN THE RM02 AND RM03 SHOULD BE INSIGNIFICANT. (NOTE: DISK MEDIA AND FORMATS ARE IDENTICAL AND INTERCHANGEABLE.)

CONCLUSION

THEREFORE, BECAUSE OF THE SMALL THROUGHPUT DIFFERENCE, THERE IS VERY LITTLE PRACTICAL ADVANTAGE TO UPGRADING FROM RM02 TO RM03 - THROUGH EITHER MODIFICATION OR DRIVE REPLACEMENT - IN THESE SITUATIONS.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 11	Page Revision A	Publication Date OCT 1979
---------	-----------------	---------------------------

PRINTED IN U.S.A.

[ ]	<b>FIELD SERVICE TECHNICAL MANUAL</b>				<b>Option or Designator</b>
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/3

<b>Title</b> RM03 HCE's DTE's ERRORS			<b>Tech Tip Number</b> RM02/3-TT-16		
<b>Author</b> Jimmie Ray McKenzie		<b>F S Office SWD Support/PX Date</b> 7/20/79		<b>Revision</b> 0	
<b>Processor Applicability</b>		<b>Mgr /Sup</b> Gary Kline <b>Date</b> 7/20/79		<b>Cross Reference</b>	
<b>All</b>		<b>Approval</b> <i>[Signature]</i> GREG EKHOLM			

The shield that covers the servo head lead on the servo pre-amp has to be reinstalled whenever a servo head or preamplifier is replaced. Failure to do this will result in DTE's and HCE errors, particularly on the upper cylinders.

<b>PAGE</b> 11A	<b>PAGE REVISION</b> A	<b>PUBLICATION DATE</b> OCT 1979
-----------------	------------------------	----------------------------------

RM03-TT-21


Title <b>PREMATURE BEARING FAILURE</b>			Tech Tip Number <b>RM02/3-TT-17</b>	
Author <b>A. GROVER</b>		F.S. Office <b>UK</b>	Date <b>18 SEP 79</b>	Revision <b>0</b>
Processor Applicability		Mgt./Sup. <b>L. YOUNG</b>	Date	Cross Reference
AN		Approval: <b>GREG EKHOLM</b>	Date <b>20.OCT.79</b>	

It is becoming increasingly apparent that a number of sites are suffering from bearing failure on RM03's. The first indications of this are Seek incomplete and HCE's (header compare errors), if no attention is paid to these symptoms a head crash is almost certain to follow.

It is possible to prevent this by carefully monitoring the state of the rails and carriage bearings at P.M. time paying particular attention to the adjustable bearing.

Under normal conditions the rail should show signs of even wear over the whole width of the bearing - if the bearing is beginning to fail the wear is over a very narrow portion - at the same time there will be signs of over heating on the bearing - i.e. change of colour.

When these signs are detected the carriage/rail should be changed at the earliest opportunity.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/3

Title <b>RM03 AIR CIRCULATION PROBLEM</b>			Tech Tip Number <b>RM03-TT-18</b>		
Author <b>JOHN STRAUSS</b>		F.S Office <b>COLUMBUS, OH</b>		Date <b>23 AUG 79</b>	
Processor Applicability		Mgr. Sup. <i>John Strauss</i>		Date <i>27 Oct 79</i>	
All		Approval <i>J. Strauss</i>		Date <i>7 Oct 79</i>	
				Cross Reference	

WHILE TROUBLESHOOTING AN RM03 PROBLEM WE IN COLUMBUS ENCOUNTERED AN AIR FLOW PROBLEM THAT WE WERE NOT AWARE OF ON RM03'S UNTIL WE CALLED DON SMITH IN CHICAGO (REGIONAL SUPPORT). WE IN FACT FOUND THE ORIGINAL CALL OUT PROBLEM WHICH WAS A BAD HEAD #4. AFTER REPLACING THE BAD HEAD WE LEFT THE COVERS OFF WHILE RUNNING DIAGNOSTICS TO CONFIRM THE FIX.

SOON AFTERWARDS WE STARTED GETTING DATA CHECK ERRORS ON HEAD ONE SO I SWAPPED HEAD ONE'S CABLE WITH HEAD TWO'S CABLE AND THE PROBLEM MOVED TO HEAD TWO, SO I SWAPPED OUT HEAD ONE. THE PROBLEM STAYED IN THE DRIVE SO I CALLED DON SMITH IN REGION AND HE ADVISED ME OF THE AIR CIRCULATION PROBLEM AND SAID THAT YOU SHOULDN'T RUN THESE DRIVES FOR MORE THAN AN HOUR AND A HALF WITHOUT THE COVERS.

I PUT THE COVERS BACK ON THE DRIVE AND AFTER A FEW MINUTES OF SETTLE DOWN TIME THE PROBLEM WENT AWAY. REMEMBER THIS WHILE TROUBLESHOOTING THESE DRIVES. IF NECESSARY STOP AND PUT THE COVERS BACK ON THE DRIVE FOR AWHILE TO ENSURE THAT YOU ARE GETTING THE CORRECT INDICATIONS WHILE PURSUING PROBLEMS.

PAGE 12A	PAGE REVISION A	PUBLICATION DATE NOV 1979
----------	-----------------	---------------------------

RM03 TT-23

Title <b>PREMATURE BEARING FAILURE</b>		Tech Tip Number <b>RM02/3-TT-19</b>	
Author <b>A. GROVER</b>	FS Office <b>READING (RB)</b>	Date <b>18 SEP 79</b>	Revision <b>0</b>
Processor Applicability <b>All</b>	Mgr /Sup. <b>I. YOUNG</b>	Date <b>18 SEP 79</b>	Cross Reference
	Approval <b>G. EKHOLM</b>	<i>REL</i> Date	

IT IS BECOMING INCREASINGLY APPEARENT THAT A NUMBER OF SITES ARE SUFFERING FROM BEARING FAILURE ON RM03'S. THE FIRST INDICATIONS OF THIS ARE SEEK INCOMPLETE AND HCE'S (HEADER COMPARE ERRORS), IF NO ATTENTION IS PAID TO THESE SYMPTOMS A HEAD CRASH IS ALMOST CERTAIN TO FOLLOW.

IT IS POSSIBLE TO PREVENT THIS BY CAREFULLY MONITORING THE STATE OF THE RAILS AND CARRIAGE BEARINGS AT P.M. TIME PAYING PARTICULAR ATTENTION TO THE ADJUSTABLE BEARING.

UNDER NORMAL CONDITIONS THE RAIL SHOULD SHOW SIGNS OF EVEN WEAR OVER THE WHOLE WIDTH OF THE BEARING - IF THE BEARING IS BEGINNING TO FAIL THE WEAR IS OVER A VERY NARROW PORTION. AT THE SAME TIME, THERE WILL BE SIGNS OF OVERHEATING ON THE BEARING. I.E.: CHANGE OF COLOR.

NOTE: WHEN THESE SIGNS ARE DETECTED THE CARRIAGE/RAIL SHOULD BE CHANGED AT THE EARLIEST OPPORTUNITY.

PART NUMBERS

CARRIAGE AND COIL ASSY-----29-22910  
 CARRIAGE AND RAIL UPPER-----29-23029  
 CARRIAGE AND RAIL LOWER-----29-23028


[ ]	<b>FIELD SERVICE TECHNICAL MANUAL</b>				<b>Option or Designator</b>
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/3

Title RM02/3 will not run Dec/Xll		Tech Tip Number RM02/3-TT- 20	
Author Frank C. Owens		FS Office Indianapolis Date 7-Jan-80	
Processor App cab: 1v		Revision 0	
All		Cross Reference	
My/Sup: <i>[Signature]</i> Date: <i>[Date]</i> Approval: <i>[Signature]</i> Date: <i>[Date]</i>			

When running Decxll with Rm02/3'S and you get the error 'Too many type que errors', then decxll aborts, your problem may not be hardware. Check to see if you have more than 32 total bad spots on all drives. This can be done by examining the user bad spot file on each pack, by using the RM02/3 formatter program (zrma). If the total number of bad spots, on the packs used to run Decxll, exceed 32 you have to change one or more of the packs with packs that have less bad spots to get that total less than 32. This does not mean the packs are bad. The problem is that the decxll module CXRMAD0 does not allow more than 32 total bad spots on all drives being run on system.

Title <b>Write Check ErrorW/O Data Check On Vav</b>		Tech Tip Number <b>RM02/3-TT-31</b>	
Author <b>Tom Crow</b>	FS Office <b>Mar P S</b>	Date <b>Jan/80</b>	Revision <b>0</b>
Processor Applicability	Mgr /Sup <b>L. Terma</b>	Date <b>Jan 6 80</b>	Cross Reference
All	Approval <b>Greg Ekholm</b>	Date <b>Feb/80</b>	<b>Rp05/6-TT-36</b>

This Tech Tip is for Cross Reference only.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/3
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title RM03 Seek Incomplete and Misposition Problems				Tech Tip RM02/3-TT-22 Number	
Author John R. Strauss		FS Office Columbus, Ohio		Date 17 JAN 80	Revision 0
Processor Applicability		Mgr /Sup Carl Swigart		Date 17 JAN 80	Cross Reference
All	11	VAX	20/20	Approval <i>[Signature]</i>	

On a recent problem which involved a RM03 with seek incomplete and misposition errors I found the two screws which hold the flex lead assembly to the rail bracket assembly had been loose. While the drive was seeking and shaking it would break the ground path and thus cause an error.

To resolve this problem make certain that there are lock washers under each one of the screws and that they are firmly secured to the rail bracket assembly.

Also, it is a good idea to check the flex leads going to the carriage coil assembly and make certain that they are not being twisted in any way when the drive is doing a seek. This may cause the flex leads to crack.

DEC CONFIDENTIAL

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip see Administration Tech Tip Number 2.

Page 15	Page Revision 0	Publication Date MAR 7/80
---------	-----------------	---------------------------

PRINTED IN U.S.A.

Title <b>RM03 SEEK INCOMPLETE AND MISPOSITION PROBLEMS</b>		Tech Tip Number <b>RM02/3-TT-22</b>	
Author <b>JOHN STRAUSS</b>	FS Office <b>OHIO</b>	Date <b>17/1/80</b>	Revision <b>0</b>
Processor Applicability	Mgr /Sup <b>CARL SWIGART</b>	Date	Cross Reference
All	Approval <b>GREG EKHOLM</b>	Date <b>2/20/80</b>	






Fig 16 Carriage and Coil Assembly


	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	ROTATING MEMORIES

Title <b>VELOCITY GAIN ADJUSTMENT</b>				Tech Tip Number RM02/03-TT-23	
Author <b>GREG EKHOLM</b>		FS Office <b>COLO SPGS</b>	Date <b>4/29/80</b>	Revision <b>A</b>	
Processor Applicability		Mgr /Sup.	Date	Cross Reference	
All	11	VAX	20		
		Approval <i>Greg Ekholm</i>	Date <b>8/12/80</b>		

THE PICTURE SHOWN IN CHAPTER 4 OF THE RM02/03 DISK SUBSYSTEM SERVICE MANUAL (EK-RM023-SV-001) FOR THE VELOCITY GAIN ADJUSTMENT IS CORRECT. THE PROCEDURE IS CORRECT; HOWEVER, THE OSCILLOSCOPE DISPLAY COULD LOOK LIKE THE ONE BELOW IF YOU LOOKED AT TEST POINT B02-3A INSTEAD OF B09-3A.



A2B02-03A



A2B09-03A

A2B09-03A CROSS REF PAGE 193 IS "+ ON CYLINDER"

A2B02-03A CROSS REF PAGE 123 IS "+ (BUS) BI" 2<sup>9</sup>"

YOU COULD ADJUST THE VELOCITY GAIN USING THIS SECOND TEST POINT BECAUSE THE BUS BIT IS RELATED TO "ON CYLINDER". HOWEVER, IT IS RECOMMENDED THAT YOU USE THE CORRECT PIN B09-03A TO PERFORM THIS ADJUSTMENT.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 17	Page Revision A	Publication Date August 1980
---------	-----------------	------------------------------

PRINTED IN U.S.A.

<b>digital</b>	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/3
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title <b>RM03 Head Alignment Tool Problem</b>				Tech Tip RM02/3-11-24 Number	
Author <b>John R Strauss</b>		F.S. Office <b>Columbus, Ohio</b>		Date <b>5 DEC 79</b>	
Processor Applicability		Mgr./Sup. <b>Carl Swigart</b>		Date <b>5 DEC 79</b>	
All	11	Vax	20	Approval <i>Carl Swigart</i> Date	
				Revision <b>0</b>	
				Cross Reference	

During a head alignment on a RM03 disk drive it is sometimes very hard to insert and remove the head cranking tool into or out of the carriage alignment holes for each of the respective heads. I have seen many cases wherein the tool may not always be in far enough and results in a rounded out head which can no longer be used. This is due to the fact that the head's body is made of aluminum and the tool is made of hardened steel.

This causes a small amount of Aluminum to build up on the Head Tool. This can be removed by polishing the tool with very fine crocus cloth purchased at your local hardware store. If you do not have any crocus cloth a piece of Bonded paper can also be used to polish off the aluminum and dirt.

It is also advisable to stay at 6 pounds of torque on the head retaining screws when doing this procedure due to the differences in the metals mentioned above. When you get the head aligned then torque it down to the 12 pounds of final torque as mentioned in the procedure. Many people try to bump the heads when they are at final torque as you can do with other types of drives and thus ruin the heads.

<b>digital</b>	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/03

Title <b>FAULT LATCH CARD</b>				Tech Tip Number <b>RM02/03-TI-25</b>	
Author <b>GREG EKHOLM</b>		F.S Office <b>CX</b>	Date <b>2/1/80</b>	Revision <b>0</b>	
Processor Applicability		Mgr./Sup	Date	Cross Reference	
All	11	VA*	20	Approval: <i>Greg Ekholm</i> Date <b>4/20/80</b>	

IF AN INTERMITTENT DRIVE FAULT OCCURS, THE OPERATING SYSTEM ISSUES A "DRIVE CLEAR" COMMAND WHICH CLEARS THE FAULT "LEDS" ON THE 9762 DISK DRIVE A2A04 CARD. THIS RESULTS IN "VV" VOLUME VALID BEING RESET AND NO OTHER ERROR CODES PRESENT. THE DRIVE IS NOW UNACCESSIBLE AND NO FAULT "LED'S" LITE. THE OPERATOR MUST NOW ISSUE A "MOUNT" COMMAND BEFORE DRIVE OPERATIONS CAN BEGIN.

THE CORRECTIVE ACTION REQUIRED TO LATCH UP THESE "LEDS" INVOLVES REMOVING INITIALIZE (MASTER FAULT CLEAR) FROM THE A2A04 CARDS RESET SIDE OF THE LED F/F'S AND RE-ROUTING IT SO THAT INITIALIZATION ONLY CLEARS THE FAULT SUMMARY F/F ON THE A2A04 CARD.

BECAUSE THIS INVOLVES MODIFYING A VENDOR CARD YOU CAN NOT LEGALLY RETURN THIS CARD FOR REPAIR OR CREDIT.

REWORK INSTRUCTIONS

1. CUT ETCH SIDE 1 BETWEEN TWO FEED THRU HOLES LOCATED BETWEEN B2R2 AND 1CR1.
2. REMOVE AND SAVE CHIP C-3.
3. CUT ETCH SIDE ONE RUNNING BETWEEN C3 PIN 3 AND C3 PIN 13.
4. RE-INSTALL CHIP C3.
5. ADD WIRE FROM C3 PIN 3 AND LEFT HAND FEED THRU LOCATED BETWEEN B2R2 AND 1CR1.

DOCUMENTATION REWORK

1. MARK UP CR PAGE 42 AS PER ENCLOSED.
2. MARK UP CR PAGE 44 AS PER ENCLOSED.

- NOTE:
1. FRONT PANEL FAULT CLEAR (MANUAL FAULT CLEAR) MUST NOW BE USED TO CLEAR THE FAULT F/F DURING MAINT.
  2. SYSTEM "DRIVE CLEAR" NOW LEAVES FAULT LEDES ON AND ONLY CLEARS THE FAULT F/F.
  3. FAULT LEDES ARE CLEARED BY CLEAR SWITCH ON A2A04 CARD OR BY POWER UP MASTER CLEAR.
  4. CHIP C3 IS A LOGIC ELEMENT 141 AND IS THE SAME AS A 7410 CHIP. DEC'S PART NUMBER FOR THIS 7410 CHIP IS 19-05576-00.


**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.


Page <b>19</b>	Page Revision <b>0</b>	Publication Date <b>June 80</b>
----------------	------------------------	---------------------------------

PRINTED IN U.S.A.


Title <b>FAULT LATCH CARD</b>		Tech Tip Number <b>RM02/3-TT-25</b>	
Author <b>GREG EKHOLM</b>	F S Office <b>CX</b>	Date	Revision <b>0</b>
Processor Applicability <b>All</b>	Mgr /Sup	Date	Cross Reference
	Approval	Date	




Title <b>FAULT LATCH CARD</b>		Tech Tip Number <b>RM02/3-TT-25</b>	
Author <b>GREG EKHOLM</b>	F S. Office <b>CX</b>	Date	Revision <b>0</b>
Processor Applicability		Mgr /Sup	Date
Approval		Date	Cross Reference



Title <b>FAULT LATCH CARD</b>		Tech Tip Number <b>RM02/3-TT-25</b>	
Author <b>Greg Ekholm</b>	F S Office <b>CX</b>	Date	Revision <b>0</b>
Processor Applicability		Mgr /Sup.	Cross Reference
Approval		Date	



	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title POWER SUPPLIES-VIBRATION SENSITIVE/DCK's			Tech Tip Number RM02/03-TT-26		
Author Greg Ekholm		F.S. Office Colo.Springs Date 4-29-80		Revision A	
Processor Applicability		Mgr /Sup Peter Petaro Date 5/19/81		Cross Reference	
All	11 VAX	20	Approval <i>Greg Ekholm</i> Date 5-13-81		

Some RM02/03 drives appear to have vibration sensitive power supplies. Problem report CC00330 detailed occurrences of data checks, header not found, and write checks occurring because of this problem.

The Quick fix appears to be to install foam and possibly part of a memory shield under the power supply mother board. The RFI filter sits under the mother board and this is the area you install the foam.

Region and District Support personnel report good results by adding the foam. Some have observed the dibits deteriorating when they tapped the regulators and others have seen spikes on the + 5 volt supplies. Consult AIDS Problem Report CC00330 for full background.

UPDATE

A fix from CDC has been received which adds a ground wire from the dynamic brake to the drive motor mounting plate. Soon to be released DEC FCO's RM02-S-CX015 and RM03-S-CX023 will update all drives between series code 29 and 36 with the fix.


Other areas to check are the spindle ground (DEC # 29-23934) and the emergency retract relay (DEC #29-23377).

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 23	Page Revision A	Publication Date May 20, 1981
---------	-----------------	-------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/03

Title RM02/03/05/80 Module Compatibility			Tech Tip Number RM02/03-TT-27		
Author Greg Ekholm		F S Office Colo. Spgs.		Date 7/15/80	Revision g
Processor Applicability			Mgr /Sup		Date
All	11	VAX	20	Approval <i>Greg Ekholm</i>	Date 7/28/80
					Cross Reference RM05 RM80

WITH THE INTRODUCTION OF THE RM05 AND THE RM80, SEVERAL MBA MODULES HAVE CHANGED. THE TABLE BELOW LISTS THE REV LEVEL THE MODULES MUST BE AT TO BE COMPATIBLE, OR IF THEY ARE UNUSABLE ARE NOTED BY A "NO".

MODULE	RM02/03	RM80	RM05
M7684	CS = R	yes	yes
M7685 M7685-YA M8685	CS = C yes yes	no no yes	no CS = D CS = B
M7686 ** M7686-YA	CS = J yes	yes yes	no yes
M7687	CS = C	yes	yes
M5922	CS = E	yes	yes
M5923	CS = E	yes	yes
70-13398 Back Plane	WL = C WT = D	WL = D WT = E	WL = D WT = E


\*\* If DUAL PORT Switches are located in the slot on the front door M7686-YA must be used.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 24	Page Revision 0	Publication Date August 1980
---------	-----------------	------------------------------

PRINTED IN U.S.A

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title <b>ASGV VERSUS 6SGV SPEED DETECT</b>				Tech Tip Number <b>RM02/03-TT-28</b>	
Author <b>GREG EHKOLM</b>		F S Office <b>COLO SPGS</b>	Date <b>7/15/80</b>	Revision #	
Processor Applicability		Mgr /Sup	Date	Cross Reference	
All	11	VA X	20/20	Approval <i>[Signature]</i>	Date <b>7/28/80</b>

BECAUSE OF A PART NUMBER MIX UP, WE HAVE RECEIVED APPROX. 500 OF THE OLD 6SGV SPEED DETECT MODULES FOR SPARES. THE ASGV IS A DEC ONLY MODULE AND HAS AN ADDITIONAL CIRCUIT ON IT. THIS CKT PREVENTS THE PACK COVER FROM BEING OPENED FOR APPROX. 10-15 SECONDS AFTER A PACK SPIN DOWN. THIS ADDITIONAL TIME WAS ADDED FOR THE SITUATION OF A CUSTOMER STARTING THE DRIVE WITHOUT A PACK INSTALLED. AFTER THE DRIVE IS STARTED, THE SPEED DETECT CARD LOOKS FOR SPEED PULSES FROM THE SPEED XDUCER. WITHOUT A PACK INSTALLED NO PULSES WILL BE PRESENT AND THE DRIVE WILL FORCE A SPIN DOWN. THE PACK COVER INTERLOCK LOOKS FOR SPEED PULSES TO DETERMINE WHEN THE PACK HAS STOPPED AND WHEN TO UNLOCK THE PACK. WITH NO PACK INSTALLED THE COVER UNLOCKED IMMEDIATELY WITH THE 6SGV AND THE SPINDLE COULD STILL BE SPINNING DOWN (APPROX. 6 - 8 SECONDS).

BECAUSE THE SEQUENCE OF EVENTS REQUIRES AN OPERATOR TO IMMEDIATELY OPEN THE PACK COVER AND TRY AND MOUNT A PACK ON THE SPINNING SPINDLE, THE LIKELIHOOD OF THIS HAPPENING IS CONSIDERED SMALL.


PRODUCT SAFETY HAS REVIEWED THE SITUATION AND DETERMINED A MANDATORY RETROFIT IS NOT REQUIRED. THE 6SGV HAS BEEN REMOVED FROM THE LOGISTICS ARL AND THE PART OBSOLETED AND CROSS REFERENCED TO THE ASGV, YOU MAY CONTINUE TO USE THE 6SGV'S IN THE PRESENT DRIVES (ALL ORIGINAL RM02'S AND RM03'S HAVE ASGV MODULES IN THEM) UNTIL THEY FAIL. ALL SPARES AND FUTURE ORDERS SHOULD BE FOR THE ASGV MODULE.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 25	Page Revision 0	Publication Date August 1980
---------	-----------------	------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/03

Title RM02/03/05/80 MBA Backplane			Tech Tip Number RM02/03-TT-29		
Author Greg Ekholm		FS Office Colo. Spgs. Date 7/15/80		Revision #	
Processor Applicability		Mgr /Sup		Cross Reference	
AN	11	VAX	20/20	Approval <i>Greg Ekholm</i>	Date 7/28/80
				RM05 -2	
				RM80 -2	

THE FOLLOWING CHANGES HAVE BEEN MADE TO THE RM02/03 BACKPLANE TO MAKE IT RM02/03 AND RM05/RM80 COMPATIBLE.

FOR THE RM05:

ADD BP3600 RPM L - A16K2 to B15P2

FOR THE RM80 THE FOLLOWING HAVE BEEN ADDED:

ADD NEW TRK READ L - A16 H1 to A19 R1

RMOF L - B15H2 TO A16 H2

RMER2 H - B15F2 to A16F2

SSE - E15U2 to E16 L1

WITH ALL 5 WIRES ADDED, THE "WL" IS AT A REV "D" AND THE "WT" IS AT A REV "E". THIS MAKES THE 70-13398 BACKPLANE RM02/03/05/80 COMPATIBLE.


NOTE: REMEMBER THESE WIRE ROUTES ARE FOR KANATA AND SLOT 1 = KA WIRE WRAP SLOT 11, SLOT 9 = KA WIRE WRAP SLOT 19.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 26	Page Revision 0	Publication Date August 1980
---------	-----------------	------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title <b>RM#3 HEAD CRASHES</b>			Tech Tip Number <b>RM02/03-IT-30</b>	
Author <b>Robby Robertson</b>		FS Office <b>Charlotte</b> Dist Date <b>5/30/80</b>		Revision <b>g</b>
Processor Applicability		Mgr /Sup		Cross Reference
All	<b>11/18</b>	<b>VAR</b>	<b>2/20/20</b>	

PREVENTION OF HEAD CRASHES

- 1) Airflow is critical - the primary filter clogs very easily and must be cleaned every P.M.




See RM#2/#3 Subsystem Service Manual Page 3-15

- 2) Do Not clean the heads while they are in the drive. It is easy to change the way they fly, causing errors and possibly head crashes. Always remove head cleaning solution residue.
- 3) Check the bearings for rough spots. See Speed Bulletins #108 and #114.
- 4) Regularly clean the shroud area.

PROCEDURE AFTER A HEAD CRASH

- 1) Identify All bad packs and tag them. It is not uncommon for a customer to "HIDE" a valuable pack, tactfully cover this angle.
- 2) Remove all heads and inspect them. RM#3 heads are oxide colored making it difficult to evaluate them. Pay special attention to the boomerang shaped hole on the head.



The boomerang shaped hole is famous for collecting debris and lint from "LINT FREE" cloths. Failure to examine this area has claimed a number of alignment packs and caused repeat head crashes. Again it is easy to change the way the head flies when attempting to clean debris out of the hole.

DEC CONFIDENTIAL


This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip see Administration Tech Tip Number 2.

Page <b>27</b>	Page Revision <b>0</b>	Publication Date <b>July 1980</b>
----------------	------------------------	-----------------------------------

PRINTED IN U.S.A.

EN 1186C(2) R277 (70V)

RM08-IT 1

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bt <input type="checkbox"/>	16 Bt <input type="checkbox"/>	18 Bt <input type="checkbox"/>	36 Bt <input type="checkbox"/>	RM02/03

Title <b>RM01 Head Crashes</b>			Tech Tip Number <b>RM02/03-TT-30</b>		
Author <b>Robby Robertson</b>		FS Office <b>Charlotte</b> Dist <b>Date 5/30/80</b>		Revision #	
Processor Applicability		Mgr /Sup.		Cross Reference	
AN	U	VAX	2/20	Approval <i>Joy Ethel</i>	Date <b>7/11/80</b>

**CAUTION!**

This next step should only be done by someone trained on the drive.

- 3) The magnet will collect debris from a bad head crash and must be removed and examined. This can be done without changing or affecting the adjustable bearing on the carriage and coil assembly. Remember when removing the magnet to hold the EMA coil so it does not follow the magnet. By preventing the EMA coil from coming off the rail you will not have to recheck the bearing adjustment.
  
- 4)
  - A. Clean the shroud area.
  - B. Check the primary filter.
  - C. Change the absolute filter.

After the respective heads have been changed and the drive is ready for head alignment, power the drive down and disconnect the E1 plug on the servo power amp (yellow wire on the servo power amp). Use the same procedure as when manually loading the heads. Power the drive up. Place a scratch pack in the drive, cycle it up. The heads will not load. Let the drive purge for a period of time (20 minutes). Then manually load the heads (7 inches per second or faster). Run the heads across the pack and listen closely for any head to disk interference. If everything is ok, unload the heads, cycle the drive down, remove power and reconnect the servo power amp plug. You may now follow the normal head alignment procedure. Remember to let the alignment pack reach ambient temperature.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>28</b>	Page Revision <b>0</b>	Publication Date <b>July 1980</b>
----------------	------------------------	-----------------------------------

PRINTED IN U.S.A.

<b>digital</b>	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	RM02-3

Title <b>Dual Port Logic Test Part 2</b>			Tech Tip Number <b>RM02/03-TT-31</b>		
Author <b>John Kopitz</b>		F S Office Corp., Field Sup. Date <b>5 AUG 80</b>		Revision	
Processor Applicability		Mgr / Sup. <i>[Signature]</i> Date <b>8-5-80</b>		Cross Reference	
All		Approval <i>[Signature]</i> Date <b>8/12/80</b>			

In running the dual port logic test part 2, the placement of the special test cable out of Port A into Port B is very important. If not cabled correctly, near the end of the test, it will hang waiting for MOL on the wrong drive.


A reminder. Massbus from RH in on Port A, special test, cable (70-10507-02) out of Port A into Port B.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page <b>29</b>	Page Revision <b>0</b>	Publication Date <b>August 1980</b>
----------------	------------------------	-------------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/03

Title RM02/03/05/80 DUAL PORT				Tech Tip Number RM02/03-TT-32	
Author Greg Ekholm		F.S. Office Colorado Spgs. Date 11/16/80		Revision	
Processor Applicability		Mgr./Sup. BOB DAVISON Date 12/12/80		Cross Reference	
All	11	10	20	VAX	Approval: <i>Greg Ekholm</i> Date 12/1/80
				RM00	
				RM05	

ECOs RM03-CX-022 and RM02-CX-012 relocated the dual port switches to the front door. RM05s have always had the slots for the dual port switches on the front door.

The original RM02/RM03 ECOs were marked FCO required however, this upgrade will be a sales item, listed in the MLP (Maynard List Price) book, and no FCO will be issued. The MLP will carry the upgrade kit as RM02-C/RM03-C for use in new drives with the slot cut out of the front door. The RM03-CA should be ordered for old single ported drives where the customer wants access to the switches as this includes a dark grey front door with a slot for the dual port switch in the kit. A new kit with a blue door instead of a grey door is presently being worked on. Upgrade kits for the RM05 and RM00 are listed under RM05-C and RM00-C in the MLP (or Standard Price) Book.

Listed below is the ship list for the present RM03-C and RM03-CA.

Item Part Number	Description	Quantity	
		C	CA
1 M5923-00	MASS BUS TRANSCEIVER, Port B	2	2
2 7419781-00	BC06S Rework	1	1
3 7418607-00	Clamp Cable	6	6
4 9005041-01	Screw, Pan, Phil 8-32X 3/4 SS	2	2
5 9006418-01	Screw, Tapping, Type TT, Pan, Phil,	4	4
6	Disk Drive, RM03	REF	REF
7 7016549-00	Dual Port Switch ASSY	1	1
8 7012830-02	Front Door ASSY (Dark Grey)	-	1
9 1214434-02	Header .100 2POS RT Angle - -(J11,J12)	-	2
10 1209350-03	Mate-N-LOK 3POS HSG,SKT - -(J10)	-	1
11 1209456-01	Mate-N-LOK SKT 20-18ASW LOOSE PC -(J10)	-	3

The original ECOs also upgraded the MBA Backplane to a WT Rev "D". This removed the Dual Port Switch and LEDs from the backplane and added plugs in their place. Some of the original backplanes WT Rev "D" had the 3 connector plug inserted wrong. This will cause the led to light in the locked on port switch but the drive will actually be locked to the opposite port. (i.e., locked on "A" switch pushed in "B" out, locked on "A" LED lites but drive actually locked on "B".)

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 30	Page Revision 0	Publication Date December 1980
---------	-----------------	--------------------------------

PRINTED IN U.S.A.


EN 1189C 12 R277 (79V)

RM05-TT-42

<b>digital</b>	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/03
	12 Bit <input type="checkbox"/>	16 Bit <input type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title RM02/3/5/80 DUAL PORT		Tech Tip Number RM02/3-TT- 32	
Author GREG EKHOLM	F.S. Office COLORADO SPRGS. Date 12/1/80	Revision	
Processor Applicability	Mgr /Sup. BOB DAVISON Date 12/12/80	Cross Reference	
All	Approval <i>Greg Ekholm</i> Date 12/1/80	M80 RM05	

Ensure that the center plug has the keyed side towards the edge of the backplane, away from the card nest as shown below.



If the keyed part of the switch plug is facing the wrong way (towards the card nest) unsolder the plug and reorientate it correctly.

The new switch assembly is used as follows:

Port select switch

"A"	"B"		
OUT	OUT	-	Programmable
IN	OUT	-	Locked on "A"
OUT	IN	-	Locked on "B"
IN	IN	-	Programmable

When the dual port select switches are located on the front door the Control Interface (M7686) Board must be a M7686-YA. The "YA" version has R57 and R58 as 15K pull up resistors (M7686 IF 5 in print set) on "Lock Port A or B-L". Other than that the two boards are identical.

DEC CONFIDENTIAL

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 31	Page Revision 0	Publication Date December 1980
---------	-----------------	--------------------------------

PRINTED IN U.S.A.

<b>digital</b>	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/03

Title 240 to 220 v 50 Hz Power Conversion				Tech Tip Number RM02/03 - TT-33	
Author Greg Ekholm		F.S. Office Colo. Springs		Date 12/9/80	Revision
Processor Applicability			Mgr /Sup.	Date	Cross Reference
All	11	10	20	VAX	Approval: <i>Greg Ekholm</i> Date 12/9/80

Because of the European voltage variation and the RM02/03 only being sold in 240 v 50 Hz versions, the following voltage conversion procedure may be used if you need the 220 v model.

RM02 - AD/BD	240 v 50 Hz	Range
RM03 - AD/BD	-27 v	213 - 257
	+16 v	
Not offered	220 v 50 Hz	Range
	-25 v	195 - 235
	+15 v	

Reference RM02/or/RM03 Print Set

ER - 0RM02 - MP Cross reference page 302  
 ER - 0RM03 - MP 302

240 v Point 1 to Tap 1 on Transformer  
 Point 2 to Tap 6 on "

220 v Point 1 to Tap 1 on Transformer  
 Point 2 to Tap 5 on "

To convert 240 v to 220 v move wire from transformer Tap 6 to transformer Tap 5.


RM02/03 Disk Engineering in Colorado Springs has endorsed and verified this Tech Tip.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 32	Page Revision 0	Publication Date December 1980
---------	-----------------	--------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	RM02/03

Title <b>RM02/03 Head Identification</b>			Tech Tip <i>Rev 2/01 - TT-34</i> Number <b>RM02/03-TT-34</b>		
Author <b>Alan King</b>		F.S. Office <b>Indianapolis</b>		Date <b>12/17/80</b>	Revision <b>0</b>
Processor Applicability			Mgr/Sup. <b>Steve Graves</b>		Date <b>12/17/80</b>
All	XX				
			Approval <i>[Signature]</i>		Date <i>[Date]</i>
			Cross Reference		

A problem exists in inadvertently substituting RM02 and RM03 heads between the two drives. To tell an RM02 head, look at the pigtail. There should be a red or maroon strip on it. For an RM03, the pigtail will be colored with a blue strip. Always double check part numbers.

RM03	R/W Lower	CDC# 75010102	RM02	CDC# 75010302
	R/W Upper	75010103		75010303
	R/W Servo	75010105		75010305


**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>33</b>	Page Revision <b>0</b>	Publication Date <b>February 1981</b>
----------------	------------------------	---------------------------------------

*33*

*PRINTED IN U.S.A. FEB 27 1981*

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	38 Bit <input checked="" type="checkbox"/>	

Title <b>Head Refurbishment Guideline</b>			Tech Tip Number <b>RM02/03-TL-35</b>		
Author <b>Greg Ekholm</b>		F.S. Office <b>Colorado Springs</b> Date <b>3-16-81</b>		Revision <b>0</b>	
Processor Applicability		Mgr./Sup.		Cross Reference	
All	11s	VAXs	20s	Approval <i>Greg Ekholm</i>	Date <b>3/17/81</b>
				Cross Reference <b>RP05/06-TT-53</b>	

This tech tip for cross reference only.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>34</b>	Page Revision <b>0</b>	Publication Date <b>March 23, 1981</b>
----------------	------------------------	--

PRINTED IN U.S.A.


	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title <b>POOR MASSBUS CABLE ZIF CONNECTORS</b>			Tech Tip Number <b>RM02/03-TT-36</b>	
Author <b>Greg Ekholm</b>		F S Office <b>Colorado Springs</b> Date <b>3/10/81</b>		Revision <b>0</b>
Processor Applicability		Mgr /Sup.		Cross Reference
All	11s	VAX	20s	10s
Approval <i>Greg Ekholm</i>		Date <b>3/16/81</b>		RP05/06-TT-52 RM80-TT-8

RM80-TT-8


Some incorrect "Amp" connectors may have made it to the field on the ends of MASSBUS cables. If you have the incorrect ZIF connectors the MASSBUS cable end may fall off the connector bulkhead during normal operation. The cables were built between October 1980 and February 1981. Below are the three (3) styles of connectors as viewed from the pin end of the plug. If you are having this problem please check your ZIF connectors.

GOOD




No  
Slots

BAD



Slots  
NO RIBS

GOOD



Slots  
&  
RIBS

DEC CONFIDENTIAL


This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>35</b>	Page Revision <b>0</b>	Publication Date <b>March 23, 1981</b>
----------------	------------------------	--

PRINTED IN U.S.A.

EN 1189C 12 R277 79V1

RM02-TT 47

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title <b>ARI Module Guidelines</b>			Tech Tip Number <b>RM02/03-TT 37</b>		
Author <b>Greg Ekholm</b>		FS Office <b>Colorado Springs</b>		Date <b>3/16/81</b>	
Revision <b>0</b>		Processor Applicability		Cross Reference	
AN	11s	VAXe	20e	Approval <i>Greg Ekholm</i>	Date <b>3/19/81</b>
				Cross Reference <b>RP05/06-TT-54</b>	


This tech tip for cross reference only.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip see Administration Tech Tip Number 2.

Page <b>36</b>	Page Revision <b>0</b>	Publication Date <b>March 23, 1981</b>
----------------	------------------------	--

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title <b>NRZ TO MFM PART NUMBER CONFUSION</b>				Tech Tip Number <b>RM02/03-TT-38</b>	
Author <b>Alan King</b>		F S Office <b>IN</b>	Date <b>3/30/81</b>	Revision <b>0</b>	
Processor Applicability		Mgr /Sup	Date	Cross Reference	
All	11s	VAX	20s	Approval <i>[Signature]</i>	Date <b>4/2/81</b>

A discrepancy exists between the CDC vendor manuals and the RM02/03 Disk Drives. The RM02 vendor manual recommended spares list calls for the same NRZ to MFM converter as the RM03. This is incorrect and is in the process of being changed.

For the RM03 order DEC #29-22891 vendor #54-278505 (ELXV)

For the RM02 order DEC #29-23115 vendor # 54-278509. (GLXV)


The GLXV module schematic cross reference, page 172, also is in error. "+ High Freq clock (12.88 MHz)" comes in on Pin #9A and only goes to chip B3A Pins 1, 2 and 13. This manual is also being corrected.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>37</b>	Page Revision <b>0</b>	Publication Date <b>April 7, 1981</b>
----------------	------------------------	---------------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM02/03

Title <b>RM02/03 NOISE SUSCEPTIBILITY</b>				Tech Tip Number <b>RM02/03-TT-39</b>	
Author <b>ROBERTSON/EARWOOD</b>		F S Office <b>CHARLOTTE DISTRICT SUPPORT</b>		Revision	
Processor Applicability		Mgr /Sup <b>Vince Gaydos</b> Date		Cross Reference	
AN		Approval		Date	


Intermittent data check errors may be caused by gas operated forklift trucks. At two sites in the Charlotte district this problem was observed. In both cases getting the customer to install resistor spark plugs and a condenser between the ignition coil and battery ground eliminated these errors. The best way to show the problem is to run the performance exerciser (ZRMB) and do sequential reads. This may be done by doing a control 'C' and under commands, type a R space drive number. Inhibit printouts and bell on error. The diagnostic stops to print out errors, therefore if you do not inhibit printouts you will not see the true frequency of errors. Have the forklift trucks evacuate the area and then have them drive one by one as close to the system as possible. In both cases the forklift trucks accounted for about 80% of the data checks. Phase imbalances, grounding, carriage bearings and spindle grounds accounted for the other 20%. Using a 7L/2 spectrum analyzer with the LA70 antenna, we observed noise spikes from 100 to 400 MHz at -65 to -38 DBM. Adding the suppressor kits reduced the number of noise spikes by about one half but did not affect the amplitude appreciably.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip see Administration Tech Tip Number 2.

Page <b>38</b>	Page Revision <b>0</b>	Publication Date <b>July 14, 1981</b>
----------------	------------------------	---------------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02 / RM03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title <b>NEW PART # FOR CDC DRIVE ECO TO IMPROVE HINGES</b>			Tech Tip Number <b>RM02/02-TT-40</b>		
Author <b>MARK H HALGAS</b>		F S Office <b>NORFOLK (NF)</b>		Date <b>5-21-81</b>	
Processor Applicability		Mgr Sup <i>[Signature]</i>		Date <i>5/21/81</i>	
All		Approval <i>[Signature]</i>		Date	
				Revision <b>0</b>	
				Cross Reference	

CDC has improved the hinges on the pack access cover. The parts for this ECO will not work on the old style drives S/C-32 and below. So if you need to replace any parts, order all 5 items to improve the cover.

If you have the new type drive S/C-33 and above just order the parts you need.

<u>Item</u>	<u>Description</u>	<u>CDC#</u>	<u>DEC</u>	<u>Quantity Needed</u>
1	Retainer Bar	73063600	29-23633	1
2	Bushing	76429600	29-23634	2
3	Washer	75174202	29-23635	2
4	Right Hand Hinge	75070002	29-23636	1
5	Left Hand Hinge	75070003	29-23637	1

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip see Administration Tech Tip Number 2.

Page <b>39</b>	Page Revision <b>0</b>	Publication Date <b>July 14, 1981</b>
----------------	------------------------	---------------------------------------

PRINTED IN U.S.A.

<b>FIELD SERVICE TECHNICAL MANUAL</b>					Unit or Designator				
<b>UK REGION</b>									
Applicable Countries		K	X	E	N	S	D	F	RM02/03
12 bit	16 bit X	8 bit	36 bit	PL					

<b>DECK11 MODULE RMDA0</b>			Tech Tab Number RM02 03-TT-41
Processor Application	Originator	GARY ROBERTS	727
ALL	Author	GARY ROBERTS	
	Reg Approval	<i>[Signature]</i>	
	Issue Date	22nd July 81	
	Rev		

Beware of DECK11 module RMDA0. There is a mistake in the code for deciding the load device, if it is an RM02/03: no problem if it is an RP04/05/06. The result is that, the drive will not be dropped, even if location 40 has not been cleared.

You will, either overwrite your diagnostic pack, or, if you are lucky, get multiple write lock errors, depending on the state of the write lock switch, which can be confusing as you are not expecting to be testing that particular drive.

The answer at present, is to deselect the load device if you do not want it tested by a MOD RMDA0 14 and clearing the bit for the appropriate drive.

RM02 TT. 52

<b>digital</b>	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/3
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	32 Bit <input checked="" type="checkbox"/>	

Title <b>INTERMITTANT POSITIONING ERRORS</b>			Tech Tip Number <b>RM 02/03-TT-42</b>		
Author <b>FRED SAAS</b>		F S Office <b>Columbus, OH</b>		Date <b>7/23/81</b>	
Processor Applicability		Mgr /Sup <b>Norm Stanski</b>		Date <b>7/23/81</b>	
All		Approval <i>F. Saas</i>		Date: <b>14-81</b>	
11's		VAX's		20's	
				Cross Reference	

I have noticed on a couple of RM03 calls that I was able to induce positioning errors by flexing/vibrating the A3A04 Power Amplifier while the Drive was running performance exerciser. The cause of the problem was discovered to be due to the sockets that the Power Transistors are mounted in. In both cases I resolved the problem by removing the Transistors, removing the socket "pins" and soldering the Power Transistor Leads directly to the Circuit Board.


This problem may show up as a vib sensitive problem or as a heat related problem, but in either case, may be responsible for many intermittent positioning related errors.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip see Administration Tech Tip Number 2.

Page <b>41</b>	Page Revision <b>0</b>	Publication Date <b>8/17/81</b>
----------------	------------------------	---------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM02/03
	12 Bit <input type="checkbox"/>	16 Bit <input type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title <b>READ/WRITE - SERVO INTERMITTENTS</b>			Tech Tip Number <b>RM 02/3-TT-43</b>		
Author <b>Randy Hitch</b>		F.S. Office <b>Miami, Fla.</b>		Date <b>7/8/81</b>	
Revision <b>0</b>		Cross Reference			
Processor Applicability		Mgr./Sup.		Date	
All 11's VAX		Approval: <i>F. P. T. 12</i>		Date <i>8-14-81</i>	

There is a CDC recognized problem with the + 12V ZENER diodes, VR1 and VR2, on the + 20V regulator board (-5KV), that may cause intermittent Rd/Wrt or Servo problems. These ZENERS provide + 12 volts for two 6.2 regulators for the Servo preamp. The preamp is used for amplification of the dibits, which provide ALL timing for the drive. If the 6.2 volt regulators are marginal, a difference between plus and minus 12 volts of as little as .5 volts may cause these intermittent failures. If these failures occur, and all attempts to resolve the problem prove unsuccessful, it is recommended that the ZENERS be checked, and if the difference between plus and minus 12 volts exceeds .5 volts, change either the regulator board or replace the diodes with those of the same type, which may be purchased locally.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>42</b>	Page Revision <b>0</b>	Publication Date <b>8/17/81</b>
----------------	------------------------	---------------------------------

PRINTED IN U.S.A.

<b>digital</b>	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title RH11 Setup for RM02/3 on 11/44			Tech Tip Number RM03-TT-44	
Author Roger Head		F.S Office Perth	Date 5/29/81	Revision A
Processor Applicability		PSG <i>Fran Ligneron</i>	Date <i>2/1/82</i>	Cross Reference
All X	11's	CSSE <i>Lydell Buckman</i>	Date <i>2/9/82</i>	RH11-TT-8 PDP11/44-TT-11

The RM02/3 DISK SUBSYSTEM SERVICE MANUAL (EP-RM02/3-SV-002) has an error in paragraph 2.4.3.1. It states that RM02 subsystems have 22 registers, and that the jumpers in E3 should be set up to select 20. In fact the number of registers is 20 and the jumpering in E3 should be for 20, but is shown for 22.

Table 2-3 should read:

SLOT	JUMPER	JUMPER IN/ JUMPER OUT
E3	1-16	OUT
	2-15	OUT
	3-14	IN
	4-13	IN
	5-12 (2)	IN
	6-11 (4)	OUT
	7-10 (8)	IN
	8-9 (16)	OUT

Note that the selection scheme is somewhat confusing because the two significant jumpers that are removed (6-11 and 8-9) have binary weightings that imply a value of 20 and yet the RH11 signal BCTA LEGALREGH will only be true for input values to the comparator E12 of 18 (because the output A>B is used). The trick is that address bit A01 is not looked at by the comparator and can therefore contribute an extra count of 2. The net result of this is that the binary weighting attached to the jumpers in E3 should be used to select the exact number of registers that you wish the subsystem to respond to.

I believe the RM02 User Manual also gives the wrong jumpering for E3.

I imagine that this error will not be apparent, nor will it cause any problems when generating a system such as RSTS or RSX on an 'ordinary' Unibus PDP11. However when generating RSX11M-PLUS on an 11/44, part of the dialogue involves telling it that you have a 22 bit addressing machine. The software goes out and checks for the existence of the RMBAE register. This is the 21st register in the subsystem, and if it responds the software assumes that it is running on an 11/70, hence, doesn't worry about setting up the Unibus Map, and your system dies the first time it tries to use the disk.


Craig Prosser (Perth Software Support) is writing an article for the Small Buffer concerning this.

DEC CONFIDENTIAL

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 43	Page Revision A	Publication Date FEBRUARY 1982
---------	-----------------	--------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM03
	12 Bit <input checked="" type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title RM02/03 EMERGENCY RETRACT RELAY			Tech Tip Number RM03-TT-45	
Author GARY ROBERTS		F.S. Office NER (EUROPE) Date 6/10/81		Revision A
Processor Applicability		PSG <i>Franz Linschoten</i> Date 2/1/82		Cross Reference RM02-TT-45
All <input checked="" type="checkbox"/>		CSSE <i>Les H. Bucken</i> Date 2/9/82		

IF YOU ARE EXPERIENCING INTERMITTENT DATA CHECK PROBLEMS IT MAY BE WORTH CHANGING THE EMERGENCY RETRACT RELAY (A1K2) MOUNTED ON THE POWER REGULATOR BOARD.


IT IS CERTAINLY WORTH CHECKING THIS RELAY AND ITS BASE FOR SIGNS OF OVERHEATING, AS THERE HAS BEEN AT LEAST ONE INSTANCE OF A BASE MELTING, RESULTING IN THE HEADS NOT RETRACTING FROM THE PACK AREA.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 44	Page Revision A	Publication Date FEBRUARY 1982
---------	-----------------	--------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	32 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	SYSTEMS

Title <b>+12 V POWER SUPPLY TO LOW</b>				Tech Tip Number <b>RM03-TT-46</b>	
Author <b>MIKE HEFFERNAN</b>		F.S. Office <b>SED SUPPORT</b>		Date <b>2 FEB 82</b>	
Processor Applicability		CSSE <b>GREG EKHOLM</b>		Date <b>3/10/82</b>	
All <input checked="" type="checkbox"/>		PSG <i>Fran Linnhan</i>		Date <b>3/10/82</b>	
				Revision <b>A</b>	
				Cross Reference <b>RM02-TT-46</b>	

The +12/20 Volt Power Supply in the RM02/3 (A1A02) feeds the following boards from the +12 V side:

1. Head Select and Read Amplifier A3A02
2. Track Servo Preamp A3A05

On occasions the +12 V Power Supply, which is non-adjustable, drops its voltage below 11.6 Volts. If this occurs, changing the three associated boards A1A02, A3A02, and A3A05 may not get the voltage above 11.6 volts. If this occurs, a temporary fix can be to insert a 200 OHM, 10 Watt resistor in parallel with the 51 OHM 10 Watt output resistor for the +12 V output, R1.

This is to be done on an emergency basis after all else has been done.

**DEC CONFIDENTIAL**


This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>45</b>	Page Revision <b>A</b>	Publication Date <b>MARCH 1982</b>
----------------	------------------------	------------------------------------

PRINTED IN U.S.A.

EN-011888-12-R1270(78Y)

RM03-TT-57

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM03
	12 Bit <input type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	32 BIT <input checked="" type="checkbox"/>	36 Bit <input type="checkbox"/>	SYSTEMS

Title <b>RM02/03/05 ALTERNATE HEAD ALIGNMENT PROCEDURE</b>			Tech Tip Number <b>RM03-TT-47</b>		
Author <b>TOM TOBIASSEN</b>		F.S. Office <b>COLO.SPRINGS</b>	Date <b>17 FEB 82</b>	Revision <b>A</b>	
Processor Applicability All <sup>y</sup> X   11'		CSSE <b>LOYD BUCHANAN</b> <i>LB</i> Date <i>18-MAR-82</i>	Cross Reference <b>RM02-TT- 47</b> <b>RM05-TT- 9</b>		
		PSG <b>FRAN LINNEHAI</b> <i>FL</i> Date <b>22 FEB 82</b>			

Subject Alternate head alignment procedure for RM02/03/05's

This can be done with or without the HFSV (head align card).  
With the HFSV card the results will equal alignment done  
with a field test unit (FTU).

Enter into memory  
starting at

Location	200	000005	Reset
		012737	Select unit 0
		000000	
		176710	
	210	012737	Set VV
		000021	
		176700	
	216	000005	Reset
	220	012737	Set WC
		177400	
		176702	
	226	012737	Set BA
		002000	
		176704	
	234	013737	Select Head
		177570	
		176706	
	242	012737	Set DCA=365g
		000365	
		176734	
	250	012737	Do Read Data
		000071	
		176700	
	256	105737	TSTB for Ready
		176700	
	262	100375	BPL to TSTB
	264	000137	Jump to 216 and
		000216	do it again

DEC CONFIDENTIAL

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only.  
For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 1 of 2

Page <b>46</b>	Page Revision <b>A</b>	Publication Date <b>APRIL 1982</b>
----------------	------------------------	------------------------------------

PRINTED IN U.S.A.

EN-011000-12-R1270(70Y)

...-TT-58

Title <b>RM02/03/05 ALTERNATE HEAD ALIGNMENT PROCEDURE</b>		Tech Tip Number <b>RM03-TT-47</b>	
Author <b>TOM TOBIASSEN</b>	F.S. Office <b>COLO. SPRINGS</b>	Date <b>17 FEB 82</b>	Revision <b>A</b>
Processor Applicability		Cross Reference	
All	CSSE <b>LOYD BUCHANAN</b> <i>LB</i>	Date <b>18 MAR 82</b>	RM02-TT-47
x   11   s	PSG <b>FRAN LINNEH/N</b> <i>FL</i>	Date <b>22 FEB 82</b>	RM05-TT-9

**Instructions:**

1. With the drive powered off, place the HFSV card in the drive logic chassis at location A02 on RM02/03 and A16 on RM05's. Insert LAP 0 into drive. If you are not using the HFSV card goto step 5.
2. Install the head alignment cable between the drive logic chassis and the jack on the card in the read/write chassis as specified in the appropriate disk subsystem user's guide. Use your DVM in place of the FTU meter.
3. Power up the drive and install a CE Pack. Enter the toggle program at location 200, load address 200 and press start with SWR = 0. Heads will seek to cyl 24510 and you are ready for head alignment on head #0.
4. To select another head, raise the switches on the console to correspond to the desired head. On 1170 with RDC console, press ctrl P to get in console mode. 1W writes a 1 into the SWR, change the value 1 to ? for another head selection.

```

15  14 13 12  11 10 09  08 07 06  05 04 03 02 01 00
*   * * HD  HD HD HD  HD * *  * * * * * *
      16  08 04 02  01
          x   x

```

First line = Switch      Second line = value calculated by adding values in line 3.

Note: x - not used by RM02/03

5. For head alignment without the HFSV card place scope probes as shown below. J104 on the read amp card A3A03. Align the head for equal simitry of the dibit pattern shown in the user guides. This is an emergency procedure and should be done using the HFSV card as soon as possible.

Goto step 3.

J104



DEC CONFIDENTIAL

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.


Page 2 of 2

Page <b>47</b>	Page Revision <b>A</b>	Publication Date <b>APRIL 1982</b>
----------------	------------------------	------------------------------------

PRINTED IN U.S.A.

EN-011000-12-R1270(70V)

M03-TT-59

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	32 BIT <input checked="" type="checkbox"/>	36 Bit <input type="checkbox"/>	SYSTEMS


Title VELOCITY GAIN ADJUSTMENT WITHOUT FTU FOR RM02/03			Tech Tip Number RM03-TT-48		
Author TOM TOBIASSEN		F.S Office COLO.SPRINGS		Date 17 FEB 82	
Processor Applicability		CSSE LOYD BUCHANAN <i>LB</i>		Date 18 MAR 82	
AM X   11		PSG FRAN LINNFHAN <i>FL</i>		Date 22 FEB 82	
				Revision A	
				Cross Reference RM02-TT-48	

The following is a procedure for adjusting velocity gain on RM02/03 using a toggle-in program on PDP-11's.

**Toggle program**

200	000005	Reset	250	012737	Seek Command
202	012737	Sel Unit 0		000005	
	000000			176700	
	176710		256	105737	TSTB for Ready
210	012737	Set VV		176700	
	000021			100375	
	176700		264	000137	Jump to the
216	012737	Set DC = 1466g		000200	beginning
	001466				
	176734				
224	012737	Seek Command			
	000005				
	176700				
232	105737	TSTB for Ready			
	176700				
	100375				
240	000005	Reset			
242	012737	Set DC = 0			
	000000				
	176734				

1. Connect a scope to pin on the bottom of the logic rack A2 B09 03A.
2. Start the drive with unit select plug #0
3. Load address 200 and start.
4. Adjust pot E2R6 on the A2A07 card for 52 - 54 MSec. See figure.



DEC CONFIDENTIAL


This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech. Tip Number 2.

Page 48	Page Revision A	Publication Date APRIL 1982
---------	-----------------	-----------------------------

PRINTED IN U.S.A.

EN-011898-12-R1270(79Y)

RM03-TT 60

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	SYSTEMS

Title <b>EXCLUSIVE OR GATE ERROR</b>			Tech Tip Number <b>RM03-TT- 49</b>		
Author <b>LOYD BUCHANAN</b>		F.S. Office <b>COLORADO</b>		Date <b>23 FEB 81</b>	
Processor Applicability		CSSE <b>GREG EKHOLM</b>		Date <b>14 JUL 81</b>	
All <input checked="" type="checkbox"/>		PSG <b>FRAN LINNEHAN</b>		Date <b>18 JUL 81</b>	
				Revision <b>A</b>	
				Cross Reference <b>RM02-TT- 49</b> <b>RM05-TT- 10</b>	

The RM02, RM03, and RM05 prints are in error on drawing exclusive OR gates. Referring to cross references 164 and 165 in the RM02 and RM03 prints, C.D.C. has shown the 149H gates as exclusive NOR gates. The manufacturer's data sheet lists the 7486 and the 3021 gates as exclusive OR's. Erasing the inversion bubbles on the outputs does make the logic work properly.


This logic appears on cross references 124 and 125 of the RM05 prints.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>49</b>	Page Revision <b>A</b>	Publication Date <b>APRIL 1982</b>
----------------	------------------------	------------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM03
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	SYSTEMS

Title TESTING CARRIAGE BEARINGS			Tech Tip Number RM03-TT-50	
Author LOYD BUCHANAN		F S Office COLORADO	Date 23 FEB 81	Revision A
Processor Applicability		CSSE GREG EKHOLM	Date 14 JUL 81	Cross Reference RM02-TT-50
All <input checked="" type="checkbox"/>	<input type="checkbox"/>	PSG FRAN LINNEHAN	Date 18 JUL 81	

When testing the RM02/03 carriage bearings, it is better to manually load the heads with no pack in the drive.

When done with reasonable care, this practice does not damage the heads.

If the bearings are tested with a spinning pack, the carriage can "float" on the air-bearing; and give a false indication that the bearings are good.


These principles would also apply to the RM05.

DEC CONFIDENTIAL

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 50	Page Revision A	Publication Date APRIL 1982
---------	-----------------	-----------------------------

10. 1. 1 - 02

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM03
	32 Bit <input checked="" type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	SYSTEMS

Title BRAKE ASSEMBLY CAUSING INTERMITTENT FAILURE			Tech Tip Number RM03-TT-51	
Author FRAN LINNEHAN	F S Office MAYNARD	Date 15 FEB 82	Revision A	
Processor Applicability		CSSE SKIP DALTON <i>SD</i>	Date 10 MAR 82	Cross Reference RM02-TT-51
All <input checked="" type="checkbox"/>		PSG. ED MALCNE <i>EM</i>	Date 15 FEB 82	

There has been an increase of intermittent failures caused by the brake assembly in RM02/03 disk drives. This does not mean that if you have an intermittent failure that you automatically go and change the brake assembly, and/or related modules. You may have one of these intermittent failures, and the problem may be in another area of the drive. However, the brake assembly is one area that should be checked. These intermittent failures may show up as data checks, write checks, seek incomplete, format errors, header compares, header CRC, or drive timing errors. These errors may show up under the operating system only.

To check whether this is your problem, just remove the brake assembly from the spindle motor for testing. Do not leave the drive in this condition because this would cause a safety problem. The pack may still be spinning, and you will be able to open the cover.

If you find that the brake assembly is the problem, you should also be aware that the driver for the brake, transistor Q10 on the A10 card may have been weakened. To verify this, touch the motor or brake. Neither of these should feel hot to the touch. If so, replace card A10. You should also compare the temperature of the motors and brake assembly on a working drive so you can feel what a normal temperature should be before you replace the A10 card. When Q10 is weakened, it will put a constant drag on the brake/drive motor, thus creating excessive heat.


**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page 51	Page Revision A	Publication Date APRIL 1982
---------	-----------------	-----------------------------

PRINTED IN U.S.A.

RM03-TT-51

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM3
	32 BIT <input checked="" type="checkbox"/>	16 Bit <input type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	SYSTEMS

Title <b>DISK PACK CLEANING/INSPECTION</b>			Tech Tip Number <b>RM3-TT-52</b>	
Author <b>GREG EKHOLM</b>	FS Office <b>COLORADO</b>	Date <b>8 APR 82</b>	Revision <b>A</b>	
Processor Applicability	<b>CSSE DENNIS SHAW</b>	Date <b>5-4-82</b>	Cross Reference	
All <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<b>PSG ED MALONE</b>	Date <b>4 20 82</b>	<b>RM2-TT-52</b>	

**COMPANY CONFIDENTIAL Tech Tip on MEDIA MAINTENANCE of DISK PACKS**

The following statements are to be included in DEC Manuals, TECH TIPS, Policies and Procedures manuals and as a general corporation stand on the subject of "to clean or not to clean".

**PACK HANDLING AND STORAGE**

Careful handling of disk packs is a must. This includes assuring that the pack is never hit against another object or dropped. Every force on a disk assembly can potentially result in the repositioning of the many parts that make up the unit and possibly effect the construction tolerances and data reliability. This is true during the insertion and extraction of the media from the drive as well as general transportation and storage. Packs should be stored in a computer room environment with temperature held between 60 to 80 degrees F (15 TO 27 c) with relative humidity of from 40 to 55 percent.

Careful handling in a clean environment, utilizing the media's protective dust covers should be taught at all times. Always store the top and bottom of the protective dust cover together when not on the disk pack. Always keep the bottom cover afixed to the pack when the pack is in the top protective cover. Storing the media in a controlled clean environment is the first order of preventative maintenance. The likelihood of contamination is decreased if the media is operated and stored in a clean, controlled environment. If the media is stored in a different room than where the disk drive is located then care should be exercised to insure temperature stabilization before the disk pack is mounted in the disk drive. A disk pack's stacking tolerances can be directly effected by temperature. The rate of change of this temperature is also important to insure that condensation and media separation does not occur. Packs stored at a temperature different than the disk drive it is to be mounted in, should be allowed to stabilize to the room temperature of the disk drive for a period not less than one hour and preferably two hours.

**DEC CONFIDENTIAL**

**PAGE 1 OF 5**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>52</b>	Page Revision <b>A</b>	Publication Date <b>APRIL 1982</b>
----------------	------------------------	------------------------------------

**PRINTED IN U.S.A.**

EN 1180C 12 R277 (70Y)

*11/6 TT 64*

Title DISK PACK CLEANING/INSPECTION				Tech Tip Number RM03-TT-52	
Author GREG EKHOLM		FS Office COLORADO		Date 8 APR 82	
Processor Applicability		CSSE DENNIS SHAW		Revision A	
All <input checked="" type="checkbox"/>		PSG ED MALONE		Cross Reference	
		Date 5-4-82		RM02-TT-52	
		Date 4-28-82			

Never store a disk pack in direct sunlight or a dirty environment. Never allow a disk pack to come in the area of any strong magnetic field. Store the disk packs on a flat surface, never on the edge. If possible avoid stacking packs and if not, only stack two high, never more. Only stack packs of the same type, never inter-mix packs of different design.

#### IMPACT DETECTORS

A device known as a "SHOCKWATCH" is commercially available from several companies. The "SHOCKWATCH" impact detector gives you an immediate, visual alert when a disk has been shocked beyond manufacturer's specs; the normally clear indicator in the "SHOCKWATCH" changes to brilliant red, indicating probable damage. "SHOCKWATCH" can be easily attached to any standard disk cartridge or disk pack, and will not interfere with drive operation. If a "SHOCKWATCH" has been activated (the "SHOCKWATCH" is now red) that media should not be mounted on any disk drive. The media should be put to one side until it can be inspected using proper media inspection equipment.

#### PACK TRACKING

A reliable method of tracking media is strongly recommended to insure the performance of not only the media but, also the disk drive(s). Each pack should be labeled to allow tracking. The label should be placed either on the inside of the disk pack hub (do not place labels on the top of the disk pack), in the appropriate label area of the pack if so equipped, or on the top of the protective disk pack cover (never place labels on the side of the disk pack's protective cover). Place labels on the inside of the disk pack hub only if the pack is designed with a deep center hub ie: RP04, RP05, RP06 not RM02 or RM03 packs. Do not apply a large number of labels to the inside hub as this can cause the pack to be out of balance thus resulting in data reliability problems. Do not use grease pencils or other marking equipment that could flake off or introduce contamination to the pack or disk drive. Do not use lead pencil to mark packs. Write the label before it is applied to the disk pack or the disk cover. Never erase the

DEC CONFIDENTIAL

PAGE 2 OF 5

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 53	Page Revision A	Publication Date APRIL 1982
---------	-----------------	-----------------------------

PRINTED IN U.S.A.

RM 1180C 12 R277 (78V)

RM03 TT-65

Title <b>DISK PACK CLEANING/INSPECTIONS</b>				Tech Tip Number <b>RM03-TT-52</b>	
Author <b>GREG EKHOLM</b>		FS Office <b>COLORADO</b>		Date <b>8 APR 82</b>	Revision <b>A</b>
Processor Applicability		CSSE DENNIS SHAW		Date <b>5-4-82</b>	Cross Reference
All <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		PSG ED MALONE		Date <b>4-28-82</b>	<b>RM02-TT-52</b>

labels, if a correction is required, apply a new label instead. Each time the disk pack is mounted, the pack identification should be noted and the disk drive it is mounted in should be identified, by serial number rather than logical unit number. The performance of the disk drive and pack should be logged and kept as a site record. As an increase in data checks will frequently accompany contamination, a running log of errors attributable to the pack can indicate when the pack is in need of maintenance. The total log of errors can indicate when the disk drive is in need of maintenance. Both will contribute to the data reliability of the disk sub-system and prove to be cost effective in the long run.

#### PACK CLEANING

DIGITAL EQUIPMENT CORPORATION does not recommend the preventative cleaning of any disk packs. This policy supersedes any and all previous statements and is based on the latest technical data available. Packs should be logged and tracked and when the performance of a particular disk pack has degraded to an established control point (this should be set on a customer by customer basis taking into consideration the individual customers tolerance to data errors ) then that disk pack should be removed from service until it can be cleaned by an approved cleaning method administered by an approved cleaning source. If this preferred method can not be implemented, then preventative cleaning should be used. DIGITAL EQUIPMENT CORPORATION does recommend the use of automated cleaning equipment using specially formulated "wet" cleaning solutions. The use of this automated cleaning equipment is believed to be very repeatable and consistent from cleaning to cleaning providing the equipment is maintained per the manufactures recommendations. It should be noted that cleaning will not solve all problems. Scratched media and dirty read/write heads require technical consideration. Media that has been damaged by improper handling should be immediately removed from service and so marked. A method to determine the condition of the actual disk surfaces is known as disk inspection and will be covered next.

DEC CONFIDENTIAL

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

PAGE 3 OF 5

Page <b>54</b>	Page Revision <b>A</b>	Publication Date <b>APRIL 1982</b>
----------------	------------------------	------------------------------------

PRINTED IN U.S.A.

EN 1189C 12 R277 (79V)

RM03 TT-66

Title <b>DISK PACK CLEANING/INSPECTION</b>		Tech Tip Number <b>RM03-TT-52</b>	
Author <b>GREG EKHOLM</b>	FS Office <b>COLORADO</b>	Date <b>8 APR 82</b>	Revision <b>A</b>
Processor Applicability	<b>CSSE DENNIS SHAW</b>	Date <b>5-4-82</b>	Cross Reference
All X	<b>PSG ED MALONE</b>	Date <b>4-28-82</b>	<b>RM02-TT-52</b>

### DISK PACK INSPECTION

A method of visually inspecting the disk surfaces is known as disk or pack inspection. Several tests are usually performed during pack inspection. The inspectors are designed to accommodate a variety of pack types, including 1316, 2316, 3336 mod I or II. Other units are available to inspect disk cartridges both single and dual platter styles. The most common test is to insure that the disk platters that make up the disk pack are at the proper stacking tolerances. This is done with what is commonly known as a comb gauge. The disk pack is mounted on a special tester and the dust cover removed. The comb gauge is mounted on the tester and positioned to allow the disk platters to pass through the comb gauge. The pack is rotated and if any of the surfaces touch the comb gauge the pack is rejected. With properly designed comb gauges, run-out can also be checked, however the less than 10 RPMs spec is used rather than the dynamic runout tolerance.

Another test usually performed during pack inspection is a visual inspection of each of the disk surfaces. This is done by mounting a light source and a set of mirrors on the tester. The mirrors allow the operator to visually scan each disk surface for surface defects. The light source provides a high intensity light to illuminate the disk surfaces. The disk pack and drive is designed in such a manner to allow a disk read/write head to touch down momentarily on the disk surface during a head load without causing a catastrophic head crash. The area of the pack known as the head load zone is reserved for this possible miniature head crash or head stabilization period. This area does not contain any data and therefore is not able to be checked except by the pack inspector. Small minor surface defects are allowed in this area. The inspector will look for defects in the surface of each platter and inspect the head load zone for defects larger than normal. Scratches, dings, dirt, etc. will be inspected for and depending upon the location of the defects a judgment can be made of the physical condition of the disk pack.

PAGE 4 OF 5

DEC CONFIDENTIAL

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page <b>55</b>	Page Revision <b>A</b>	Publication Date <b>APRIL 1982</b>
----------------	------------------------	------------------------------------

PRINTED IN U.S.A.

EN 1180C 12 R277 (78V)

RM03-TT-67

Title <b>DISK PACK CLEANING/INSPECTION</b>		Tech Tip Number <b>RM03-TT-52</b>	
Author <b>GREG EKHOLM</b>	FS Office <b>COLORADO</b>	Date <b>8 APR 82</b>	Revision <b>A</b>
Processor Applicability		Cross Reference	
All <input checked="" type="checkbox"/>	<b>CSSE DENNIS SHAW</b>	Date <b>5-4-82</b>	<b>RM02-TT-52</b>
	<b>PSG ED MALONE</b>	Date <b>4-21-82</b>	

A further test sometimes performed on the disk pack is a test for run-out. This is accomplished by mounting a dial gauge on the tester and positioning the ball of the gauge on the outer rim of the disk platter. When the disk is rotated the gauge will show any variation in the roundness of the disk platter.

DIGITAL EQUIPMENT CORPORATION does endorse the use of the disk pack inspectors by qualified personnel. Because most of the defects are inspected for by visual methods the judgement of the inspector is of prime importance and therefore only qualified, experienced personnel should perform this inspection. Also, because the protective cover is removed from the disk pack during this inspection, care must be used to prevent contamination from reaching the surfaces of the disk pack. A clean environment should be used for the disk packs when they are being inspected.

DEC CONFIDENTIAL

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.


PAGE 5 OF 5

Page <b>56</b>	Page Revision <b>A</b>	Publication Date <b>APRIL 1982</b>
-------------------	---------------------------	---------------------------------------

PRINTED IN U.S.A.

EN-1188C 12 R277 (70V)

RM03-TT-68


	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM03
	<input checked="" type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input checked="" type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category SYSTEMS
Title <b>PACK SEAL ADJUSTMENT / HOLD DOWN BOLTS</b>					Tech Tip No. RM03-TT-53	
Processor Applicability ALL			Cross Reference N/A		Tech Tip Rev A	Page 1 of 1
Author Ron Hruby				Mgr / Supv. Approval N/A		
Location Parker Street			Mail Stop PK3-2/K11		Date 5-12-82	
CSSE Approval Dennis Shaw				Date 5-21-82		
PSG Approval				Date		

It has been found that a lot of head crashes can be attributed to air seal leaks. The following procedure should rectify this problem.

This can be checked by noting the drag on a sheet of paper as it is pulled out from between the closed pack access cover, and the shroud assembly. The amount of drag should be even around the seal. Adjust if necessary, by moving the front catch on the shroud up or down until the pack access cover latches tightly enough to provide an air tight seal. This adjusts the sides and front of the pack access cover..

If you have a rear seal leak do the following: Loosen hinge screws, and while applying slight pressure on closed pack access cover tighten screws. Also, shroud cover hold down bolts must be in and tightened down, while in customer operation.

NOTE: Because of the use of paper to check seal, you must purge pack for at least 15 minutes.



FOR INTERNAL USE ONLY: This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 57	Page Revision 8	Publication Date MAY 1982
-------------------	--------------------	------------------------------

FD-302 (Rev. 7-16-77)

RM03-TT-69

<b>FIELD SERVICE TECH TIP</b>					Option Designator RM03
<input type="checkbox"/> 12 BH	<input type="checkbox"/> 16 BH	<input type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category SYSTEMS
Title RM02/RM03 HEADER COMPARE ERROR					Tech Tip No. RM03-TT-54
Processor Applicability 11   VAX 10   20			Cross Reference RM02-TT-53		Tech Tip Rev A
Author ANDREW WYNN			Mgr./Supv. Approval ORVILLE BERESKA		
Location VANCOUVER, CANADA			Mail Stop VAO		Date 3 NOV 82
CSSE Approval DENNIS SHAW <i>[Signature]</i>			Date 31 MAR 83		
PSG Approval DAVE GURSKY <i>[Signature]</i>			Date 15 APR 83		

A FAULTY DOOR CLOSE SWITCH WAS FOUND TO HAVE CAUSED INTERMITTENT HEADER COMPARE ERROR UNDER RSTS. THE PROBLEM WAS ISOLATED BY TAPPING THE SWITCH WHILE RUNNING PERFORMANCE EXERCISER (DIAGNOSTIC GIVES H.C.E. SKI ETC.)


PROBLEM WAS SOLVED BY REPLACING THE SWITCH (DEC PART NUMBER 29-22919).

FOR INTERNAL USE ONLY: This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 58	Page Revision A	Publication Date APRIL 1983
-------------------	--------------------	--------------------------------

DA-0000-13-01V4/T00

RM03-TT-70

		<b>FIELD SERVICE TECH TIP</b>				Option Designator RM03
		<input type="checkbox"/> 12 BN	<input checked="" type="checkbox"/> 16 BN	<input checked="" type="checkbox"/> 18 BN	<input checked="" type="checkbox"/> 32 BN	<input checked="" type="checkbox"/> 36 BN
Title 50 Hz Power Transformer Shorting					Tech Tip No. RM03-TT-55	
Processor Applicability A   L   L			Cross Reference RM02-TT-54		Tech Tip Rev A	Page 1 of 5
Author Mark Himes <i>Mark Himes</i>			Mgr/Supv. Approval Dennis Shaw <i>Dennis Shaw</i>			
Location CX CSSE		Mail Stop CX01-1/N27		Date 17-May-83		
CSSE Approval Dennis Shaw <i>Dennis Shaw</i>				Date <i>17 MAY 83</i>		
PSG Approval DAVE GURSKY <i>Dave Gursky</i>				Date 18 MAY 83		

CFSPS: ROBERT BARNARD *Bob Barnard*

The following material is intended as interim information until a CDC ECO and subsequent DEC ECO/FCO's are generated and released.

A few instances have been reported where the main 50hz power transformer (A1T1, physically larger than the 60Hz unit) have shorted to the upper deck casting in 50hz RM02/3 drive units. This has resulted in physical damage and insulation breakdown to the transformer insulation material and subsequent safety concerns.

On the next PM or service call, check your RM02/3 for proper clearance between the transformer and the upper deck chassis. This clearance must be checked with the deck in its LOWERED position. This check should be performed as follows:

- 1) Power down the drive and disconnect the AC power source.
- 2) Remove the top cover assembly.
- 3) From the rear of the drive, loosen the logic chassis clamp screws (see figure 1).
- 4) CAREFULLY slide the logic chassis (on its hinges) towards the rear of the drive and then up and to the left (counterclockwise) into the maintenance position (arrows 1 & 2, figure 1).
- 5) Locate the main 50hz transformer (A1T1) as shown in figure 2.
- 6) A closer view of the transformer is shown in figure 3.
- 7) The critical area of clearance is noted by arrow 5, figure 3. Check to be sure that there is sufficient clearance between the transformer and the upper deck chassis. A minimum of 2mm (.08") clearance is required. A flashlight and feeler gauge set may be required.

If the clearance is sufficient, then skip to step 13. Otherwise proceed with the next step(s) for proper transformer re-adjustment.

NOTE: If the transformer windings or winding insulation appear punctured or damaged, the transformer should immediately be replaced.

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 59	Page Revision A	Publication Date MAY 1983
-------------------	--------------------	------------------------------

DEC-01226 (12/82) 4/83

... 71

[      ]	<b>FIELD SERVICE TECH TIP</b>	Option Designator RMB3	
	<b>Continuation Sheet</b>		Category SYSTEMS
Title 50 Hz Power Transformer Shorting		Tech Tip No RMB3-TT-55	
Processor Applicability	Cross Reference RMB2-TT-54	Tech Tip Rev A	Page 2 of 5




Fig 1

8) Loosen the transformer mounting screws (#1, #2, and #3 in figure 4). Screw #4 is unaccessible at this time.

**FOR INTERNAL USE ONLY.** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 68	Page Revision A	Publication Date MAY 1983
-------------------	--------------------	------------------------------

DA-01000-12-00007000

RMB3-TT-72

<b>FIELD SERVICE TECH TIP</b>		Option Designator RM#3	
<b>Continuation Sheet</b>		Category SYSTEMS	
Title 50 Hz Power Transformer Shorting		Tech Tip No RM#3-TT-55	
Processor Applicability A L L	Cross Reference RM#2-TT-54	Tech Tip Rev A	Page 3 of 5




Fig 2

- 9) Rotate the transformer (using screw 4 as the pivot point) in the direction noted by arrow 6 in figure 4 until the required clearance is obtained. Since screw #4 is still tightened, the transformer may have to be lightly "tapped" to perform this step. If the transformer will not move, the 4th screw will have to be loosened. This screw is accessible by first removing the power supply assembly (figure 4).

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 61	Page Revision A	Publication Date MAY 1983
-------------------	--------------------	------------------------------

DA-000-11-00000000

RM#3-TT-55

<b>FIELD SERVICE TECH TIP</b>		Option Designator RM03	
<b>Continuation Sheet</b>		Category SYSTEMS	
Title 50 Hz Power Transformer Shorting		Tech Tip No RM03-TT-55	
Processor Applicability	Cross Reference RM02-TT-54	Tech Tip Rev A	Page 4 of 5




Fig 3

- 10) After readjusting the transformer, retighten the transformer mounting screws (1,2,3,4 in figure 4).
- 11) With the upper deck in its LOWERED POSITION, check for adequate clearance on the "other" side of the transformer. This will be the side of the transformer closest to the power supply. This area may be observed by looking through the hole in the rear of the positioner (arrow 3, figure 1) and applying sufficient light (with a flashlight) as shown by arrow 4 in figure 1. Assure there are no pinched wire harnesses and no chance of damage due to contact between the transformer or transformer winding assembly and other surrounding components or chassis.

**FOR INTERNAL USE ONLY** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 62	Page Revision A	Publication Date MAY 1983
-------------------	--------------------	------------------------------

DA-0000-12-000000

RM03-TT-74

<b>FIELD SERVICE TECH TIP</b>		Option Designator RM03-TT	
<b>Continuation Sheet</b>		Category SYSTEMS	
Title 50 Hz Power Transformer Shorting		Tech Tip No RM03-TT-55	
Processor Applicability	Cross Reference RM02-TT-54	Tech Tip Rev A	Page 5 of 5




Fig. 4


- 12) If the transformer cannot be sufficiently adjusted to provide the required clearance, contact your nearest Digital Area F.S. support representative and have them notify CSSE in Colorado Springs. Otherwise, continue with the next step.
- 13) Carefully return the logic chassis to its operating position and retighten the clamp screws (figure 1).
- 14) Verify drive operation using the available diagnostics on site.

**FOR INTERNAL USE ONLY** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 63	Page Revision A	Publication Date MAY 1983
-------------------	--------------------	------------------------------

DA-000-12 000000

RM03-TT-75

	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM03
	<input type="checkbox"/> 12 BN	<input type="checkbox"/> 16 BN	<input type="checkbox"/> 18 BN	<input type="checkbox"/> 32 BN	<input type="checkbox"/> 36 BN	Category SYSTEMS
Title NEW LINE FILTER IN SERIES 34 AND ABOVE					Tech Tip No. RM03-TT56	
Processor Applicability			Cross Reference RM02-TT-55		Tech Tip Rev A	Page 1 of 1
Author STEVE SCHWEIN				Mgr./Supv. Approval		
Location ST. LOUIS, MO.			Mail Stop		Date 4 APR 83	
CSSE Approval DENNIS SHAW <i>Dennis Shaw</i>			Date 1 JUNE 83			
PSG Approval DAVE GURSKY <i>Dave Gursky</i>			Date 6 June 83			

CDC is using a new line filter on later model RM02/03 Drives. The filter does not have a DEC part number but can be ordered via the vendor number 92 009801.

The new filter is smaller than the old one and has a male receptacle mounted at the back.

FOR INTERNAL USE ONLY. This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 64	Page Revision A	Publication Date July 1983
-------------------	--------------------	-------------------------------

<b>digital</b>	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM03	
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input checked="" type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category SYSTEMS	
Title BRAKE noise and Grounding FCO's					Tech Tip No. RM03-TT-57		
Processor Applicability A   L   L			Cross Reference RM02-TT-56		Tech Tip Rev A	Page 1 of 1	
Author Mark Himes <i>Mark Himes</i>			Mgr./Supv. Approval Dennis Shaw <i>Dennis Shaw</i>				
Location CX CSSE		Mail Stop CX02-1/K97		Date 26-Oct-83			
CSSE Approval Dennis Shaw <i>Dennis Shaw</i>			Date 26 OCT 83				
			Date				

The vendor (CDC) originally created the following ECO/FCO's to resolve a problem with the ungrounded brake assembly as a source of noise into the drive.

Vendor ECO # PE60337  
Vendor FCO # PE60378 (FCO kit, vendor p/n 89053893)

This particular vendor FCO kit included a ground "wire" and other various hardware items. This FCO kit was incorporated into the following DEC FCO kits:

EQ-01096 (RM02-S0015 FCO documentation + 1 ea. 29-11997)  
EQ-01097 (RM03-S0023 FCO documentation + 1 ea. 29-11997)

Note: DEC p/n 29-11997 contained vendor part number 89053893 which in turn contained the CDC kit for FCO PE63078.

It was later determined that the original FCO was not adequate in many situations. The vendor created another ECO/FCO to supercede the previous ECO/FCO. The new ECO/FCO replaced the ground "wire" with a ground "BRAID" to reduce and/or eliminate brake generated noise. The new vendor ECO/FCO is:

Vendor ECO # DJ00200  
Vendor FCO # DJ00200 (FCO kit vendor p/n 89053931)

The NEW PARTS + DOCUMENTATION ARE NOW AVAILABLE under the ORIGINAL DEC part numbers:

EQ-01096 (RM02-S0015 FCO documentation + 1 ea. 29-11997)  
EQ-01097 (RM03-S0023 FCO documentation + 1 ea. 29-11997)  
29-11997 (vendor kit p/n 89053931 for FCO DJ00200)

The vendor kit (supplied with the DEC FCO kit) includes new instructions and hardware for both of the possible situations:

- 1) Install the new brake assembly ground BRAID.
- 2) Replace any existing brake assembly ground "wire" with the BRAID.

It is recommended that the NEW revised FCO kit be installed at the next PM or service call if brake generated noise problems are suspected.

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 65	Page Revision A	Publication Date NOVEMBER 1983
-------------------	--------------------	-----------------------------------

RM03-TT-57

<b>digital</b>	<b>FIELD SERVICE TECH TIP</b>				Option Designator RM03	
	<input type="checkbox"/> 12 BIT	<input checked="" type="checkbox"/> 16 BIT	<input type="checkbox"/> 18 BIT	<input checked="" type="checkbox"/> 32 BIT	<input checked="" type="checkbox"/> 36 BIT	Category SYSTEMS
Title DATA ERRORS DUE TO RUNOUT					Tech Tip No. RM03-TT-58	
Processor Applicability 11's 20's VAX		Cross Reference RM02-TT-57 RM05-TT-22			Tech Tip Rev A	Page 1 of 1
Author MARK LICATA			Mgr/Supv. Approval <i>Ronald G. Chan</i>			
Location CHICAGO PRODUCT SUPPORT		Mail Stop RLO ROLLING MEADOWS, IL		Date 10 AUG 1983		
CSSE Approval <i>Jan Milano</i>				Date 3 JAN 1984		

PROBLEM

EXCESSIVE DATA PROBLEMS DUE TO INABILITY OF CARRIAGE TO FOLLOW OUT OF ROUND SPINDLE OR PACK DURING FINE MODE.

SYMPTOMS

IF YOU ARE EXPERIENCING OFF CYLINDER FAULTS OR EXCESSIVE DATA ERRORS THE CAUSE COULD BE EXCESS RUNOUT OF THE PACK OR SPINDLE. THE RM POSITIONER HAS TO DRIFT OFF CYLINDER IN FINE MODE FOR MORE THAN 800 MICROSECONDS TO ACTUALLY FLAG AN OFF CYLINDER FAULT. IF THE POSITIONER DRIFTS BECAUSE OF PACK OR SPINDLE OUT OF ROUNDNESS FOR LESS THAN 800 MICROSECONDS, NO POSITIONER ERROR OR FAULT IS DETECTED. AT 3600 RPM'S A SECTOR IS ONLY 520 MICROSECONDS, SO A WHOLE SECTOR COULD BE READ OR WRITTEN OFF CYLINDER WITH NO INDICATION OF A RUNOUT PROBLEM.

SOLUTION

LOAD HEADS AND SCOPE RUNOUT AT GIVEN TEST POINT TO DETERMINE IF SPINDLE AND PACK ARE WITHIN GUIDELINES. WHEN TAKING READINGS ROTATE PACK 90 DEGREES 4 SEPARATE TIMES, THEN LOOK AT ALL READINGS TO DETERMINE STATUS.

	<u>RUNOUT TEST POINT</u>	<u>MAX SPEC P-PEEK</u>	<u>INDEXTRIGGER</u>
RM02/03 RM05	A2A08 TPF A2A19 TPC	1.0 VP-P 400 MVP-P	A2B08 TPC A2A06 TPC

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation. For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 66	Page Revision A	Publication Date JANUARY 1984
-------------------	--------------------	----------------------------------

HN 38-78

[ ]	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM03	
	<input type="checkbox"/> 12 BN	<input checked="" type="checkbox"/> 16 BN	<input type="checkbox"/> 18 BN	<input type="checkbox"/> 32 BN	<input type="checkbox"/> 36 BN	Category SYSTEMS	
Title PROBLEMS USING RM02/03 RAIL ALIGNMENT TOOL					Tech Tip No. RM03-TT-59		
Processor Applicability			Cross Reference RM02-TT-58		Tech Tip Rev A		Page 1 of 2
Author JOHN LOCKRIDGE				Mgt/Supv. Approval <i>[Signature]</i>			
Location LYNCHBURG, VA			Mail Stop LBO		Date 11/4/83		
CSSE Approval <i>[Signature]</i>					Date 1/3/84		
					Date		

PROBLEM

ANYONE WHO HAS REPLACED RAILS ON AN RM02/03 HAS PROBABLY EXPERIENCED DIFFICULTY WITH THE ALIGNMENT TOOL AS FOLLOWS:

AFTER FOLLOWING INSTRUCTIONS AND SECURING THE TOOL TO THE BOTTOM RAIL WITH THE TWO THUMB-SCREWS, THE TOOL "WOBBLES" OR "ROCKS" BACK AND FORTH AND IS NOT STABLE. THIS CAUSES INCONSISTANT RESULTS. THE TOP RAIL MAY BE PARALLEL TO THE BOTTOM, BUT IS NOT NECESSARILY ALIGNED. IT MAY BE RIGHT OR LEFT OF THE BOTTOM RAIL BY VARYING DEGREES.

IF LEFT IN THE CONDITION DESCRIBED ABOVE, THE RM02/03 MAY EXPERIENCE EXCESSIVE RAIL/BEARING WEAR AND/OR HEAD CRASHES BECAUSE THE ENTIRE CARRIAGE/HEAD ASSEMBLY WILL BE TILTED WITH RESPECT TO THE DISK SPINDLE.

CAUSE

THE THUMB-SCREWS WHICH SECURE THE TOOL TO THE BOTTOM RAIL EACH HAVE TWO SETS OF THREADS; ONE SCREWS INTO THE TOOL AND THE OTHER INTO THE BOTTOM RAIL. ON SOME DRIVES, THIS WILL ACT AS A "JACK SCREW" AND ACTUALLY LIFT THE TOOL OFF THE BOTTOM RAIL. IN THIS "SUSPENDED" CONDITION, THE TOOL IS UNSTABLE AND DOES NOT PROVIDE A RELIABLE REFERENCE FOR THE "RAIL BRACKET" OR THE TOP RAIL.

SOLUTION

REMOVE THE THUMB-SCREWS AND USE A LOCALLY PURCHASED SIZE 6-32 SCREW CUT TO EXACTLY 1.4". REMEMBER THAT YOU ARE ONLY CATCHING TWO OR THREE THREADS, SO DON'T OVERTIGHTEN. BY FOLLOWING THIS PROCEDURE, YOU WILL FIND THAT THE TOP & BOTTOM RAILS LINE UP JUST AS THE BOOK SAYS THEY SHOULD.


**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation. For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 67	Page Revision A	Publication Date JANUARY 1984
-------------------	--------------------	----------------------------------

01-0102-10-01/11/78

RM1 - TT-79

[ ]	<b>FIELD SERVICE TECH TIP</b>	Option Designator RM03	
	<b>Continuation Sheet</b>	Category SYSTEMS	
Title PROBLEMS USING RM02/03 RAIL ALIGNMENT TOOL		Tech Tip No. RM03-TT-59	
Processor Applicability	Cross Reference RM02-TT-58	Tech Tip Rev A	Page 2 of 2






RAIL ALIGNMENT TOOL

FRONT END VIEW

FOR INTERNAL USE ONLY: This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 68	Page Revision A	Publication Date JANUARY 1984
-------------------	--------------------	----------------------------------

RM03-TT-59

		<b>FIELD SERVICE TECH TIP</b>				Option Designator RM03	
		<input type="checkbox"/> 12 BN	<input type="checkbox"/> 16 BN	<input type="checkbox"/> 18 BN	<input checked="" type="checkbox"/> 32 BN	<input type="checkbox"/> 36 BN	Category Diagnostics
Title EVRDA Rev 4.1 Problem					Tech Tip No. RM03-TT-60		
Processor Affected Vax1			Cross Reference RM02-TT-59, RM05-TT-23, RM80-TT-21		Tech Tip Rev A		Page 1 of 1
Author Koller				Mgr./Supv. Approval			
Location CXO			Mod/Stop CXO 2-1/K97		Date 3-23-84		
CSSE Approval Ron Milano			 		Date 3.24.84		
PSPSG Approval Al Snyder					Date 3.24.84		

**PROBLEM:**

EVRDA Rev 4.1 fails Test 73, Subtest 0 (Error 3), when run on a VAX11-780 with the new extended silo module for the RM780 (module MB274). Since the new module has a deeper silo, the diagnostic's timer times out before the silo empties.

**FIX:**

The fix consists of a patch to be made to the program after it is loaded in memory via the Diagnostic Supervisor.

Since it appears that there may be two versions of the diagnostic both identifying themselves as Rev 4.1, the patch that follows covers both cases:

1. Load program EVRDA
2. SET BASE 9BFC                    [old Rev 4.1]
3. EXAM E9 contents should be 00530200
  - A. IF this is correct, then DEP/L E9 00530700
  - B. Done. Run the program.
4. If the contents were not correct, SET BASE 9D66
5. EXAM F6 contents should be 00530200
  - A. IF this is correct, then DEP/L F6 00530700
  - B. Done. Run the program [new Rev 4.1]

A new revision of the program will be released on the very next VAX Diagnostic release cycle.

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 69	Page Revision A	Publication Date APRIL 1984
-------------------	--------------------	--------------------------------

RM03-TT-60

[ ]	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM03
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category Safety
Title RM Mass Buss Adapter Caution					Tech Tip No. RM03-TT-61	
Processor Applicability 10   11   20 VAX			Cross Reference SEE BELOW		Tech Tip Rev A	Page 1 of 1
Author Louis Carpenito				Mgr/Supv Approval Bob Barnard		
Location OGO			Mail Stop 1-1/F17		Date 19-JUN-84	
CSSE Approval Dennis Shaw				<i>RWM</i>		Date <i>23 Jul 84</i>
FSPE Approval Bob Barnard				<i>Bob Barnard</i>		Date <i>6-23-84</i>

# CAUTION

Extreme care must be used when working in or around the RM Mass Buss Adapter chassis slides. The flat bearings inside the channel of the slide may be sharp enough to inflict a minor cut to your fingers and/or hands.


Also extreme care must be taken when fastening the ground cables to the ground stud on the side of the unit, because your wrist may be close to the sharp edges of the chassis slide.

**CROSS REFERENCE:**

RM MASS BUSS ADAPTER-TT-01  
 RM02-TT-60  
 RM80-TT-22  
 SAFETY-TT-18

FOR INTERNAL USE ONLY This information is property of Digital Equipment Corporation  
 For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 70	Page Revision A	Printed on Date August 1984
-------------------	--------------------	--------------------------------

	<b>FIELD SERVICE TECH TIP</b>				Option Designator RM03
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH
Title RM ADAPTER POWER SUPPLY (70-13826) CAUTION					Tech Tip No. RM03-TT-62
Processor Applicability 111'd (VAX) LCG		Cross Reference RM05-TT-26 RM02-TT-61 , RM 80-TT-23		Tech Tip Rev . A	Page 1 of 1
Author RICK SWANSON			Mgr/Supv Approval RON MILANO <i>R. Milano</i> /CSSE		
Location COLORADO SPRINGS		Mail Stop CX0-17K97		Date 3-JANUARY-1985	
CSSE Approval RON MILANO CX/CSSE <i>R. Milano</i>			Date 3-JANUARY-1985		
FSPSG Approval			Date		


Extreme caution must be used when working in or around the RM Adapter Power Supply.

When the Power Supply is disassembled to allow service access, there are exposed uninsulated parts with primary AC voltage present on them. The possibility of coming in contact with such voltage is very likely when servicing the RM Adapter Power Supply.

**WARNING:** WHEN SERVICING THE RM ADAPTER POWER SUPPLY, LOCATED IN THE RM ADAPTER, ALWAYS MAKE SURE THAT THE RM ADAPTER MAIN AC POWER CORD CONNECTOR IS REMOVED FROM THE SITE POWER SOURCE.

FOR INTERNAL USE ONLY. This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 71	Page Revision A	Publication Date JANUARY 1985
-------------------	--------------------	----------------------------------

	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM03
	<input type="checkbox"/> 12 BN	<input checked="" type="checkbox"/> 16 BN	<input type="checkbox"/> 18 BN	<input checked="" type="checkbox"/> 32 BN	<input checked="" type="checkbox"/> 36 BN	Category DISK
Title SPEED SENSOR PROBLEM					Tech Tip No. RM03-TT- 63	
Processor Applicability  114   VAX   LCG			Cross Reference RM02-TT- 62		Tech Tip Rev A	Page 1 of 2
Author Ricky C. Swanson				Mgr/Supv Approval Ron Milano <i>Ron Milano</i>		
Location Colorado Springs			Mail Stop CX01/P14		Date 6-MARCH-1985	
CSSE Approval Ron Milano CX/CSSE <i>Ron Milano</i>				Date 6-MARCH-1985		
FSPSG Approval				Date		

**PROBLEM:** When checking or adjusting the speed sensor assembly on the RM02/RM03 disk drive, always make sure that the metallic transducer pickup is properly secured inside the plastic threaded housing of the speed sensor assembly.

During some occasions the adhesive securing the transducer pickup inside the threaded stud has broken down. When this occurs the transducer pickup will usually slip down inside the threaded stud instead of protruding from the top of the stud housing.

When adjusting the speed sensor assembly a GO/NOGO tool is used to get the transducer pickup to a maximum height without interfering with the rotating disk pack. This is done by resting the tool on the spindle face plate and observing that the tool "GO SIDE" will pass over the top of the transducer pickup while the tool "NOGO" side will not clear the top of the transducer pickup. When the adhesive breaks down it lets the transducer pickup recess itself inside the threaded stud. When the speed transducer adjustment is attempted with the transducer pickup in its lowered position, the height of the threaded stud must now be increased to the height of the tool. This is because the clearance is normally measured from the bottom of the GO/NOGO tool to the top of the metallic transducer pickup.

With the transducer pickup recessed the plastic housing must be elevated to satisfy the proper clearance with the GO/NOGO tool. The result is, the top of the sensor gets chipped away by the speed sensing magnets embedded in the bottom of the pack. These plastic particles can be the contributing cause that eventually results in a head crash.

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 72	Page Revision A	Publication Date MARCH 1985
-------------------	--------------------	--------------------------------

RM08 TT 84

[ ]	<b>FIELD SERVICE TECH TIP</b>		Option Designator RM03	
	<b>Continuation Sheet</b>		Category DISK	
Title SPEED SENSOR PROBLEM			Tech Tip No RM03-TT- 63	
Processor Applicability 11's MAX   LCG		Cross Reference RM02-TT- 62	Tech Tip Rev A	Page 2 of 2

**SOLUTION:** When adjusting or checking the speed transducer for the proper clearance, carefully inspect the adhesive that secures the transducer pickup inside the plastic threaded housing. If there is evidence of the adhesive breaking down you will either notice tiny cracks in the adhesive or else the transducer pickup will not be securely mounted in the center of the plastic threaded stud. In either case, replacement of the speed sensor assembly is required.

SPEED SENSOR ASSEMBLY -- PART NUMBER -- 29-22909 --

**FOR INTERNAL USE ONLY** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 73	Page Revision A	Publication Date MARCH 1985
-------------------	--------------------	--------------------------------

14-01185-12 DE 1/85

RM03 TT-85

[ _ ]	<b>FIELD SERVICE TECH TIP</b>				Option Designator RM03	
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category Disk
Title FCO: RM02-50020 Documentation					Tech Tip No. RM03-TT-64	
Processor Applicability VAXI III's ILCG I			Cross Reference RM02-TT-63		Tech Tip Rev A	Page 1 of 1
Author Ken Davis				Mgr./Supv Approval Terry Howard		
Location Winnipeg			Mail Stop WNO		Date 28-August-1985	
CSSE Approval Ron Milano CX/CSSE <i>R. Milano</i>					Date 07-October-1985	
FSPSG Approval					Date	

PROBLEM:

FCO DOCUMENTATION ERRORS AND OMISSION.

SOLUTION:

- 1) PAGE 1 OF 4: QUICK CHECK BLOCK STATES "PRESENCE OF 5.0 MFD CAPACITOR...". IT SHOULD STATE "PRESENCE OF 8.0 MFD CAPACITOR...".
- 2) PAGE 2 OF 4: STEP 9 STATES "INSTALL A 5 MFD CAPACITOR,...". IT SHOULD READ "INSTALL AN 8 MFD CAPACITOR,...".
- 3) PAGE 2 OF 4: STEP 11 STATES "SOLDER OTHER LEAD OF CAPACITOR TO PIN 6 OF J1." IT SHOULD READ "SOLDER OTHER LEAD OF CAPACITOR TO PIN 6 OF J1B".  
SOLDERING THE CAPACITOR TO J1A WILL CAUSE THE EMA COIL TO EMIT A VERY LOUD, HIGH-PITCHED TONE.

FOR INTERNAL USE ONLY This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 74	Page Revision A	Publication Date OCTOBER 1985
-------------------	--------------------	----------------------------------

FIELD SERVICE TECH TIP					Option Designator
					RM03
	12 BH	X 16 BH	18 BH	X 32 BH	X 36 BH
Title					Tech Tip No.
CPX Head Inspection Tool Kit					RM02-TT-64 RM03-TT-65
Processor Applicability			Cross Reference		Tech Tip Rev
VAX	11/4	LCG	RP05-TT-64	RP06-TT-71	A
Author				Mgr/Supv Approval	
Gene Ridge CX/CSSE				Ron Milano <i>[Signature]</i>	
Location			Mail Stop		Date
Colorado Springs			CX01-1/P14		02-October-1985
CSSE Approval					Date
Ron Milano CX/CSSE <i>[Signature]</i>					02-October-1985
FSPSG Approval					Date

### CPX HEAD INSPECTION TOOL KIT

VESE and CPX Company are pleased to announce the availability and special price to Digital branches for the CPX Head Inspection Tool Kit. This tool kit has been evaluated and approved by the Colorado Springs CSSE Maintainability Engineering Group for use on the following disk drives.

DIGITAL - RP05, RP06, RM02, RM03, RM05

MEMOREX - 677


CDC - 9762, 9766

The kit part number from CPX is HIMKK2531N, which is a combination of two standard CPX Head Inspection Kits. Included in this kit are the following items.

CPX P/N	DESCRIPTION	QTY
HIMKG1125N	MDG25 Base Unit with Optics offset at 105 degrees	1
HIACC1006N	Optical tube, 10x power magnification	1
HIACC1005N	Optical Brush	1
MICAS1002N	Aluminum Case	1
HITRA1062N	Power Transformer 24 VAC, 16 amp output	1
HIACC1003N	E230 Removeable Rails	1
HIBKT1001N	E124 RM05 Carriage Limit Bracket	1
HIBKT1002N	E123 RM03 Carriage Limit Bracket	1

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation. For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number	Page Revision	Publication Date
75	A	OCTOBER 1985

	<b>FIELD SERVICE TECH TIP</b>		Option Designator RM03	
	<b>Continuation Sheet</b>		Category Disk	
Title CPX Head Inspection Tool Kit		RPO5-TT-64	Tech Tip No RM03-TT-65	
Processor Applicability VAX   11's   LCG		Cross Reference RPO6-TT-71 RM02-TT-64	Tech Tip Rev A	Page 2 of 2

With this Head Inspection Tool Kit, an engineer will be able to closely inspect R/W Heads on the above disk drives without removing the heads themselves. This will save valuable labor time for the F.S. Engineer and will help decrease the amount of down time for the customer. The head inspection tool may be used during PM's to help the engineer diagnose a dirty head before a major failure occurs.

To facilitate orders in a timely manner, Field Service Branches and Regional Logistics offices may order through the local CPX Sales Office or place the order with the CPX home office by sending a Purchase Order to:

CPX  
21900 Plummer Street  
Chatsworth, CA 91311

Tel: (818)709-4003  
Telex: 371-9692  
TWX: 310-371-9692  
FAX: 818-882-7799

ATTENTION: Jenny Rippel

The Digital price for the Head Inspection Tool Kit (HIMKK2531N) is \$745.00. Digital's Field Service Logistics Organization will not stock this item in Woburn (SR #17) unless sufficient demand for this tool kit is present. If there are any questions regarding the ordering of this Head Inspection Tool, you may contact Fran Linnehan at Mailstop 0G01-1/H11.

**FOR INTERNAL USE ONLY** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 76	Page Revision A	Publication Date OCTOBER 1985
-------------------	--------------------	----------------------------------

# Field Service **TECH TIP**



**Title** Diagnostic CZRMPBO.BIC  
**Failure**  
**Cross Reference** RM02-TT-65  
 RM05-TT-30

**Category** Disks  
**Option** RM03  
**Rev** A  
**TECH TIP No** RM03-TT-66

**Problem/Solution**

Test 72 of Diagnostic CZRMPBO.BIC (RM02/03/05 Diskless Test 1) fails on a PDP 11/60 with Cache, the indication is that the AOE bit did not set. The problem is due to the speed of the cache memory on an 11/60 system. The following patch has been written by Diagnostic Engineering and will be available on the next release of XXDP in the January '87' time frame.

Change loc.	From	To
034400	012760	012702
034402	061001	000020
034404	000024	004737
034406	012760	000630
034410	041001	005302
034412	000024	001376
000630	000632	012760
000632	000000	061001
000634	000636	000024
000636	000000	012760
000640	000642	041001
000642	000000	000024
000644	000646	000207

**Approvals**

<b>Author</b> Gary Cable	<b>ESD&amp;P TECH TIP Coordinator</b> Bruce J. Conley	<b>CSSE</b> Gary Cable
<b>Author's Manager</b> Mike Mayfield		<b>Field Service Product Safety</b>
<b>Release Date</b> 5 November 1986		<b>Revision</b> A

**FOR INTERNAL USE ONLY:** This information is the property of Digital Equipment Corporation  
 For more information on writing or approving TECH TIPS see Administrative TECH TIP Number 2







DIGITAL EQUIPMENT CORPORATION



Engineering Change  
Order Log

**RM05**

Disk Drive

PROCESSOR TYPE: PDP-11, VAX

**RM05-00001 CODE: D**  
MAR 80 - PROBLEM Minor documentation changes needed to bring documentation in conformity to DEC Std 140  
CORRECTION Correct documentation  
IN-PLANT EFFECTIVITY Documentation change only

**RM05-00002 CODE: D**  
APR 80 - PROBLEM Present Dual Port configuration design is not adequate.  
CORRECTION Redesign necessary hardware for revised Dual Port configuration  
IN-PLANT EFFECTIVITY. Phase-In to Colorado by 26 April 1980

**RM05-00003 CODE: D**  
APR 80 - PROBLEM Present Dual Port configuration design is not adequate  
CORRECTION Redesign necessary hardware for revised Dual Port configuration  
IN-PLANT EFFECTIVITY Phase-In to Colorado by 15 June 1980

**RM05-00004 CODE: D**  
JUL 80 - PROBLEM 1 Present documentation structure does not allow manufacturing of inhouse Dual Port MBA s  
CORRECTION 1 Restructure documentation allowing Colorado to build Dual Port MBA s  
PROBLEM 2 Latch to lock MBA in home position not documented  
CORRECTION 2 Include latch callout for Cabinet Assembly 7017612  
PROBLEM 3 Access Hole Cover never implemented  
CORRECTION 3 Add Access Hole Cover (7424313-00) to Cabinet Assembly.  
PROBLEM 4 Cable Clamps compensate for unused new Round I/O Cable  
CORRECTION 4 Add Cable Clamps, 7424324-00, to Cabinet Assembly.  
PROBLEM 5 Backplane Shield should be used.  
CORRECTION 5 Add Backplane Shield 7424464-00 to Single Port MBA Chassis Assembly 7017606  
IN-PLANT EFFECTIVITY: Documentation change only. CORRECTIONS 1 and 2 Phase-In to Colorado by 10 September 1980, CORRECTIONS 3, 4, and 5

**RM05-00005 CODE: D**  
NOV 80 - PROBLEM 1 Terminators should not be used on this assembly level  
CORRECTION 1 Remove terminators from Unit Assembly Drawing D-UA-RM05-0-0  
PROBLEM 2 Ground strap not needed from MBA Backplane Logic to Drive Logic  
CORRECTION 2 Remove Logic Ground from Unit Assembly Drawing D-UA-RM05-0-0  
PROBLEM 3 Method of grounding I/O Cable never documented  
CORRECTION 3 Show method and hardware for grounding I/O Cable  
PROBLEM 4 MBA Single Port Assembly should be secondary level assembly drawing  
CORRECTION 4 Revise Parts List Drawing K-PL-7017606-0-DBP and Assembly Drawing D-AD-7017606-00 to reflect second level assembly Replace third level assembly drawing with Assembly Drawing D-AD-7018322-0-0  
PROBLEM 5 MBA Chassis Assembly does not reflect actual build  
CORRECTION 5 Update MBA Chassis Assembly 7018322-00 to show Module Holder Clip 1209856-02 Kep Nut 9006565-00, and Lock Washer 9006635-00  
IN-PLANT EFFECTIVITY Immediately Co-requisite ECO 7017344-00002.

**RM05-00006 CODE: D**  
JUL 81 - PROBLEM Current production models not documented  
CORRECTION Correct Table of Contents Drawing B-TC-RM05-0-1 and Specifications Drawing B-SP-RM05-0-BK7B  
IN-PLANT EFFECTIVITY Documentation change only

**RM05-00007 CODE: D**  
AUG 82 - PROBLEM This ECO was changed to ECO RM05-00008

**RM05-00008 CODE: D**  
SEP 82 - PROBLEM 1 Cable is difficult to manufacture and to assemble  
CORRECTION 1 Use new cable 7019688-15  
PROBLEM 2 RM05-00007 has incorrect Colorado Control Number  
CORRECTION 2 Change RM05-00007 to RM05-00008.

DIGITAL EQUIPMENT CORPORATION

Engineering Change  
Order Log

**RM05**

PROCESSOR TYPE: PDP-11, VAX

Disk Drive

**PROBLEM 3** Documentation changes not documented

**CORRECTION 3** Revise Unit Assembly Drawing D-UA-RM05-0-0 Parts List Drawing K-PL-RM05-0-DBP, Assembly Drawing D-AD-7018322-0-0, Parts List Drawing K-PL-7018322-0-DBP, Assembly Drawing D-AD-7017612-0-0, and Parts List Drawing K-PL-7017612-0-DBP

**IN-PLANT EFFECTIVITY** Phase-In to Colorado by 13 August 1982 and phase-in to Kaufbeuren by 30 September 1982

**RM05-00009 CODE: D**

**OCT 82 - PROBLEM** Improved Bridge Rectifier needed

**CORRECTION** Change wiring at TBG in Power Supply See CDC NEC 2433

**IN-PLANT EFFECTIVITY** Phase-In to all units by 1 February 1981

**RM05-00010 CODE: D**

**OCT 82 - PROBLEM 1** Inadequate air flow on 50Hz units

**CORRECTION 1** Change to single wheel style blower See CDC NEC H206

**PROBLEM 2** VDE modification not incorporated in 60Hz units

**CORRECTION 2** Modify Parts List Drawing K-PL-RM05-0-DBP and incorporate changes See CDC NEC H140B

**PROBLEM 3** Improved servo cable retainer needed

**CORRECTION 3** Modify servo cable retainer See CDC NEC H243

**IN-PLANT EFFECTIVITY** Phase-In **CORRECTION 1** in all 50Hz units by 14 January 1982 and phase-in **CORRECTIONS 2 and 3** in all units by 14 January 1982.

**RM05-00011 CODE: D**

**OCT 82 - PROBLEM 1** Inadequate air flow on 60Hz units

**CORRECTION 1:** Change to single wheel style blower See CDC NEC H206

**PROBLEM 2** Crimping of cable to motor and power supply assembly.

**CORRECTION 2.** Re-position motor relay box 180°. See CDC NEC H201.

**PROBLEM 3** Shorter length levelers needed

**CORRECTION 3** Modify thread length of levelers to 2.25 in. See CDC NEC H202A.

**PROBLEM 4** Insufficient overcurrent protection  
**CORRECTION 4** Add fuses and circuit breakers to secondary circuits of Ferro Transformers See CDC NEC H193A

**IN-PLANT EFFECTIVITY** Phase-In **CORRECTION 1** in all 60Hz units by 12 April 1982 and phase-in **CORRECTIONS 2, 3, and 4** by 12 April 1982

**RM05-80012 CODE: F**

**APR 83 - PROBLEM SYMPTOM** Carriage slam on loss of  $\pm 20V$  DC

**PROBLEM** Loss of  $\pm 20V$  causes carriage slamming

**CORRECTION** Replace FQPV card with HQPV card in Location A2A08 and change 4 backplane wires See CDC NEC H241

**IN-PLANT EFFECTIVITY** (October, 1982) Phase-In to all Units by 1 March 1982

**FIELD EFFECTIVITY** Retrofit all RM05 drives series code 18 through 29

**QUICK CHECK** Presence of HQPV card in location A2A08

The DEC on-site labor charge will be the time required to install and test the FCO at the then-current hourly rate

**FCO KIT ORDERING**

EQ-01182-00 FCO, PARTS

FA-04431-G FCO only



**LIBRARY TYPE  
PDP 11, VAX**

**RM05-00013 CODE: D**

OCT 82 - PROBLEM Pack Access interlocking is not VDE compliant

CORRECTION Add interlock switch A359 and two wires.

IN-PLANT EFFECTIVITY Phase in all units by SEP 82

**RM05-R0014 CODE: F**

OCT 84 -PROBLEM: 1. Intermittent Carriage Slam 2 Frequent power supply related problems 3 Intermittent head unloading, spin down, or drive off line errors

IN-PLANT EFFECTIVITY NOV 82

FIELD EFFECTIVITY Retrofit all VDE RM05 drives, series code 35 and below, when the problem symptoms are evident

QUICK CHECK Verify presence of VDE power supply, vendor part number 73133111 or higher in 50HZ drives or 73133112 or higher 50HZ drives

The DEC on-site labor charge will be the time required to install and test the FCO at the then current hourly rate

**FCO KIT ORDERING**

EQ-01254-01: FCO, PARTS

EQ-01254-02: FCO, PARTS

FA-04426-01: FCO only



30-Oct-1986  
RM05-INDEX.A  
REV A

MICROMEDIA PUBLISHING

Field Change Order Index  
-----

FCO Number -----	FA REV ---	Rel. Date -----	SB# ---	Problem -----
-RM05---S012	A	7-Apr-83	276	Loss of +/-20V causes carriage slamming
-RM05---R014	A	12-Oct-84	352	Intermittent carriage slam, power supply, head unloading, spin down

Rm05-FCO-1



# FIELD CHANGE ORDER

FA-04431-00

PCO

RM05

5

0012

PAGE  
1 of 2

Level of Urgency (LOU)

STATUS	PCO EXPENSE RESPONSIBILITY			ESTIMATED TIME TO INSTALL and TEST (on-site) (Travel time not included)
	MANDATORY	R	PER CALL	
Mandatory	DIGITAL			1.0 DECIMAL HOURS
Required			CUST	
Specification			CUST	
Improvement			CUST	
Hardware Option	PURCHASEABLE OPTION			
Cosmetic	CUST	CUST	CUST	

On-site PCO installation, by DEC, will be in accordance with both APPLICABILITY and the above PCO EXPENSE RESPONSIBILITY needs.

QUICK CHECK (To determine if PCO has been installed)  
PRESENCE OF HQPV CARD IN LOCATION A2A08.

LAST PREVIOUS PCO: NONE

RELATED OR PREREQUISITE PCO # / MCO #  
NONE

PCO KIT CHARGES (United States and Canada only)

KIT ITEM	DOCUMENTATION	PARTS	OTHER
<input checked="" type="checkbox"/> PCO	NONE	::	
<input type="checkbox"/> PRINTS	\$10.00		

Parts charges are as of FCO release date and are subject to change.

PARTS AVAILABILITY DATE: MAY, 1983

LOGISTICS CODING: 4K 3K 4K

LOGISTICS REVIEW: *EM Dyer 3/14/83*

QTY	PART NUMBER	DESCRIPTION
1	29-23557-00	CDC FCO KIT 85010002

ORDER BY THIS NUMBER	KIT CONTAINS		
	FCO	PRINTS	PARTS
EQ-01182-00	X		X
FA-04431-00	X		

\*\*PARTS PRICE UNDETERMINED AT DATE OF FCO RELEASE.

## APPLICABILITY

RETROFIT ALL RM05 DRIVES SERIES CODES 18 THROUGH 29.

SPECIAL TEST EQUIPMENT, TOOLS, or SUPPLIES  
(Not included in the Field Retrofit Kit)

NONE

## FIELD INSTALLATION and TEST PROCEDURE

SEE PAGE 2 OF THIS FCO.

COMPATABILITY: HQPV MODULE WILL NOT FUNCTION WITHOUT BACKPLANE WIRING CHANGES.

PROBLEM SYMPTOM: CARRIAGE SLAM ON LOSS OF  $\pm$  20V DC.

APPROVED-Field Service Product Support

*Loyd G. Buchanan*  
LOYD G. BUCHANAN

LIBRARIES: 11  
VAX*DM*

APPROVED-Field Service Product Safety

LOUIS CARPENITO

*Louis Carpenito*

FCO RELEASE DATE

7 APRIL 1983

RM05 FCO 1A

TO BE INSTALLED ONLY BY RM05 TRAINED PERSONNELREWORK PROCEDURE  
FOR  
FCO RM05-S0012

- 1- POWER DOWN DRIVE.
- 2- REMOVE FQPV MODULE FROM DRIVE. INSTALL NEW HQPV MODULE IN SAME LOCATION.
- 3- INSTALL WIRE ADDITIONS TO BACKPLANE AS FOLLOWS:

<u>SIGNAL NAME</u>	<u>FROM</u>	<u>TO</u>
- (SPEED FAULT+VOLTAGE FAULT)	A1914A	A0808A
+ TIE HIGH	A1322B	A0203B
+ [(~UP TO SPEED)+VOLTAGE FAULT]	A1715B	A1915A
+ [(~UP TO SPEED)+VOLTAGE FAULT]	A1715B	A1914B

- 4- INSTALL A SCRATCH DISK PACK.
- 5- POWER UP DRIVE AND ALLOW HEADS TO LOAD.
- 6- TO ENSURE PROPER OPERATION, MANUALLY DROP  $\pm$  20V CIRCUIT BREAKER AND OBSERVE EMERGENCY RETRACT. MAKE SURE HEADS DO NOT SLAM TOWARDS SPINDLE.



# FIELD CHANGE ORDER

FA-04426-01

FCO

RM05

R

0014

PAGE

1 of 17

Level of Urgency (LOU)

SLATE  
LOU

## FCO EXPENSE RESPONSIBILITY

	MANDATORY	R	PER CALL
Mandatory			
Required			CUST
Specification			CUST
Improvement			CUST
Hardware Option	PURCHASEABLE OPTION		
Comments	CUST	CUST	CUST

ESTIMATED TIME TO INSTALL and TEST (on-site)  
(Travel time not included)

1.0

DECIMAL HOURS

## APPLICABILITY

Retrofit all VDE RM05 drives, series code 35 and below, when problem symptoms are evident.

See NOTE 1 under "Notes for FCO RM05-R0014" (page 2 of 17)

On-site FCO installation, by DEC, will be in accordance with both APPLICABILITY and the above FCO EXPENSE RESPONSIBILITY matrix.

## QUICK CHECK (To determine if FCO has been installed)

Verify presence of VDE power supply, vendor part number 73133111 or higher in 60 hz drives or 73133112 or higher 50 hz drives.

LAST PREVIOUS FCO: RM05-S0012

RELATED OR PREREQUISITE FCO # / MOD #

None

## FCO KIT CHARGES (United States and Canada only)

KIT ITEM	DOCUMENTATION	PARTS	OTHER
	<input type="checkbox"/> FCO <input type="checkbox"/> PRINTS		

Parts charges are as of FCO release date and are subject to change.

PARTS AVAILABILITY DATE: November 1984

LOGISTICS CODING: 6,000 - 190/90 - 500

LOGISTICS REVIEW: *EM Deegan 10/1/84*

QTY PART NUMBER DESCRIPTION

See NOTE 3 under "Notes for FCO RM05-R0014" (Page 4 of 17)

Order by This Number	Kit Contains	
	FCO	Prints Parts
EQ-01254-01	X	X
EQ-01254-02	X	X
FA-04426-01	X	

SPECIAL TEST EQUIPMENT, TOOLS, or SUPPLIES  
(Not included in the Field Retrofit Kit)

Standard Field Service Tool Kit DVM  
(Digital Voltmeter)

## FIELD INSTALLATION and TEST PROCEDURE

See attached REWORK PROCEDURES  
This FCO Incorporates the following ECOs:

- \*RM05-CX014 (Problem/Correction #1)
- \*RM05-CX015
- \*RM05-CX019

Problem/Symptoms: 1. Intermittent Carriage Slam.  
2. Frequent power supply related problems.  
3. Intermittent head unloading, spin down, or drive off line errors.

Compatibility: See Note 2 under "NOTES for FCO RM05-R0014" (page 4 of 17)

APPROVED-Field Service Product Support

Mark Himes *Mark Himes*Libraries: 11  
Mini

APPROVED-Field Service Product Safety

Bob Barnard *Bob Barnard 4-18-84*  
Bob Barnard

FCO RELEASE DATE

12 October 1984

RM05-FCO-3





digital

FCJ PM05-P0014

PAJF 4 JF 11

**COMPATIBILITY - NOTE 2**

This FCJ implements a new keyed AC power cable assembly for the power supply.

**OLD AC POWER CABLE**

Vendor Part Number

70734120 (50 Hz)

70734121 (60 Hz)

**NEW AC POWER CABLE (keyed)**

Vendor Part Number

70734122 (50 Hz)

70734123 (60 Hz)

The new AC power cables may be used with any of the VDF power supplies, but the old AC power cables will not fit into the new VDF power supplies with the vendor part numbers 73133108 and the above. An example of the new "keyed" cable is shown in Figure 3.


**PARTS NEEDED - NOTE 3**

FJ-01254-01 is used only on the affected 50Hz VDF PM05 Drives.

<u>QTY</u>	<u>PART NUMBER</u>	<u>DESCRIPTION</u>
1	29-23889	50 Hz VDF P.S. assy. (CDC P/N 73133112)
1	29-24773	50 Hz AC power cable (CDC P/N 70734122)

FJ-01254-02 is used only on affected 60 Hz VDF PM05 Drives.

<u>QTY</u>	<u>PART NUMBER</u>	<u>DESCRIPTION</u>
1	29-23888	60 Hz VDF P.S. assy. (CDC P/N 73133111)
1	29-24773	60 Hz AC power cable (CDC P/N 70734123)



**FIGURE 3 VDE RM05 AC POWER CABLE**

RM06-FCO-6

digital

This FCO describes the removal and replacement procedure to install the new RM05 VDE power supply (50 Hz or 60 Hz). It also describes the new keyed AC power cable replacing any of the previous revision power supply assemblies and non-keyed AC power cables.

NOTE

It is strongly recommended that the installation of this FCO be performed by RM05 trained Field Service Engineers only.

1. Press the START switch on the operators front panel to stop the drive motor and unload the heads. (See Figure 4)
2. Remove the disk pack.
3. Open the rear door of the RM05 drive cabinet.




FIGURE 4 RM05 OPERATORS PANEL

digital

4. Locate the "MAIN AC" circuit breaker on the power supply control panel and press the circuit breaker down to the "OFF" position (labeled "0"). (See Figure 5)

.....  
● CAUTION ●  
● Disconnect the RM05 AC Power Cord "plug" from the AC ●  
● Power Source Receptacle before proceeding. ●  
● .....  
.....

5. Disconnect the RM05 Main AC Power Cable from the site power source.




FIGURE 5 VDE RM05 POWER SUPPLY CONTROL PANEL

1111111111  
1111111111  
1111111111

FCJ RM05-R0014

PAGE 7 OF 17

6. Carefully disconnect the blower hose from the rear of panel of the power supply assembly. (See Figure 6)
7. Unplug the main AC power cable from the power supply receptacle labeled as AC INPUT. (See Figure 5)




FIGURE 6 RM05 VDE POWER SUPPLY (REAR VIEW)

digital

FCU RM05-R0014

PAGE 8 OF 17

8. Remove the cable clamp that secures the main AC power cable to the top of the power supply. (See Figure 7)
9. Remove the main AC power cable from the power supply. (See Figure 7)
10. Remove the main AC power cable from the drive and put it aside.
11. Note the location of all external cables connected to the power supply and then disconnect all of these cables.




FIGURE 7 RM05 WITH VDE POWER SUPPLY

RM05-FCO-10

digital

FCO RM05-R0014

PAGE 9 OF 17

12. Remove the two (2) 10-24 mounting screws that secure the control panel end of the power supply to the drive chassis. (See Figure 5)
13. Pull the power supply towards the back of the drive cabinet until the flange on the rear of the power supply clears the retaining bracket on the bottom of the drive cabinet. (See Figure 7)
14. Remove the power supply from the drive cabinet.
15. Mount the new power supply assembly (supplied with EQ- for 50Hz or EQ- for 60Hz) into the drive cabinet.

digital

FCO RM05-R0014

PAGE 10 OF 17

16. Slide the new power supply back into the drive until the flange on the rear of the supply slips under the retaining bracket on the bottom of the drive cabinet.
17. Re-install the two (2) 10-24 mounting screws and secure the control panel end of the power supply to the drive cabinet.
18. Re-attach all the external connectors to the power supply assembly (as noted in step 11).
19. Using the cable clamp removed in step 8, attach the NEW keyed AC power cable (supplied in the FCO kit) to the top of the power supply. (See Figure 8)




FIGURE 8 RM05 WITH VDE POWER SUPPLY

RM05-FCO-12

1111111111  
1111111111  
1111111111

FCO RM05-R0014

PAGE 11 OF 17

20. Insert the keyed plug of the new AC power cable into the receptacle labeled AC INPUT on the control panel of the new power supply. (See Figure 9)




FIGURE 9 VDE RM05 POWER SUPPLY CONTROL PANEL

digital

21. Re-connect the blower hose to the "new air plenum" located on the rear panel of the new power supply. (See Figure 10)
22. Re-connect the new main AC power cable to the site power source.




FIGURE 10 VDE RM05 POWER SUPPLY (REAR VIEW)

11111111  
11111111  
11111111

FCO RM05-R0014

PAGE 13 OF 17

23. Raise all of the indicated switches and circuit breakers to their UP position. (See Figure 11)
24. Locate the "MAIN AC" circuit breaker on the power supply control panel and lift the breaker up to the "ON" position (labeled "1"). (See Figure 11)




FIGURE 11 VDE RM05 POWER SUPPLY CONTROL PANEL

digital

FCO RM05-R0014

PAGE 14 OF 17

25. Connect the negative (-) lead of a DVM (Digital Voltmeter) to the GND (ground) test jack on the power supply control panel and verify the following DC voltages. (See Figure 12)
26. Connect the positive (+) lead of the DVM to each of the voltage test jacks on the power supply control panel and verify the following DC voltages. (See Figure 12)

<u>TEST JACK</u>	<u>MEASURED DC</u>	<u>VOLTS</u>
+46	+44 to +51	Volts
-46	-44 to -51	Volts
+20	+18 to +22	Volts
-20	-18 to -22	Volts
+28	+26 to +30	Volts
+9.7	+8.7 to +10.7	Volts
-9.7	-8.7 to -10.7	Volts

27. Disconnect the DVM from the power supply.




FIGURE 12 VDC BIAS POWER SUPPLY CONTROL PANEL

RM05-FCU-16

1111111111  
1111111111  
1111111111

FCJ RM05-R0014

PAGE 15 OF 17

28. Locate the wire-wrapped side of the main logic chassis directly above the power supply. (See Figure 13)
29. Connect the negative (-) DVM lead to one of the GND (ground) tabs on the left edge of the wire-wrapped side of the main logic chassis. (See Figure 13)
30. Connect the positive (+) DVM lead to Pin A2JD94-04A on the wire wrapped side of the main logic chassis. (See Figure 13)




FIGURE 13 RM05 MAIN LOGIC CHASSIS (WIRE WRAPPED SIDE)

RM05-FCO-17

00000000  
01111111  
00000000

FCO RM05-R0014

PAGE 16 OF 17

31. Adjust the bottom potentiometer of the +/- 5 volt DC regulator card on the card side of the main logic chassis until the DVM reads between +5.05 and -5.15 volts DC. (see Figure 14)
32. Connect the positive DVM lead to Pin A2JD94-01A on the wire wrapped side of the logic chassis. (See Figure 13)
33. Adjust the top potentiometer of the +/- 5 volt DC regulator card on the card side of the main logic chassis until the DVM reads between -5.05 and -5.15 volts DC. (See Figure 14)
34. Disconnect the DVM from the main logic chassis.
35. Close the rear door of the drive cabinet.
36. Prepare the drive for return to Online operation.
37. Install a scratch pack and close the pack access cover.




FIGURE 14 RM05 MAIN LOGIC CHASSIS (CARD SIDE)

RM05-FCO-18

digital

FCO RM05-R0014

PAGE 17 OF 17

38. Press the start button on the drive operator panel. (See Figure 15)
39. Verify that the drive "READY" lamp illuminates in approximately 20-30 seconds. (See Figure 15)
40. Verify that the FAULT lamp does not illuminate and that no FAULT condition exists. (Figure 15)
41. Verify that the drive operation using any of the available diagnostics on the site. Thirty (30) minutes run time should be sufficient.
42. Log installation of this FCO into the Digital Site Management Guide.




FIGURE 15 RM05 OPERATORS PANEL

RM05-FCO-19




10-Nov-1986  
RM05-INDEX.A  
REV A

MICROMEDIA PUBLISHING

Tech Tip Index

Tech Tip Number	REV	Rel. Date	SB#	Title
-RM05--TT-01	0	28-Jul-80		RM02/3/5/80 Model Compatibility
-RM05--TT-02	0	28-Jul-80		RM02/3/5/80 MBA Backplane
-RM05--TT-03	0	2-Dec-80		RM02/3/5/80 Dual Port
-RM05--TT-04	0	19-Mar-81		Poor MASSBUS Cable ZIP Connection
-RM05--TT-05	0	19-Mar-81		ARL Module Guidelines
-RM05--TT-06	0	1-Jun-81		Speed Sensor Assy Adjustment Hazd
-RM05--TT-07	A	8-Feb-82		RM05 Vibration Problem
-RM05--TT-08	A	23-Mar-82	223	Handling Information
-RM05--TT-09	A	22-Feb-82		RM02/3/5 Alt Head Alignment Proc
-RM05--TT-10	A	18-Jul-81		Exclusive or Gate Error
-RM05--TT-11	A	11-Feb-82		Leaky Spindle Motor Capacitor
-RM05--TT-12	A	29-Apr-82	229	Pack/Head Cleaning
-RM05--TT-13	A	29-Apr-82	230	CE Pack Orientation
-RM05--TT-14	A	17-May-82	233	Power Problems
-RM05--TT-15	A	17-May-82	233	Velocity Transcender Replacement
-RM05--TT-16	A	17-May-82	233	Pack Seal Adjustment
-RM05--TT-17	A	17-May-82	233	Head Crashes
-RM05--TT-18	A	12-Oct-82	253	RM Adapter Cabling Problem
-RM05--TT-19	A	30-Oct-82		A/B Cable Shorting
-RM05--TT-20	A	29-Mar-83	275	Pack Trim Shield Labels
-RM05--TT-21	A	11-Apr-83	276	Velocity Transducer Servicing
-RM05--TT-22	A	3-Jan-84	314	Data Errors Due To Runout
-RM05--TT-23	A	24-Mar-84	325	EVRDA Rev 4.1 Problem
-RM05--TT-24	A	16-Apr-84	329	AC Power Cables for VDE Power Sup
-RM05--TT-25	A	15-May-84	332	Power Supply Failures
-RM05--TT-26	A	3-Jan-85	363	RM Adapter Power Supply Caution
-RM05--TT-27	A	8-Aug-85	394	RM05 Re-Skidding
-RM05--TT-28	A	2-Oct-85	402	CPX Head Inspection Tool Kit
-RM05--TT-29	A	6-Jun-86	434	Absolute Air Filter Springs
-RM05--TT-30	A	10-Nov-86	456	Diagnostic CZRMPBO.BIC Failure

RM05-TT-1

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM05

Title RM02/03/05/80 Module Compatibility				Tech Tip Number RM05-TT-1	
Author Greg Ekholm		FS Office Colo Spgs.		Date 7/15/80	Revision 0
Processor Applicability			Mgr /Sup		Date
All 11 VAX 20			Approval <i>Greg Ekholm</i>		Date 7/28/80
					Cross Reference RM02/03-TT-27

THIS TECH TIP FOR CROSS REFERENCE ONLY.

**DEC CONFIDENTIAL**


This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page 1	Page Revision 0	Publication Date August 1980
--------	-----------------	------------------------------

PRINTED IN U.S.A.

EN 1180C 12 R277 (78V)

RM05-TT-2

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM05

Title <b>RM02/03/05/80 MBA Backplane</b>				Tech Tip Number <b>RM05-TT-2</b>	
Author <b>Greg Ekholm</b>		FS Office <b>Colo. Spgs.</b>		Date <b>7/15/80</b>	
Processor Applicability		Mgr /Sup		Date	
All		Approval <i>Greg Ekholm</i>		Date <b>7/20/80</b>	
				Revision <b>0</b>	
				Cross Reference	
				<b>RM02/03-TT-29</b>	


THIS TECH TIP FOR CROSS REFERENCE ONLY.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>2</b>	Page Revision <b>0</b>	Publication Date <b>August 1980</b>
---------------	------------------------	-------------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	RM05

Title RM02/03/05/80 Dual Port				Tech Tip Number RM05-TT-3	
Author Greg Ekholm		F. S. Office Colorado Springs Date 12/2/80		Revision	
Processor Applicability		Mgr /Sup BOB DAVISON Date 12/12/80		Cross Reference	
All	11	10	20	VAX	Approval <i>Greg Ekholm</i> Date 12/2/80
				RM02/03-TT-32	

This tech tip for cross reference only.

**DEC CONFIDENTIAL**


This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip see Administration Tech Tip Number 2.

Page 3	Page Revision 0	Publication Date December 1980
--------	-----------------	--------------------------------

PRINTED IN U.S.A.

EN 1188C 12 R277 (79V)

RM05-TT 4

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM05
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title Poor MASSBUS Cable Zif Connecting			Tech Tip Number RM05-TT-5 <sup>4</sup>		
Author Greg Ekholm		F S Office Colorado Springs Date 3/16/81		Revision 0	
Processor Applicability			Mgr /Sup		Cross Reference
All	11a	VAX	Approval <i>Greg Ekholm</i>	Date 7/11/81	RM02/03-TT-3636

This tech tip for cross reference only.

**DEC CONFIDENTIAL**


This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 4	Page Revision 0	Publication Date March 23, 1981
--------	-----------------	---------------------------------

PRINTED IN U S A

EN 1180C 12 R277 78V

RM05-TT-5

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM05
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title <b>ARL Module Guidelines</b>			Tech Tip Number <b>RM05-TT-5</b>		
Author <b>Greg Ekholm</b>		F S Office <b>Colorado Springs</b>		Date <b>3/16/81</b>	
Revision <b>0</b>		Mgr /Sup		Date	
Processor Applicability		Approval <i>Greg Ekholm</i>		Date <b>3/16/81</b>	
All		Cross Reference		<b>RP05/06 - TT -54</b>	
<b>11d</b>	<b>VAX</b>				

This tech tip for cross reference only.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>5</b>	Page Revision <b>0</b>	Publication Date <b>March 23, 1981</b>
---------------	------------------------	--

PRINTED IN U.S.A.

<b>digital</b>	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM05
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title <b>Speed Sensor Assembly Adjustment Hazard</b>			Tech Tip Number <b>RM05-TT-6</b>		
Author <b>Kathy McGuire</b>		F S Office <b>CX</b>	Date <b>06-01-81</b>		Revision
Processor Appl cabil ty		Mgr Sup <i>J. Sweeney</i>	Date <i>7/31/81</i>		Cross Reference
All <b>11/70</b>	<b>11/750</b>	<b>11/780</b>	Approval <i>Kathy McGuire</i>	Date <b>06-01-81</b>	

This technical tip is to inform all field engineers of a possible hazard which may be encountered while doing a speed sensor assembly adjustment / replacement.

On the bottom of the spindle pulley is mounted a steel pin which passes over the speed sensor pickup. **NEVER** place a screwdriver, your finger, or any other object in this area while the spindle is turning. Doing so may cause damage to the spindle pin, speed sensor, or yourself.

See Figure 1 (attached).

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page <b>6</b>	Page Revision <b>0</b>	Publication Date <b>July 31, 1981</b>
---------------	------------------------	---------------------------------------

PRINTED IN U.S.A.

Title <b>Speed Sensor Assembly Adjustment Hazard</b>			Tech Tip Number <b>RM05-TT-6</b>	
Author <b>Kathy McGuire</b>	FS Office <b>CX</b>	Date <b>06-01-81</b>	Revision	
Processor Appl. cablity	Mgr. Sup <b>J Siciemsky</b>	Date <b>07-30-81</b>	Cross Reference	
AN	Approval <b>Kathy McGuire</b>	Date <b>06-01-81</b>		





FIGURE 1 SENSOR ASSEMBLY ADJUSTMENT

DEC CONFIDENTIAL  
 This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only.  
 For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page <b>7</b>	Page Revision <b>B</b>	Publication Date <b>July 31, 1981</b>
---------------	------------------------	---------------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM05
	12 Bit <input checked="" type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input checked="" type="checkbox"/>	36 Bit <input checked="" type="checkbox"/>	

Title <b>RM05 Vibration Problem</b>			Tech Tip Number <b>RM05-TT-7</b>		
Author <b>D.C. Waterman</b>		FS Office <b>Kansas City</b>		Date <b>5/14/81</b>	
Revision <b>A</b>		Processor Applicability		Cross Reference	
All <input checked="" type="checkbox"/> VAX		PSG <i>Fran Lushan</i>		Date <i>2/1/82</i>	
		CSSE <i>Loy Decker</i>		Date <i>2/8/82</i>	

The RM05's are presently being shipped with metal feet. The drive has a tendency to walk and the resultant vibration causes modules to shake loose. This cause many intermittent problems.

Placing rubber cups under the metal feet will cure this problem.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>8</b>	Page Revision <b>A</b>	Publication Date <b>FEBRUARY 1982</b>
---------------	------------------------	---------------------------------------

PRINTED IN U.S.A.

<b>digital</b>	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input type="checkbox"/> 18 BH	<input type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category SYS EMS
Title RM05 HANDLING INFORMATION					Tech Tip No. RM05-TT- .	
Processor Applicability ALL			Cross Reference		Tech Tip Rev A	Page 1 of 1
Author FIELD SERVICE PRODUCT SAFETY			Mgr./Supv. Approval LOUIS CARPENITO <i>LC</i>			
Location PK3-2		Mail Stop S99		Date 13 MAR 82		
CSSE Approval SKIP DALTON				Date 23 MAR 82		
PSG Approval ED MALONE				Date 23 MAR 82		

## CAUTION!!

DURING SHIPMENT THE RM05 IS BANDED ONLY AND NOT BOLTED TO THE SKID. ONCE THE SHIPPING BANDS ARE REMOVED THE RM05 SHOULD NOT BE TRANSPORTED AROUND ON ITS SKID. IF IT IS NECESSARY TO TRANSPORT THE RM05 AROUND IT MUST EITHER BE REMOVED FROM THE SKID OR REBANDED TO THE SKID.

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation. For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 4	Page Revision .	Publication Date MARCH 1982
------------------	--------------------	--------------------------------

0-700-00000

RM05-TT-10

<b>digital</b>	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM05
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	32 BIT <input checked="" type="checkbox"/>	36 Bit <input type="checkbox"/>	SYSTEMS

Title RM02/03/05 ALTERNATE HEAD ALIGNMENT PROCEDURE			Tech Tip Number RM05-TT-9	
Author TOM TOBIASSEN		F.S Office COLO.SPRINGS	Date 17 FEB 82	Revision A
Processor Applicability		CSSE LOYD ZUCHANAN <i>LD</i>	Date 17-MAR-82	Cross Reference RM03-TT-47
All X	1's	PSG FRAN LINNEHAN <i>FL</i>	Date 22 FEB 82	RM02-TT-47

Subject Alternate head alignment procedure for RM02/03/05's

This can be done with or without the HFSV (head align card).  
With the HFSV card the results will equal alignment done  
with a field test unit (FTU).

Enter into memory  
starting at

Location	200	000005 012737 000000 176710	Reset Select unit 0
	210	012737 000021 176700	Set VV
	216 220	000005 012737 177400 176702	Reset Set WC
	226	012737 002000 176704	Set BA
	234	013737 177570 176706	Select Head
	242	012737 000365 176734	Set DCA=365g
	250	012737 000071 176700	Do Read Data
	256	105737 176700	TSTB for Ready
	262 264	100375 000137 000216	BPL to TSTB Jump to 216 and do it again

Page 1 of 2

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only.  
For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 10	Page Revision A	Publication Date APRIL 1982
---------	-----------------	-----------------------------

PRINTED IN U.S.A.

EN-011000 12 R1270(70Y)

RMCE 11-11

Title RM02/03/05 ALTERNATE HEAD ALIGNMENT PROCEDURE		Tech Tip Number RM05-TT-9	
Author TOM TOBIASSEN	F S Office COLO.SPRINGS	Date 17 FEB 82	Revision A
Processor Applicability		CSSE LOYD BUCHANAN <i>LB</i> Date 17 MAR 82	Cross Reference RM03-TT-47
All x   11	PSG FRAN LINNEHAN <i>FL</i>	Date 22 FEB 82	RM02-TT-47

Instructions:

1. With the drive powered off, place the HFSV card in the drive logic chassis at location A02 on RM02/03 and A16 on RM05's. Insert LAP 0 into drive. If you are not using the HFSV card goto step 5.
2. Install the head alignment cable between the drive logic chassis and the jack on the card in the read/write chassis as specified in the appropriate disk subsystem user's guide. Use your DVM in place of the FTU meter.
3. Power up the drive and install a CE Pack. Enter the toggle program at location 200, load address 200 and press start with SWR = 0. Heads will seek to cyl 24510 and you are ready for head alignment on head #0.
4. To select another head, raise the switches on the console to correspond to the desired head. On 1170 with RDC console, press ctrl P to get in console mode. 1W writes a 1 into the SWR, change the value 1 to ? for another head selection.

```

15  14 13 12  11 10 09  08 07 06  05 04 03 02 01 00
*   * *  HD  HD HD HD  HD * *  * * * * * *
      16  08 04 02  01
      x   x

```

First line = Switch      Second line = value calculated by adding values in line 3.

Note: x - not used by RM02/03

5. For head alignment without the HFSV card place scope probes as shown below. J104 on the read amp card A3A03. Align the head for equal simitry of the dibit pattern shown in the user guides. This is an emergency procedure and should be done using the HFSV card as soon as possible.

Goto step 3.

J104



Page 2 of 2

DEC CONFIDENTIAL


This document is proprietary to Digital Equipment Corporation and is intended for use by its Field-Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 11	Page Revision A	Publication Date APRIL 1982
---------	-----------------	-----------------------------

PRINTED IN U.S.A.

EN-011000-12-R1270(70Y)

RM05-TT-12

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM05
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	SYSTEMS

Title EXCLUSIVE OR GATE ERROR			Tech Tip Number RM05-TT- 10	
Author LOYD BUCHANAN		F S Office COLORADO	Date 23 FEB 81	Revision A
Processor Applicability		CSSE GREG EKHOLM	Date 24 FEB 81	Cross Reference RM02-TT- 49 RM03-TT- 49
All <input checked="" type="checkbox"/>	<input type="checkbox"/>	PSG FRAN LINNEHAN	Date 18 JUL 81	

The RM02, RM03, and RM05 prints are in error on drawing exclusive OR gates. Referring to cross references 164 and 165 in the RM02 and RM03 prints, C.D.C. has shown the 149H gates as exclusive NOR gates. The manufacturer's data sheet lists the 7486 and the 3021 gates as exclusive OR's. Erasing the inversion bubbles on the outputs does make the logic work properly.

This logic appears on cross references 124 and 125 of the RM05 prints.

**DEC CONFIDENTIAL**


This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 12	Page Revision A	Publication Date APRIL 1982
---------	-----------------	-----------------------------

PRINTED IN U.S.A.

EN-011000-12-R1270(70Y)

RMCE-TT- 13

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM05
	32 BIT <input type="checkbox"/>	16 Bit <input type="checkbox"/>	18 Bit <input type="checkbox"/>	38 Bit <input checked="" type="checkbox"/>	SYSTEMS

Title LEAKY SPINDLE MOTOR CAPACITOR				Tech Tip Number RM05-TT-11	
Author FRAN LINNEHAN		F.S Office MAYNARD	Date 11 FEB 82	Revision A	
Processor Applicability		CSSE SKIP DALTON	Date 2 MAR 82	Cross Reference	
All <input checked="" type="checkbox"/>	<input type="checkbox"/>	PSG ED MALONE	Date 11 FEB 82		

On DEC 9766 50Hz drives, if the drive motor has a date code of F813, G813, or H813 and with the run capacitor ground wire soldered to the capacitor, the capacitor and wire should be replaced. this effects BK7B1F and BK7B1F drives only (RM05).

Listed is the suggested procedure for checking the run capacitor on the DEC version 9766 drive motors.

Procedure:

1. Power down drive.
2. Gain access to drive motor from the left side of the drive (as facing drive).
3. Locate capacitor cover opposite from motor power wires and remove cover.

Caution: Capacitor May be charged.

4. Check to determine whether the ground wire is soldered to the capacitor case or is attached via quick connector.
5. If the ground is a quick connect attachment, no rework is necessary.
  - 5.1 Replace cover on drive motor and return to customer.
6. If soldered:
  - 6.1 Contact Fran Linnehan, Corporate Product Support Group, PK3-2/K11, DTN: 223-8855 or ( 617 ) 493-8855 for parts and rework instructions

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page 13	Page Revision A	Publication Date APRIL 1982
---------	-----------------	-----------------------------

PRINTED IN U.S.A.

EN 1180C 12 R277 (78V)

RM06 TT-14

<b>digital</b>	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM05
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	32 BIT <input checked="" type="checkbox"/>	36 Bit <input type="checkbox"/>	SYSTEMS

Title <b>RM05 PACK/HEAD CLEANING</b>			Tech Tip Number <b>RM05-TT-12</b>	
Author <b>A. GROVER</b>		F S Office	Date <b>3 JUN 81</b>	Revision <b>A</b>
Processor Applicability		CSSE DENNIS SHAW	<del>3 JUN 81</del> <b>4-16-82</b>	Cross Reference
All	11 VAX	PSG ED MALONE	Date	

THE FOLLOWING IS A RECOMMENDATION FROM DISK ENGINEERING/MAINTAINABILITY -

"BECAUSE OF THE LOW FLYING HEIGHT OF RM05 HEADS NEITHER HEADS NOR PACKS SHOULD BE CLEANED".


A PROCEDURE TO DETERMINE IF A HEAD NEEDS REPLACING IS TO BE FOUND IN THE "RM05 DISK SUBSYSTEM MAINTENANCE MANUAL" PARA. 4.7.

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page <b>14</b>	Page Revision <b>A</b>	Publication Date <b>MAY 1982</b>
----------------	------------------------	----------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECHNICAL MANUAL</b>				Option or Designator RM05
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	32 BIT <input checked="" type="checkbox"/>	36 Bit <input type="checkbox"/>	SYSTEMS

Title <b>RM05 CE PACK ORIENTATION</b>			Tech Tip Number <b>RM05-TT-13</b>		
Author <b>J. WHITFIELD</b>		F S Office <b>UK REGION</b>		Date <b>20 OCT 81</b>	Revision <b>A</b>
Processor Applicability		CSSE DENNIS SHAW		Date <b>4-16-82</b>	Cross Reference
All		VAX 11		PSG ED MAIONE	Date <b>4 29-82</b>

THE FOLLOWING IS A LIST OF THE VARIOUS ALIGNMENT TRACKS ON THE RM05 CE PACK AND THEIR USES.

CYLINDER ADDRESS

<u>DECIMAL</u>	<u>OCTAL</u>	<u>USED FOR</u>
491	753	HEAD ALIGNMENT
5	5	SERVO OFFSET
4	4	" "
800	800	" "


NOTE: THEY ARE NOT THE SAME AS THE RM02/03

**DEC CONFIDENTIAL**

This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only. For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page <b>15</b>	Page Revision <b>A</b>	Publication Date <b>MAY 1982</b>
----------------	------------------------	----------------------------------

PRINTED IN U.S.A.

	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input checked="" type="checkbox"/> 18 BH	<input type="checkbox"/> 32 BH	<input type="checkbox"/> 36 BH	Category SYSTEMS
Title RM05 Power Problems					Tech Tip No RM05-TT-14	
Processor Applicability 1 1 1 V A X			Cross Reference N/A		Tech Tip Rev A	Page 1 of 1
Author W. L. Robertson				Mgr/Supv Approval N/A		
Location Charlotte			Mail Stop CE		Date 3-17-82	
CSSE Approval Dennis Shaw					Date 5-21-82	
PSG Approval					Date	



The rectifier and capacitor board (YEN) may fail in such a manner that regulator chips on both the E01 card (read/write control) 10.5V regulator (VR14) and the E03 card (read amp) 6V regulator (VR22) may be damaged. When replacing the YEN card, if the voltage checks in the service manual are o.k. and the drive is getting DTEs (drive timing errors) or the tester is getting address errors check the output of these regulators. 6V reg VR22 (E03) is located on drawing cross ref. 632. 10.5V reg VR14 (E01) is located on drawing cross ref. 612. The above voltages are not monitored and will not cause a voltage fault.

FOR INTERNAL USE ONLY. This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 16	Page Revision A	Publication Date MAY 1982
-------------------	--------------------	------------------------------

14-0100-12 00007000

RM05-TT-17

[ ]	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05
	- 12 BH	x 16 BH	- 18 BH	x 32 BH	36 BH	Category SYSTEMS
Title VELOCITY TRANSDUCER REPLACEMENT					Tech Tip No. RM05-TT-15	
Processor Applicability 11/780 11/750			Cross Reference N/A		Tech Tip Rev A	Page 1 of 1
Author Dan Edgell				Mgr/Supv Approval N/A		
Location CINCINNATI			Mail Stop CY		Date N/A	
CSSE Approval Dennis Shaw						Date 5-21-82
PSG Approval 				Date 5-21-82		

When removing and/or replacing a velocity transducer assembly in a RM05, follow the procedure exactly as described in the "RM05 Service Manual" (EK-ORM05-SV-002 Page 4-81).


In the instances when the transducer was replaced or handled improperly, the problem symptom was that the RM05 was unable to perform seeks above cylinder 1200 (octal).

FOR INTERNAL USE ONLY This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 17	Page Revision A	Publication Date MAY 1982
-------------------	--------------------	------------------------------

14-01280-1 (02/82)


RM05 TT 18

	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05
	<input type="checkbox"/> 12 BH	<input type="checkbox"/> 16 BH	<input type="checkbox"/> 18 BH	<input type="checkbox"/> 32 BH	<input type="checkbox"/> 36 BH	Category SYSTEMS
Title Pack Seal Adjustment					Tech Tip No RM05-TT-16	
Processor Applicability All			Cross Reference N/A		Tech Tip Rev A	Page 1 of 1
Author Ron Hruby				Mgr Supv Approval N/A		
Location Parker Street			Mail Stop PK3-2/K11		Date 4-29-82	
CSSE Approval Dennis Shaw				Date 5-21-82		
PSG Approval				Date		

It has been found that a lot of head crashes can be attributed to air seal leaks. The following procedure should rectify this problem.

This can be checked by noting the drag on a sheet of paper as it is pulled out from between the closed pack access cover, and the shroud assembly. The amount of drag should be even around the seal. Adjust if necessary, by moving the front catch on the shroud up or down until the pack access cover latches tightly enough to provide an air tight seal. This adjusts the sides and front of the pack access cover.


NOTE: Because of the use of paper to check seal, you must purge pack for at least 15 minutes.



FOR INTERNAL USE ONLY This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip see Administration Tech Tip Number 2

Page Number 18	Page Revision A	Publication Date MAY 1982
-------------------	--------------------	------------------------------

RM05 TT 19

	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05
	<input checked="" type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input checked="" type="checkbox"/> 18 BH	<input type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category SYSTEMS
Title RM05 HEAD CRASHES					Tech Tip No RM05-TT-17	
Processor Applicability A   L   L			Cross Reference N/A		Tech Tip Rev A	Page 1 of 3
Author Ron Hruby				Mgr Supv Approval N/A		
Location Parker Street			Mail Stop PK3-2/K11		Date 5-14-82	
CSSE Approval Dennis Shaw				Date 5-21-82		
PSG Approval				Date		

Due to the very low flying height of the heads and the critical characteristics of the RM05 packs, it is recommended that if a head crash is experienced, you should replace all the heads in the drive. There is no way you can determine with the unaided eye whether or not the remaining heads are good or not. This requires a microscope and a thorough knowledge of head construction.

In the event of a crash, the following steps should be taken:



1. Because the RM05 uses a perforated shroud assembly, you must disassemble the shroud and clean the deck area very thoroughly. Some repeat crashes have been attributed to contamination left in the drive from the original crash.
2. Take no chances. Replace every head when reassembling the drive. Visually inspect each head for signs of improper assembly or contamination before installing.
3. Inspect the positioner and magnet for metal particles. BE THOROUGH IN EVERY RESPECT.
4. When drive is reassembled, allow the drive to purge for a minimum of 30 minutes. Visually inspect the shroud area before installing a new scratch pack.
5. When the pack has spun up for a few minutes and things look stable, you can then proceed with the head alignment procedures.
6. Complete the attached form and forward it to:

Ron Hruby  
SSG Product Support Group  
129 Parker Street PK3-2/K11  
Maynard, MA 01754

FOR INTERNAL USE ONLY This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 19	Page Revision A	Publication Date MAY 1982
-------------------	--------------------	------------------------------

HM05-TT-20

	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05
	x 12 BH	x 16 BH	x 18 BH	x 32 BH	x 36 BH	Category SYSTEMS
Title RM05 HEAD CRASHES (continued)					Tech Tip No RM05-TT-17	
Processor Applicability A   L   L			Cross Reference N/A		Tech Tip Rev A	Page 2 of 3
Author Ron Hruby				Mgr Supv Approval N/A		
Location Parker Street			Mail Stop PK3-2/K11		Date 5-14-82	
CSSE Approval Dennis Shaw						Date 5-21-82
PSG Approval						Date

Due to the "Burnished media" technology used on these packs, the normal pack cleaning procedures tend to leave a residue on the platter surfaces. The media requires a special power wash cycle to insure that all the residue is removed. Again, only a keen eye trained to recognize a media defect can spot a problem by inspecting a pack. CDC recommends a program of media inspection at certain intervals but will not recommend any cleaning. Therefore, a clean environment and proper storage of media to prevent pack contamination is strongly suggested.


The maintainability group for the RM05 needs to have more complete reporting of RM05 head crashes. It has been found that some RM05 calls, especially if they are repeat crashes, have been reported on LARS against systems. This makes accurate performance statistics difficult at best. The last page of this Tech-Tip is a reporting format which should be used in every instance of a RM05 head crash until further notice. Send the completed form to: Ron Hruby; SSG Product Support Group, PK3-2/K11. We will appreciate your assistance in this very much.

Until the head crash problem has been resolved, we recommend that all branches have their RM05 CE and scratch packs inspected at least once a month by a trained field engineer. This is necessary to eliminate the possibility that our test packs may be a source of contamination.

FOR INTERNAL USE ONLY This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip see Administration Tech Tip Number 2

Page Number 20	Page Revision A	Publication Date MAY 1982
-------------------	--------------------	------------------------------

RM05-17 21

	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05
	<input checked="" type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input checked="" type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category SYSTEMS
Title RM05 HEAD CRASHES (Continued)					Tech Tip No RM05-TT-17	
Processor Applicability A   L   L			Cross Reference N/A		Tech Tip Rev A	Page 3 of 3
Author Ron Hruby				Mgr Supv Approval N/A		
Location Parker Street			Mail Stop PK3-2/K11		Date 5-14-82	
CSSE Approval Dennis Shaw					Date 5-21-82	
PSG Approval					Date	

PLEASE USE THIS FORM TO DOCUMENT RM05 HEAD CRASHES FOR  
MAINTAINABILITY ENGINEERING IN COLORADO.

\*\*\*\*\*

Branch Office \_\_\_\_\_ Cost Center \_\_\_\_\_

Customer Name \_\_\_\_\_ LARS Log # \_\_\_\_\_

RM05 Serial # \_\_\_\_\_ Pack Serial # \_\_\_\_\_

Date of failure \_\_\_\_\_ Date of installation \_\_\_\_\_

Hour Meter reading \_\_\_\_\_ Head #s (loc) that actually crashed \_\_\_\_\_

\_\_\_\_\_

Site Environment \_\_\_\_\_

Suspected Cause \_\_\_\_\_

Name of Engineer \_\_\_\_\_ Telephone # \_\_\_\_\_

Additional comments: \_\_\_\_\_

\_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_

Send to: Ron Hruby  
SSG Product Support  
129 Parker Street, PK3-2/K11  
Maynard, MA 01754


FOR INTERNAL USE ONLY: This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 21	Page Revision A	Publication Date MAY 1982
-------------------	--------------------	------------------------------

	<b>FIELD SERVICE TECH TIP</b>				Option Designator RM05
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input type="checkbox"/> 36 BH
Title RM ADAPTER CABLING PROBLEM					Tech Tip No RM05-TT-18
Processor Applicability 11 VAX			Cross Reference N/A		Tech Tip Rev A
Author Richard Mautz			Mgr/Supv. Approval <i>Donald Mullin</i>		
Location Santa Monica, CA		Mail Stop LX0		Date 9/8/82	
CSSE Approval DENNIS SHAW <i>[Signature]</i>			Date 10-4-82		
PSG Approval DON DAVIS <i>[Signature]</i>			Date 10/12/82		

A problem exists between the AMP connector on the M7684 (J1) of the RM adapter, and its corresponding cable from the RM05 transition bracket. The problem is that the cable connector plug is narrower than the mating AMP socket on the M7684 (J1) board. This can result in the cable being plugged in two pins off. The proper connection of the cable is with all pins of J1 mated with the cable plug.

INCORRECT RESULT:





FOR INTERNAL USE ONLY This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2


Page Number 22	Page Revision A	Publication Date OCTOBER 1982
-------------------	--------------------	----------------------------------

4-108 2 3000 12

RM05 TT 22

[ ]	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05	
	<input type="checkbox"/> 12 BN	<input checked="" type="checkbox"/> 16 BN	<input type="checkbox"/> 18 BN	<input type="checkbox"/> 32 BN	<input type="checkbox"/> 36 BN	Category Systems	
Title RM05 A/B Cable Shorting					Tech Tip No. RM05-TT-19		
Processor Applicability A   L   L			Cross Reference N/A		Tech Tip Rev A		Page 1 of 1
Author Mark Himes				Mgr./Supv. Approval N/A			
Location CX01-1			Mail Stop N27		Date 30-DEC-82		
CSSE Approval Dennis Shaw 					Date 30-DEC-82		
PSG Approval DON DAVIS 					Date 30 Dec 82		

The new FCC shielded A/B cable (p/n 70-19688-15) may cause shorting to the RM05 MBA. Specifically, the end of the 26-pin "B" cable that plugs into J1 of the M7687 module in the MBA, may have "exposed" shielded braid within the cable "window" of the berg connector as shown by area # 1 below.



Cables with exposed shield in this area (#1) can cause shorting of etches on the M7687 when installed. These cables should NOT be reworked in the Field as cable damage could result. Covering the exposed area with tape is also NOT acceptable since you will only be prolonging the problem. You may tape the exposed braid on an existing cable ONLY AS AN INTERIM TO REPLACEMENT. The best solution is replacement of the cable with a reworked Rev "A" cable.


The new FCC approved A/B cables that are now being manufactured or "reworked" to Rev "A" will have moved the exposed portion to either area #2 of the cable (shown above) or completely concealed within the berg housing itself, either condition of which is acceptable. New shipments of MBA assemblies will have a round red sticker on the back of the MBA chassis denoting that the A/B cable has been checked or re-worked to revision "A" for this condition.

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 23	Page Revision A	Publication Date JANUARY 1983
-------------------	--------------------	----------------------------------

01-0100-10-0000700

HM0E-17-24

		<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05	
		<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input checked="" type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category SYSTEMS	
Title RM05 Pack Trim Shield Labels						Tech Tip No. RM05-TT-20		
Processor Applicability A L L			Cross Reference N/A			Tech Tip Rev A	Page 1 of 1	
Author Mark Himes <i>Mark Himes</i>				Mgr Supv Approval Dennis Shaw <i>Dennis Shaw</i>				
Location CX CSSE			Mail Stop CX01-1/N27			Date 18-Mar-83		
CSSE Approval Dennis Shaw <i>Dennis Shaw</i>						Date 18 MAR 83		
PSG Approval FRAN LINNEHAN <i>Fran Linnehan</i>						Date 29-MAR-83		

RM05 packs frequently contain a white mylar blank label (item A in Fig 1). It is provided as a customer convenience item by pack vendors and serves no other useful purpose.

These labels are prone to release from the trim shield during spin-up cycles and could seriously damage the drive and/or heads.

CSSE and Engineering advise these labels be removed from all existing and new packs prior to installation into a drive.

An ECO is being written to have these plastic labels excluded from all future packs.







FIG 1, DISK PACK COMPONENTS

FOR INTERNAL USE ONLY This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 24	Page Revision A	Publication Date MARCH 1983
-------------------	--------------------	--------------------------------

14-0100-12 000700

HMC5-TT-25

	<b>FIELD SERVICE TECH TIP</b>				Option Designator RM05
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH
Title RM05 VELOCITY TRANSDUCER SERVICING					Tech Tip No. RM05-TT-21
Processor Applicability 11, 19 VAX			Cross Reference N/A		Tech Tip Rev A
Author TOM TOBIASSEN			Mgr./Supv. Approval N/A		
Location COLORADO SPRINGS		Mail Stop CX01-1/N27		Date 18 FEB 83	
CSSE Approval DENNIS SHAW 				Date 31 MAR 83	
PSG Approval FRAN LINNEHAN 				Date 11-APR-83	

While servicing the velocity transducer in the RM05, care should be used NOT to remove the transducer core from the transducer coil housing.

If you remove the core from the housing, you may electrically damage the transducer causing SKI's, HCE's, etc. and requiring it's replacement.


Both parts should always be removed, installed and handled with the core inside the coil.

This is not clear in the RM05 Service Manual, paragraph 4.33, and should be noted.

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 25	Page Revision A	Publication Date APRIL 1983
-------------------	--------------------	--------------------------------

RM05-TT 26

		<b>FIELD SERVICE TECH TIP</b>				Option Designator RM05
		<input type="checkbox"/> 12 BN	<input checked="" type="checkbox"/> 16 BN	<input type="checkbox"/> 18 BN	<input checked="" type="checkbox"/> 32 BN	<input checked="" type="checkbox"/> 36 BN
Title DATA ERRORS DUE TO RUNOUT					Tech Tip No. RM05-TT-22	
Processor Applicability 11's & 20's VAX			Cross Reference RM02-TT-57 RM03-TT-58		Tech Tip Rev A	Page 1 of 1
Author MARK LICATA				Mgt. Supv. Approval <i>Ronald G. Chen</i>		
Location CHICAGO PRODUCT SUPPORT			Main Shop RLO ROLLING MEADOWS, IL		Date 18 AUG 1983	
CSSE Approval <i>Ron Mullen</i>					Date 3 JAN 1984	

**PROBLEM**            EXCESSIVE DATA PROBLEMS DUE TO INABILITY OF CARRIAGE TO FOLLOW OUT OF ROUND SPINDLE OR PACK DURING FINE MODE.


**SYMPTOMS**            IF YOU ARE EXPERIENCING OFF CYLINDER FAULTS OR EXCESSIVE DATA ERRORS THE CAUSE COULD BE EXCESS RUNOUT OF THE PACK OR SPINDLE. THE RM POSITIONER HAS TO DRIFT OFF CYLINDER IN FINE MODE FOR MORE THAN 800 MICROSECONDS TO ACTUALLY FLAG AN OFF CYLINDER FAULT. IF THE POSITIONER DRIFTS BECAUSE OF PACK OR SPINDLE OUT OF ROUNDNESS FOR LESS THAN 800 MICROSECONDS, NO POSITIONER ERROR OR FAULT IS DETECTED. AT 3600 RPM'S A SECTOR IS ONLY 520 MICROSECONDS, SO A WHOLE SECTOR COULD BE READ OR WRITTEN OFF CYLINDER WITH NO INDICATION OF A RUNOUT PROBLEM.

**SOLUTION**            LOAD HEADS AND SCOPE RUNOUT AT G' EN TEST POINT TO DETERMINE IF SPINDLE AND PACK ARE WITHIN GUIDELINES. WHEN TAKING READINGS ROTATE PACK 90 DEGREES 4 SEPARATE TIMES, THEN LOOK AT ALL READINGS TO DETERMINE STATUS.

	<u>RUNOUT TEST POINT</u>	<u>MAX SPEC P-PEEK</u>	<u>INDEXTRIGGER</u>
RM02/03	A2A08 TPF	1.0 VP-P	A2B08 TPC
RM05	A2A19 TPC	400 MVP-P	A2A06 TPC

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation. For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 26	Page Revision A	Publication Date JANUARY 1984
-------------------	--------------------	----------------------------------

	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05
	<input type="checkbox"/> 12 BIT	<input type="checkbox"/> 16 BIT	<input type="checkbox"/> 18 BIT	<input checked="" type="checkbox"/> 32 BIT	<input type="checkbox"/> 36 BIT	Category Diagnostics
Title EVRDA Rev 4.1 Problem					Tech Tip No. RM05-TT-23	
Processor Applicability Vax			Cross Reference RM02-TT-59, RM03-TT-60, RM80-TT-21		Tech Tip Rev A	Page 1 of 1
Author Koller				Mgr./Supv. Approval		
Location CX0		Mod/Stop CX0 2-1/K97		Date 3-23-84		
CSE Approval Ron Milano				Date 3.24.84		
FSPSG Approval Al Snyder				Date 3.24.84		

**PROBLEM:**

EVRDA Rev 4.1 fails Test 73, Subtest 0 (Error 3), when run on a VAX11-780 with the new extended silo module for the RM780 (module M8274). Since the new module has a deeper silo, the diagnostic's timer times out before the silo empties.

**FIX:**

The fix consists of a patch to be made to the program after it is loaded in memory via the Diagnostic Supervisor.

Since it appears that there may be two versions of the diagnostic both identifying themselves as Rev 4.1, the patch that follows covers both cases:


1. Load program EVRDA
2. SET BASE 9BFC                    [old Rev 4.1]
3. EXAM E9 contents should be D05302D0
  - A. IF this is correct, then DEP/L E9 D05307D0
  - B. Done. Run the program.
4. If the contents were not correct, SET BASE 9D66
5. EXAM F6 contents should be D05302D0
  - A. IF this is correct, then DEP/L F6 D05307D0
  - B. Done. Run the program [new Rev 4.1]

A new revision of the program will be released on the very next VAX Diagnostic release cycle.

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 27	Page Revision A	Publication Date APRIL 1984
-------------------	--------------------	--------------------------------

RM05 TT 28

	<b>FIELD SERVICE TECH TIP</b>					Option Designator <b>RM05</b>
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input checked="" type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category <b>OPTION</b>
Title <b>New AC Power Cables for VDE Power Supplies</b>					Tech Tip No. <b>RM05-TT-24</b>	
Processor Applicability			Cross Reference <b>N/A</b>		Tech Tip Rev	Page <b>4</b> of <b>4</b>
Author <b>Mark Hines</b>			Mgr/Supv Approval <b>Ron Milano</b>		<i>R. Milano</i>	
Location <b>CX CSSE</b>			Mail Stop <b>CX02-1/K97</b>		Date <b>26-Oct-83</b>	
CSSE Approval <b>Ron Milano</b>			<i>Ron Milano</i>		Date <b>16 Apr 84</b>	
FSPSG APPROVAL					Date	

RM05 drives have started shipping with higher revision VDE power supplies using new "keyed" AC power cords to further meet VDE requirements. The new keyed power cords are compatible with ALL VDE power supplies. However, drives previously installed in the field may contain an earlier non-keyed AC power cords which WILL NOT FIT INTO the new VDE power supplies. Figure 1 and Figure 2 illustrate the physical differences between the keyed and non-keyed cables.

VDE RM05 Drive	OLD (non-keyed) AC Power Cord Vendor p/n	NEW (keyed) AC Power Cord Vendor p/n	NEW (keyed) AC Power Cord DEC p/n
50 Hz	70734120	70734122	29-24778
60 Hz	70734121	70734123	29-24779

The following table represents all of the different VDE RM05 power supplies that we have been exposed to at the present. A previously installed RM05 may contain any of these VDE power supplies. The table also represents the compatibilities that exist between the different power supplies and the OLD (non-keyed) AC power cord versus the NEW (keyed) AC power cord.


VDE RM05 Drive	VDE Power Supply Vendor p/n	VDE Power Supply DEC p/n	AC Power Cord Required	VDE Power Supply Level
50 Hz	73133100	-----	New or Old	VDE I
50 Hz	73133102	-----	New or Old	VDE I
50 Hz	73133104	29-23889	New or Old	VDE I
50 Hz	73133108	-----	ONLY NEW	VDE II
50 Hz	73133112	-----	ONLY NEW	VDE II
60 Hz	73133101	-----	New or Old	VDE I
60 Hz	73133103	-----	New or Old	VDE I
60 Hz	73133105	29-23888	New or Old	VDE I
60 Hz	73133109	-----	ONLY NEW	VDE II
60 Hz	73133111	-----	ONLY NEW	VDE II

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation. For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number <b>28</b>	Page Revision <b>A</b>	Publication Date <b>MAY 1984</b>
-----------------------	------------------------	----------------------------------

DA-0428-13-001-000

RM05 TT-24

	<b>FIELD SERVICE TECH TIP</b>	Option Designator RM05	
	<b>Continuation Sheet</b>	Category OPTION	
Title New AC Power Cables for VDE Power Supplies		Tech Tip No. RM05-TT-24	
Processor Applicability	Cross Reference N/A	Tech Tip Rev A	Page 2 of 4




Figure 1. OLD Non-keyed AC Power Cord (VDE)

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 29	Page Revision A	Publication Date MAY 1984
-------------------	--------------------	------------------------------

RM05 TT 24

<b>FIELD SERVICE TECH TIP</b>		Option Designator RM05	
		<b>Continuation Sheet</b>	
Title New AC Power Cables for VDE Power Supplies		Tech Tip No RM05-TT-24	
Processor Applicability		Cross Reference N/A	Tech Tip Rev A
			Page 3 of 4




Figure 2. NEW KEYED AC Power Cord (VDE)

**FOR INTERNAL USE ONLY**· This information is property of Digital Equipment Corporation  
 For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number	Page Revision	Publication Date
30	A	MAY 1984

RM05 TT 31

[ ]	<b>FIELD SERVICE TECH TIP</b>	Option Designator RM05	
	<b>Continuation Sheet</b>	Category OPTION	
Title New AC Power Cables for VDE Power Supplies		Tech Tip No RM05-TT-24	
Processor Applicability     A	Cross Reference N/A	Tech Tip Rev A	Page 4 of 4

An FCO has been generated (RM05-R0014) and will soon be released. This will implement the latest VDE power supplies with new cables. The FCO should ONLY be installed if the problem symptoms are present as described in the FCO documentation.


The Digital part numbers 29-23888 and 29-23889 will be updated in the near future to also reflect the latest VDE power supplies 73133111 and 73133112. Until such time, they can only be obtained by ordering the Vendor Part Number or the FCO kit (when released).

**FOR INTERNAL USE ONLY** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 31	Page Revision A	Publication Date MAY 1984
-------------------	--------------------	------------------------------

DA-0122-12-000000

RM05 TT 32

		<b>FIELD SERVICE TECH TIP</b>				Option Designator RM05
		<input type="checkbox"/> 12 BIT	<input checked="" type="checkbox"/> 16 BIT	<input type="checkbox"/> 18 BIT	<input checked="" type="checkbox"/> 32 BIT	<input type="checkbox"/> 36 BIT
Title POWER SUPPLY FAILURES					Tech Tip No. RM05-TT-25	
Processor Applicability ALL VAX			Cross Reference N/A		Tech Tip Rev A	Page 1 of 1
Author MARK LICATA			Mgr./Supv. Approval RON MILANO <i>[Signature]</i>			
Location CHICAGO PRODUCT SUPPORT		Mail Stop ROLLING MEADOWS, ILL (RL)		Date 1 MAY 1984		
CSSE Approval RON MILANO <i>[Signature]</i>				Date 15 MAY 1984		
FSPSG APPROVAL				Date		

**PROBLEM** - RM05 (CDC 9766) OLD STYLE NON-VDE POWER SUPPLY FAILS MORE OFTEN THAN SHOULD. COMMONLY CAPACITOR-RECTIFIER ASSEMBLY PN:29-23541.

- SYMPTOMS** -
- 1) WRITE FAULT APPEARS IMMEDIATELY AFTER POWER UP AND WILL NOT CLEAR. ALL VOLTAGES ARE WITHIN PUBLISHED TOLERANCES.
  - 2) START LAMP ON CONTROL PANEL GLOWS DIMLY EVEN WHEN DRIVE IS SPUN DOWN OR READY LAMP DOES NOT BLINK ON SPIN UP, STAYS ON SOLID. NUMEROUS SPIN UP AND SPIN DOWN PROBLEMS.
  - 3) CARRIAGE OSCILLATES AFTER HEAD LOAD.

- SOLUTIONS** -
- 1) ALTHOUGH +28 VOLT TOLERANCE IS LISTED TO BE  $\pm 2$  VOLTS, I HAVE FOUND THE + TOLERANCE TO BE INCORRECT ON THE NON-VDE SUPPLY. ON THREE OCCASIONS I HAVE SEEN +28 AT +26.9 AND +27.1, AND THE CAUSE WAS CAPACITOR C2 ON THE SYEN CAP-REC PCB. THE WRITE DRIVER CHECKS AND GENERATES WRITE FAULT (4 CAUSES) BASED ON WHETHER +22 VOLTS IS GREATER THAN +22.0. THE +22 VOLTS IS DERIVED FROM +28 VOLTS.
  - 2) REMOVE POWER SUPPLY COVER TO SCOPE AND METER THE +20V VOLTAGE AT A1TB2 PIN 11 ON THE SYEN CAP-REC ASSEMBLY. THIS VOLTAGE IS USED TO PICK AND HOLD ALL CONTROL RELAYS IN THE NON-VDE SUPPLY. NEEDLESS TO SAY, THE TOLERANT NOISE LEVEL IS HIGHER THAN A DC SUPPLY FOR A LOGIC RACK BUT NOT AS IMPORTANT TO THE PROPER FUNCTION OF A MECHANICAL DISK DRIVE. IF BAD SCOPE WILL TELL.
  - 3) SCOPE  $\pm 46$  WHILE CARRIAGE IS OSCILLATING, IF NOISY PROBLEM COULD BE C7 OR C8 AGAIN ON THE CAP-REC ASSEMBLY.


**NOTE:** WHEN REMOVING SYEN MAKE A CHART TO INDICATE WHAT WIRE GOES WHERE BEFORE YOU REMOVE THE ASSEMBLY, THERE ARE 31 CONNECTORS IN ALL. ALSO IF YOU NEED THE CAPS FOR PROBLEMS 1 OR 2 THEY ARE USED ON THE  $\pm 20$  VOLT SUPPLY USED IN THE RM03.

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation. For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 32	Page Revision A	Publication Date MAY 1984
-------------------	--------------------	------------------------------

DA-0100-1-80-4700

HMLC 33

	<b>FIELD SERVICE TECH TIP</b>					Option Designator RM05
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH	Category DISK
Title RM ADAPTER POWER SUPPLY (70-13826) CAUTION					Tech Tip No RM05-TT- 26	
Processor Applicability  11's   VAX   LCG			Cross Reference RM02-TT- 61 RM80-TT-23 , RM03-TT- 62		Tech Tip Rev A	Page 1 of 1
Author RICK SWANSON				Mgr/Supv Approval RON MILANO <i>R. Milano</i> CX/CSSE		
Location COLORADO SPRINGS			Mail Stop <i>R. Milano</i> CX02-1/K97		Date 3-JANUARY-1985	
CSSE Approval RON MILANO CX/CSSE <i>R. Milano</i>				Date 3-JANUARY-1985		
FSPSG Approval				Date		

Extreme caution must be used when working in or around the RM Adapter Power Supply.


When the Power Supply is disassembled to allow service access, there are exposed uninsulated parts with primary AC voltage present on them. The possibility of coming in contact with such voltage is very likely when servicing the RM Adapter Power Supply.

**WARNING:** WHEN SERVICING THE RM ADAPTER POWER SUPPLY, LOCATED IN THE RM ADAPTER, ALWAYS MAKE SURE THAT THE RM ADAPTER MAIN AC POWER CORD CONNECTOR IS REMOVED FROM THE SITE POWER SOURCE.

**FOR INTERNAL USE ONLY** - This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 33	Page Revision A	Publication Date JANUARY 1985
-------------------	--------------------	----------------------------------



	<b>FIELD SERVICE TECH TIP</b>	Option Designator RM05	
	<b>Continuation Sheet</b>	Category DISK	
Title RM05 RE-SKIDDING		Tech Tip No. RM05-TT-27	
Processor Applicability VAX   11   11C   11CG   11D   11E   11F   11G   11H   11I   11J   11K   11L   11M   11N   11O   11P   11Q   11R   11S   11T   11U   11V   11W   11X   11Y   11Z   11AA   11AB   11AC   11AD   11AE   11AF   11AG   11AH   11AI   11AJ   11AK   11AL   11AM   11AN   11AO   11AP   11AQ   11AR   11AS   11AT   11AU   11AV   11AW   11AX   11AY   11AZ   11BA   11BB   11BC   11BD   11BE   11BF   11BG   11BH   11BI   11BJ   11BK   11BL   11BM   11BN   11BO   11BP   11BQ   11BR   11BS   11BT   11BU   11BV   11BW   11BX   11BY   11BZ   11CA   11CB   11CC   11CD   11CE   11CF   11CG   11CH   11CI   11CJ   11CK   11CL   11CM   11CN   11CO   11CP   11CQ   11CR   11CS   11CT   11CU   11CV   11CW   11CX   11CY   11CZ   11DA   11DB   11DC   11DD   11DE   11DF   11DG   11DH   11DI   11DJ   11DK   11DL   11DM   11DN   11DO   11DP   11DQ   11DR   11DS   11DT   11DU   11DV   11DW   11DX   11DY   11DZ   11EA   11EB   11EC   11ED   11EE   11EF   11EG   11EH   11EI   11EJ   11EK   11EL   11EM   11EN   11EO   11EP   11EQ   11ER   11ES   11ET   11EU   11EV   11EW   11EX   11EY   11EZ   11FA   11FB   11FC   11FD   11FE   11FF   11FG   11FH   11FI   11FJ   11FK   11FL   11FM   11FN   11FO   11FP   11FQ   11FR   11FS   11FT   11FU   11FV   11FW   11FX   11FY   11FZ   11GA   11GB   11GC   11GD   11GE   11GF   11GG   11GH   11GI   11GJ   11GK   11GL   11GM   11GN   11GO   11GP   11GQ   11GR   11GS   11GT   11GU   11GV   11GW   11GX   11GY   11GZ   11HA   11HB   11HC   11HD   11HE   11HF   11HG   11HH   11HI   11HJ   11HK   11HL   11HM   11HN   11HO   11HP   11HQ   11HR   11HS   11HT   11HU   11HV   11HW   11HX   11HY   11HZ   11IA   11IB   11IC   11ID   11IE   11IF   11IG   11IH   11II   11IJ   11IK   11IL   11IM   11IN   11IO   11IP   11IQ   11IR   11IS   11IT   11IU   11IV   11IW   11IX   11IY   11IZ   11JA   11JB   11JC   11JD   11JE   11JF   11JG   11JH   11JI   11JJ   11JK   11JL   11JM   11JN   11JO   11JP   11JQ   11JR   11JS   11JT   11JU   11JV   11JW   11JX   11JY   11JZ   11KA   11KB   11KC   11KD   11KE   11KF   11KG   11KH   11KI   11KJ   11KK   11KL   11KM   11KN   11KO   11KP   11KQ   11KR   11KS   11KT   11KU   11KV   11KW   11KX   11KY   11KZ   11LA   11LB   11LC   11LD   11LE   11LF   11LG   11LH   11LI   11LJ   11LK   11LL   11LM   11LN   11LO   11LP   11LQ   11LR   11LS   11LT   11LU   11LV   11LW   11LX   11LY   11LZ   11MA   11MB   11MC   11MD   11ME   11MF   11MG   11MH   11MI   11MJ   11MK   11ML   11MN   11MO   11MP   11MQ   11MR   11MS   11MT   11MU   11MV   11MW   11MX   11MY   11MZ   11NA   11NB   11NC   11ND   11NE   11NF   11NG   11NH   11NI   11NJ   11NK   11NL   11NM   11NO   11NP   11NQ   11NR   11NS   11NT   11NU   11NV   11NW   11NX   11NY   11NZ   11OA   11OB   11OC   11OD   11OE   11OF   11OG   11OH   11OI   11OJ   11OK   11OL   11OM   11ON   11OO   11OP   11OQ   11OR   11OS   11OT   11OU   11OV   11OW   11OX   11OY   11OZ   11PA   11PB   11PC   11PD   11PE   11PF   11PG   11PH   11PI   11PJ   11PK   11PL   11PM   11PN   11PO   11PP   11PQ   11PR   11PS   11PT   11PU   11PV   11PW   11PX   11PY   11PZ   11QA   11QB   11QC   11QD   11QE   11QF   11QG   11QH   11QI   11QJ   11QK   11QL   11QM   11QN   11QO   11QP   11QQ   11QR   11QS   11QT   11QU   11QV   11QW   11QX   11QY   11QZ   11RA   11RB   11RC   11RD   11RE   11RF   11RG   11RH   11RI   11RJ   11RK   11RL   11RM   11RN   11RO   11RP   11RQ   11RR   11RS   11RT   11RU   11RV   11RW   11RX   11RY   11RZ   11SA   11SB   11SC   11SD   11SE   11SF   11SG   11SH   11SI   11SJ   11SK   11SL   11SM   11SN   11SO   11SP   11SQ   11SR   11SS   11ST   11SU   11SV   11SW   11SX   11SY   11SZ   11TA   11TB   11TC   11TD   11TE   11TF   11TG   11TH   11TI   11TJ   11TK   11TL   11TM   11TN   11TO   11TP   11TQ   11TR   11TS   11TT   11TU   11TV   11TW   11TX   11TY   11TZ   11UA   11UB   11UC   11UD   11UE   11UF   11UG   11UH   11UI   11UJ   11UK   11UL   11UM   11UN   11UO   11UP   11UQ   11UR   11US   11UT   11UU   11UV   11UW   11UX   11UY   11UZ   11VA   11VB   11VC   11VD   11VE   11VF   11VG   11VH   11VI   11VJ   11VK   11VL   11VM   11VN   11VO   11VP   11VQ   11VR   11VS   11VT   11VU   11VV   11VW   11VX   11VY   11VZ   11WA   11WB   11WC   11WD   11WE   11WF   11WG   11WH   11WI   11WJ   11WK   11WL   11WM   11WN   11WO   11WP   11WQ   11WR   11WS   11WT   11WU   11WV   11WW   11WX   11WY   11WZ   11XA   11XB   11XC   11XD   11XE   11XF   11XG   11XH   11XI   11XJ   11XK   11XL   11XM   11XN   11XO   11XP   11XQ   11XR   11XS   11XT   11XU   11XV   11XW   11XZ   11YA   11YB   11YC   11YD   11YE   11YF   11YG   11YH   11YI   11YJ   11YK   11YL   11YM   11YN   11YO   11YP   11YQ   11YR   11YS   11YT   11YU   11YV   11YW   11YZ   11ZA   11ZB   11ZC   11ZD   11ZE   11ZF   11ZG   11ZH   11ZI   11ZJ   11ZK   11ZL   11ZM   11ZN   11ZO   11ZP   11ZQ   11ZR   11ZS   11ZT   11ZU   11ZV   11ZW   11ZX   11ZY   11ZZ	Cross Reference N/A	Tech Tip Rev A	Page 2 of 2

### RE-SKIDDING PROCEDURE


1. PLACE THE NON CUSHIONED SKID (99-07387-01) INTO POSITION AT THE END OF THE RAMP (99-07387-02).
  2. PUSH THE RM05 (70-17618-00) DRIVE UP THE RAMP AND ONTO THE SKID.
- NOTE: FRONT OF THE DRIVE MUST BE ORIENTED TOWARD THE END OF THE SKID (99-07387-01) WITH LAG BOLT RUNNER. USE LOCATING LINES ON THE SKID TO POSITION THE UNIT.
3. PLACE THE PLYWOOD RAMP (99-07387-02) ON THE SKID DECK BETWEEN THE 2 x 4 BLOCKS.
  4. SECURE THE RM05 DRIVE TO THE SKID USING TWO (2) SHIPPING BRACKETS (74-31322-01) AND (4) LAG SCREWS (90-00048-14).
  5. PLACE ONE SHIPPING BRACKET IN THE FRONT OF THE UNIT UNDER THE FRAME ON THE LEFT HAND SIDE. THE LIP OF THE BRACKET WILL FIT OVER THE FRAME.
  6. USING A 9/16" SOCKET WRENCH, SCREW EACH OF THE LAG SCREWS INTO THE PREDRILLED HOLES UNTIL TIGHT AGAINST THE BRACKET.
  7. PLACE ONE BRACKET DIAGONALLY FROM THE FRONT TO THE REAR OF THE UNIT. NOTE: THE BRACKET WILL FIT IN THE SPACE BETWEEN THE FILTER FRAME AND THE SIDE OF THE UNIT.
  8. COVER THE UNIT WITH THE POLY BAG (P/N 99-06104-44).

**FOR INTERNAL USE ONLY: This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2**

Page Number 35	Page Revision A	Publication Date AUGUST 1985
-------------------	--------------------	---------------------------------

16-01000-12 01 1985-08

**RM05-TT-26**

	<b>FIELD SERVICE TECH TIP</b>				Option Designator RM05
	<input type="checkbox"/> 12 BH	<input checked="" type="checkbox"/> 16 BH	<input type="checkbox"/> 18 BH	<input checked="" type="checkbox"/> 32 BH	<input checked="" type="checkbox"/> 36 BH
Title CPX Head Inspection Tool Kit				RM02-TT-64	Tech Tip No RM05-TT-28
Processor Applicability VAX1 111's HCG1		Cross Reference RP05-TT-64		RM03-TT-65 RP06-TT-71	Tech Tip Rev A
Author Gene Ridge CX/CSSE			Mgr./Supv Approval Ron Milano <i>[Signature]</i>		
Location Colorado Springs		Mail Stop CX01-1/P14		Date 02-October-1985	
CSSE Approval Ron Milano CX/CSSE <i>[Signature]</i>			Date 02-October-1985		
FSPSG Approval			Date		

### CPX HEAD INSPECTION TOOL KIT

VESE and CPX Company are pleased to announce the availability and special price to Digital branches for the CPX Head Inspection Tool Kit. This tool kit has been evaluated and approved by the Colorado Springs CSSE Maintainability Engineering Group for use on the following disk drives.

DIGITAL - RP05, RP06, RM02, RM03, RM05

MEMOREX - 677


CDC - 9762, 9766

The kit part number from CPX is HIMKK2531N, which is a combination of two standard CPX Head Inspection Kits. Included in this kit are the following items.

CPX P/N	DESCRIPTION	QTY
HIMKB1125N	MDG25 Base Unit with Optics offset at 105 degrees	1
HIACC1006N	Optical tube, 10x power magnification	1
HIACC1005N	Optical Brush	1
HICA51002N	Aluminum Case	1
HITRA1062N	Power Transformer 24 VAC, 16 amp output	1
HIACC1003N	E230 Removeable Rails	1
HIBKT1001N	E124 RM05 Carriage Limit Bracket	1
HIBKT1002N	E123 RM03 Carriage Limit Bracket	1

**FOR INTERNAL USE ONLY:** This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2.

Page Number 36	Page Revision A	Publication Date OCTOBER 1985
-------------------	--------------------	----------------------------------

	<b>FIELD SERVICE TECH TIP</b>		Option Designator RM05	
	<b>Continuation Sheet</b>		Category Disk	
Title CPX Head Inspection Tool Kit		RP06-TT-71	Tech Tip No. RM05-TT-28	
Processor Applicability  VAX   UL's   CG	Cross Reference RM03-TT-65	RP05-TT-64 RM02-TT-64	Tech Tip Rev A	Page 2 of 2

With this Head Inspection Tool Kit, an engineer will be able to closely inspect R/W Heads on the above disk drives without removing the heads themselves. This will save valuable labor time for the F.S. Engineer and will help decrease the amount of down time for the customer. The head inspection tool may be used during PM's to help the engineer diagnose a dirty head before a major failure occurs.

To facilitate orders in a timely manner, Field Service Branches and Regional Logistics offices may order through the local CPX Sales Office or place the order with the CPX home office by sending a Purchase Order to:

CPX  
21900 Plummer Street  
Chatsworth, CA 91311

Tel: (818)709-4003  
Telex: 371-9692  
TWX: 310-371-9692  
FAX: 818-882-7799

ATTENTION: Jenny Rippel

The Digital price for the Head Inspection Tool Kit (HIMKK2531N) is \$745.00. Digital's Field Service Logistics Organization will not stock this item in Hoburn (SR #17) unless sufficient demand for this tool kit is present. If there are any questions regarding the ordering of this Head Inspection Tool, you may contact Fran Linnehan at Mailstop 0601-1/H11.

FOR INTERNAL USE ONLY This information is property of Digital Equipment Corporation  
For more information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page Number 37	Page Revision A	Publication Date OCTOBER 1985
-------------------	--------------------	----------------------------------

# Field Service **TECH TIP**



Page 1 of 1

<b>Title</b> Absolute Air Filter Springs	<b>Category</b> Safety	<b>Rev</b> <u>A</u>
<b>Cross Reference</b> N/A	<b>Option</b> RM05	
	<b>TECH TIP No.</b> RM05-TT-29	

**Problem/Solution**

The springs holding down the plenum of the RM05 absolute air filter are extremely strong and unless proper precautions are taken can slip and injure a service person trying to work on the blower motor or absolute filter assembly. The RM05 service manual and the RM05 Preventive Maintenance manual are not clear as to the strength of these springs.

**PROPER CAUTIONARY MEASURES FOR WORKING ON RM05 ABSOLUTE FILTER OR BLOWER MOTOR ASSEMBLY.**

- A - Replacing the blower motor assembly or the absolute air filter requires removing the entire blower assembly from the drive.  
(there is insufficient room in the cabinet for safe maneuverability or access to parts)
- B - Use a spring hook or spring pliers to remove and replace the four (4) plenum hold-down springs.  
these springs are very strong and may cause injury if removed by hand.
- C - When removing the air filter plenum, place one hand on top of the plenum to stabilize it.  
the springs are strong enough that they can cause the plenum to tip.

**Approvals**

<b>Author</b> S.W. Caccia	<b>ESD&amp;P TECH TIP Coordinator</b> Bruce J. Conley	<b>CSSE</b> N. Fisette
<b>Author's Manager</b> S. Hoyt		<b>Field Service Product Safety</b> S.W. Caccia
<b>Release Date</b> 06 June 1986		<b>Revision</b> A

**FOR INTERNAL USE ONLY:** This information is the property of Digital Equipment Corporation  
For more information on writing or approving TECH TIPS, see Administrative TECH TIP Number 2

# Field Service **TECH TIP**



**Title** Diagnostic CZRMPBO.BIC  
**Failure**  
**Cross Reference** RM02-TT-65  
 RM03-TT-66

**Category** Disks  
**Option** RM05  
**Rev** A  
**TECH TIP No.** RM05-TT-30

**Problem/Solution**

Test 72 of Diagnostic CZRMPBO.BIC (RM02/03/05 Diskless Test 1) fails on a PDP 11/60 with Cache, the indication is that the AOE bit did not set. The problem is due to the speed of the cache memory on an 11/60 system. The following patch has been written by Diagnostic Engineering and will be available on the next release of XXDP in the January '87' time frame.

Change loc.	From	To
034400	012760	012702
034402	061001	000020
034404	000024	004737
034406	012760	000630
034410	041001	005302
034412	000024	001376
000630	000632	012760
000632	000000	061001
000634	000636	000024
000636	000000	012760
000640	000642	041001
000642	000000	000024
000644	000646	000207

**Approvals**

<b>Author</b> Gary Cable	<b>ESD&amp;P TECH TIP Coordinator</b> Bruce J. Conley	<b>CSSE</b> Gary Cable
<b>Author's Manager</b> Mike Mayfield		<b>Field Service Product Safety</b>
<b>Release Date</b> 5 November 1986		<b>Revision</b> A

**FOR INTERNAL USE ONLY:** This information is the property of Digital Equipment Corporation  
 For more information on writing or approving TECH TIPS, see Administrative TECH TIP Number 2